Certifies that the items identified above were many factured in conformity to: Approved design data and are in condition for safe operation Non-approved design data specified in block 12, the work identified work the items are considered ready for release to service.	conformity to: 14a. Part-145.A.50 Release to Service Certifies that unless otherwise specified in block 12, th described in block 12, was accomplished in accordanc work the items are considered ready for release to ser 14b. Authorised Signature 14c. 14c.
conformity to: 14a. Part-145.A.50 Release to Service Certifies that unless otherwise specified in block 12, the wo described in block 12, was accomplished in accordance will work the items are considered ready for release to service.	conformity to: 14a. Part-145.A.50 Release to Service Certifies that unless otherwise specified in block 12, the wo described in block 12, was accomplished in accordance will work the items are considered ready for release to service. 206 UK.145.



IMT Aviation Scotland Ltd. Aircraft Acessories Division 21 Monument Crescent Prestwick KA9 2RQ United Kingdom Tel: +44 1292 473855 Fax: +44 1292 671576

EASA Maintenance Orga , sation:

FAA Repair Station:

Workshop Roper

No: WP50005/1 Issue: 02 Date: 25-Oct-18 Burwood Avir ion pplies Ltd Burwood House 8 Bessemer Close Verwood Dorset **BH31 6AZ** United Kingdom Attn: Mr Daron Golding From: Richard McKee Tel: +44 1202 825434 Fax: E-Mail: daron@burwood.aero E-Mail: richard@imtaviation.com Your Ref: PO 110555 Our Ref No: WP50005 Tat Required: N/A Part No: 8061-536 Description: H. DREMECH ANICAL FUEL CONTROL TSN: N/A CSN: N/A Serial No: WYGA6515 Workscope: Repair &) st CSO: N/A TSO: N/A DoM: Overhauled: Inspected: Removed From: Serial No: Rea Nu: Position: Technical Reference: 73-21-78 - Issue No: 1 - Rev No: 9

Inspection Findings:			
As received inspection revealed the foll	owing anomolies;		
1/ SB data plate missing. P/N 3081-556			
3/ On removal of electrical connector bo 4/ On removal of manifold plate, all sea	ox cover, all pins found remo ls and packings found missi	oved f am chainel A & B connectors.	
Disassembly Findings: Unit had been reassembled with no pac	kings or seals installed.		
Recommended Action: Rebuid Unit, Calibrate and Final Test			
	fill be verified at final testing	as the unit is loosely `ssembled with no sea	als
Corrective Action:	an be samed but.		
Unit was completely Disassembled, Clea	aned, Inspected, Assembled	d, Calibrated and Final Tested IA' a the curre	nt
Signed:	Name:	Date: / /	
For and on the behalf of IMT Aviation Scotland Ltd.			