

Barfield, Inc. Miami, FL, 33142 FAA#: XBIR995K

Teardown

WO: WO1012726 Cust. RO: 39765

To:

DIVERSIFIED SERVICES, INC.

(DASI)

10000 NW 25TH ST LET

MIAMI, FL 33172

US

Ship To:

DIVERSIFIED AERO SERVICES, INC.

10000 NW 25 STREET

DORAL

Incoming PN: PPA110

Descr: SMOKE DETE/ JOR

S/N: 20808

Incoming Work Req: REPAIR

OutgoingPN: PPA1102-00

Mfg: F4885

Warranty: No

Outgoing Work Req: REPAIRED

Removal Date:

Tail N mber:

Station:

Position:

Manuals: TYPE: CMM PUB: 26-16-16 REV ATF: 11/16/2010

Tools:

SYMPTOMS:

REASON FOR REMOVAL

FOR CLEANING

FAULTS:

FAULT

CELL REQUIRES CLEANING HOWEVER BROKEN COVER.

CORRECTIVE ACTIONS:

REPLACED DEFECTIVE PARTS

REPLACED COVER AND TESTED W/I MFGS SPECS.

Technician:

TOMAS ROQUE DE ESCOBAR

Inspector:

SAMMY LOPEZ

Date:

2/22/2018

Signature:

Time: 3:42:06 PM

Page: 1

FORM 7.5.3.6

Date Printed: 2/22/2018

REV 4, DATE: 12/18/2017



Barfield, Inc. Miami, FL, 33142 FAA#: XBIR995K

Teardown

WO: WO1012726 Cust. RO: 39765

To:

DIVERSIFIED AERO SERVICES, INC. (DASI) 10000 NW 25TH STREET MIAMI, FL 33172 US

Ship To:

DIVERSIFIED AERO SERVICES, INC. 10000 NW 25 STREET

DORAL

Incoming PN: PPA1102-00

Descr: SMOKE DETECTOR

S/N: 20808

Incoming Work Req: REPAIR

OutgoingPN: PPA1102-00

Mfg: F4885

Warranty: No

Outgoing Work Req: REPAIRED

Removal Date:

Tail Number:

Station:

Position:

Manuals: TYPE: CMM PUB: 26-16-16 REV: 5 DATE: 11/16/2010

Tools:

Fig-Item PN

Description

CD

Qty

056765

COVER

NE

1.00

Aviation

Technician:

TOMAS ROQUE DE ESCOBAR

Date:

2/22/2018

Date Printed: 2/22/2018

Inspector:

SAMMY LOPEZ

Signature:

Page: 2

FORM 7.5.3.6

Time: 3:42:07 PM

REV 4, DATE: 12/18/2017