1. Approving Competent Authority 4.		O Com Tradina Nimban
CAA.UK	AUTHORISED RELEASE CERTIFICATE  EASA FORM 1	W201814128
4. Organization Name and Address:	Avia Technique Ltd.	
Avia Technicus	Unit 1,3,4 & 6 Fishponds Estate	5. Work Order / Contract / Invoice Number:
SK AeroSafety Group	Wokingham, Berkshire, United Kingdom RG41 2QJ Ph: +441189789789, Fax: +441189794511	W201614128
		110302
6. Item: 7. Description:	8. Part Number: 9. Quantity: 10. Serial Number:	
1 Reheater	1.00	Or the
12. Remarks:		CV SIBIL.
CMM: 21-52-08 Revision; 11	"The work it intiffed in B	*The work it snilfied in Bit 11 and described herein has been
Avia Technique have checked and verified the	Avia Technique have checked and verified that there are no perlinent AD's or SB's relevant.  Avia Technique have checked and verified that there are no perlinent AD's or SB's relevant.  Co-"ficate no. 18c	to that work, the least one will record return to service under ce-"fcale no. [8]
ioa. Cerilles that the tems identified above were manufactured in conformity to	4a. X Part-145.A.50 Release to Service X	Other regulation specified in Block 12
	Certifies that unless otherwise specified in Block 12, the described in Block 12 was accomplished in accordance.	ork identified in Block 11 and
Non-approved design data specified in Block 12		ii Fair 145, and in respect to that
13b. Authorised Signature: 13c. Ct	(lificate / liphu Ref No.;   14b. Authorised Signature: AVIA	14c. Certificate /Approval Ref No.:
13d. Name		UK.145.00846
	νσ (σωτιπιπηγγγγ).	14e. Date (dd/mmm/yyyy);
	Hobert West 12/Sep/2018	018
	USER / INSTALLER RESPONSIBILITIES	
in the item(s).  'After 1 a use, "astally performs work in accordance with regulations of an At-	uthority to install the item(s).	
u. Vilins ens en hat his/her Airworthiness Au	u. With the first the Airworthiness Authority accepts items from the Airworthiness Authority specified in block 1, it is essential that the	, it is essential that the
State, rents blocks 13a and 14a do not constitute nations we guitations by the user/installer before the	State, vents blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national by the user/installer before the aircraft may be flown.	ued in accordance with the



Avia Technique Ltd.

Unit 1,3,4 & 6 Fishponds Estate Fishponds Road

Wokingham, Berkshire, United Kingdom

**RG41 2QJ** 

Ph: +441189789789, Fax: +441189794511

Tear Down/Inspection

Work Order #: W201814128

Date Printed:

04/09/2018

Page:

To:

Burw od Avis ion Supplies Ltd 8 Bess mer close Burwood Hou Verwood, Forset BH31 6AZ United Kingdom

Ship To:

**Burwood Aviation Supplies Ltd** 

8 Bessemer Close **Burwood House** 

Verwood, Dorset BH31 6AZ

United Kingdom

Reference:

Date Received: 30/08/2018

Part Number:

755A0000 04

Description:

Reheater

Serial Number: 00205

**Customer Remarks:** 

Overhaul

Results from inspection:

Date of manufacture

05/1988

No Faults found

Corrective actions:

Overhaul with reference to the correct CMM Rev

Apply corrosion protection and clean. Overhaul, Test and Certify with reference the correct issue of the CMM.

Inspection report generated by: Simon Day

Reference: SK-GF-005

Issue: Initial