

1. Approving Competent Authority/Country **2.**

AUTHORISED RELEASE CERTIFICATE
EASA FORM 1

3. Form Tracking Number **21 2 12 09347**

4. Organisation Name and Address:

DIEHL Aerospace GmbH
Alte Nudborfer Straße 23
88662 Überlingen - Germany

Telephone : +49 7551 891 0
 Telefax : +49 7551 891 4001
 Mail address : Postfach 10 12 62,88642 Überlingen

5. Work Order / Contract / Invoice (Delivery Note No. / Order No.)
410162734 / 20080251

6. Item	7. Description	8. Part No.	9. Quantity	10. Serial-No.	11. Status / Work
0010	EPSU 3214-55 W/O BAT	773-873-00	1	3330	REPAIRED

12. Remarks

This ARC issued by DAs location ZAC de Saint Martin du Touch, 6 Impasse Alice Guy, 31300 Toulouse - France
 Change State: AMDT A
 Work performed according to CMM 33-51-09 REV.2.0 dated AUG 04/94
 Technical action report 50702350 describing the actual work performed is attached
 The PN a.m. in block 8 is not referenced on the part.
 Part of NHA Emergency Power Supply Unit PN 3214-55

The civil aeronautical product has been maintained, altered or modified (as appropriate) in accordance with U.S. Federal Aviation Regulations under FAA Certificate Number B3WY6963

13a. Certifies that the items identified above were manufactured in conformity to:

approved design data and are in a condition for safe operation.

non-approved design data specified in block 12.

14a. Part-145 A.50 Release to Service Other regulation specified in block 12

14b. Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.

13b. Authorised Signature

13c. Approval/Authorisation Number

14b. Authorised Signature *N. AMRI*

14c. Certificate/Approval Ref.No. **DE.145.0041**

14d. Name **N. AMRI**

14e. Date (DD/MM/YY) **27. Dec 2012**

EASA Form 1 - MF/145 Issue 2

USER / INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).
 Where the user/installer performs work in accordance with regulations of an Airworthiness Authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.
 Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

DAs EASA Form 1 - 092010

DIEHL

Aerospace

FAA Approved Repair Station
No B3WY696J

LAAC de Saint Martin du Touch
6 Imp. Alice Guy
13000 Toulouse

Tel (33) 05 61 71 00 67
Fax (33) 05 61 50 00 98

TEST REPORT FOR EPSU W/O BATTERY

Unit : Supply Unit
Part Number : 773-873-00
SERIAL NUMBER : 3330
Amendment : A
Manufactured By : Vendor Code D1347
Date of Manufacture : 11/1997

Test in accordance with CMM : 33-51-09
Test Equipment : EP4-105-68

Visual Check : OK
Test of BITE function : OK
Test of voltage monitoring : OK
Test of power outputs, converter mode : OK
Test of power outputs, battery mode : OK
Test of failure detection capability : OK

Test Performed by : N. GONZALEZ

Date : 27/12/2012

Stamp : 4357

The Acceptance Inspection was performed according to the reference document. The result of the Acceptance Inspection is satisfactory.

Date :

Inspected by

Stamp

27 DEC 2012

J. Muri



DIEHL
Aerospace.

TECHNICAL ACTION REPORT

Rep.-No. :
50102350
Page : 1 / 1

EPSU 3214-55 W/O BAT

Sales Order :
320088951-10000

Customer : Monarch Airlines

Removal Date : 12.12.2012

In PN : 773-873-00
Amdt : A
SN : 3330

Crst.Order : R10764712

Failure Report :

Out PN : 773-873-00
Amdt : A
SN : 3330

Comp. Date In : 13.12.2012

MFG : /

Maintenance Requirement : CMM 33-51-09 REV.2.0 AUG 04/94

Complaint confirmed: YES

Work Type: Repair

Warranty accelerated: NO

Special Investigation: NO

Customer Complaint:

EXIT LIGHT U/S AND ALSO EXIT LIGHT OUT IN CEILING DOORS 3

**Shop finding/actions:
Defects/replacements:**

140 0000405857 HF MODULE

component defective
Replaced with new part

Comment:

Datum:
27.12.2012

Customer Support(Author):
FOURE

[Signature]
