

Global Air Services LLC 14075 SW 143 CT Unit#4 MIAMI, FL 33186

Ph: 786-539-1538, Fax: 786-362-7177

info@globalairserv.com

Tear Down/Inspection

Work Order #: 17563

Date Printed: 9/19/2018 Time: 11:39:07 AM

Page: 1

To:

ATTN: JANINE ALC/ RAZ MAC AEROSPACE LC 820 E. 16 ST

TUCSON, AZ 85719 USA

Ship To:

MAC AEROSPACE LLC

820 E. 16 ST **TUCSON 85719**

USA

Ref #: 6423

Pt /ne #: 520-647-2647

Fax #: 520-908-7116

Email: lisa@mac-aero.com

Code: MACAERO

Rev: 3

PN: 976J498-2

Descr: AC GENERATOR

Qtv: 1

tation:

Make:

Model:

Mfg:HAMILTON

TSN: 0

TSO: 0

TSR: 0

CSN: 0

CSO: 0

CSR: Ð

Cond: OVERHAULED Manual: 24-20-77

Mechanic: (SOTOL) 30

Inspector: L FERRER

Engine Number:

Rev Date: 2/15/2017

Tail Number:

Serial Numbers: PT16273

Symptoms:

RELIABILTY

REASON FOR REMOVAL: OVERHAUL

REMOVAL DATE: UNK

CUSTOMER RO DATE: 31AUG2018

A/C REG: UNK POS: UNK TIME: UNK CYCLE: UNK

PRIMARY FAILURE: UNIT FUNCTIONAL TESTED IAW CI 'M 24 7-77 REV. 36 DATED 02/16/2017, UNIT FAILED FUNCTIONAL TEST DUE TO HIGH RESISTANCE. WILL REVINE OV MAUL.

REASON FOR REMOVAL CONFIRMED: YES PART NUMBER ON DATAPLATE MATCHES CUSTOMER RO:) -S SERIAL NUMBER ON DATAPLATE MATCHES CUSTOMER RO: YES

IDENTIFICATION

AS PER OEM CMM UNIT IS IDENTIFIED CORRECTLY

AD'S FOUND

NO FAA OR EASA AIRWORTHINESS DIRECTIVES FOUND ON 19SEP2018. REPLACEMENT PARTS

UNIT IS QUOTED FOR: OVERHAUL

REPLACEMENT PARTS REQUIRED:

1 976J498-GASKIT 100% EXPENDABLES KIT (MANDATORY)

Corrective Actions:

RECEIVING INSPECTION

UNIT PN AND SN VERIFIED WITH CUSTOMER RO. NO VISIBLE DAMAGE NOTED UPON ARRIVAL RECV: M SOLARES INSP: L FERRER DATE: 09/13/2018

PRELIMINARY INSPECTION

LAZARO FERRER

Form created with Quantum Control(tm) technology. Product Licensed to: Global Air Services LLC



Global Air Services LLC 14075 SW 143 CT

Unit#4

MIAMI, FL 33186

Ph: 786-539-1538, Fax: 786-362-7177

info@globalairserv.com

Tear Down/Inspection

Work Order #: 17563

Date Printed: 9/19/2018

Time: 11:39:08 AM

Page: 2

PN ND SN VERIFIED WITH CUSTOMER RO. UNIT PN VERIFIED WITH OEM CMM 24-20-77. •CH: O SOTOLONGO INSP: L FERRER DATE: 09/14/2018

FUNCTION AL TEST

FUNCTIONAL TESTED IAW CMM 24-20-77 REV. 36 DATED 02/15/2017. UNIT FAILED FUNCTIONAL TEST DUE TO HIGH P ANCE. WILL REQUIRE OVERHAUL.
TEC .. O SOTCLONGO INSP: L FERRER DATE: 09/14/2018

DISASSEMBLED

UNIT DISA SENT ED, CLEANED AND INSPECTED IAW CMM 24-20-77 REV 36 DATED 02/15/2017. NO MAJOR ABNORM THE NOTED TO UNIT. UNIT REQUIRES LISTED ITEMS AND ALL DISTURBED EXPENDABLES FOR OVERHAUL.

TECH: O SO MINSP: L FERRER DATE: 09/14/2018

ASSEMBLY

UNIT ASSEMBLEL AND P .INTED IAW CMM 24-20-77 REV. 36 DATED ON 02/15/2017. REPLACED 100% EXPENDABLE KIT AND ALL REQUIRED. ARES FOR OVERHAUL.
TECH: O SOTOLONGO IN AP. LITERER DATE: 09/18/2018

TEST

LAZARO FERRER