

NFF Avionics Services, Inc.

115 Corporation Drive,

Aliquippa

15001 USA

Tel: 724-378-9454 FAA R.S. N01R648Y

1-877-NFF-TOGO

E-MAIL: info@nffavionics.com

Fax: 724-378-9461 EASA.145.5059

WEBSITE: www.nffavionics.com

ZEARDOWN AND DISPOSITION REPORT Page: 1 of 2

Status TTSN TTSO

OVEF AULED

Un' Unknown N380SW

A/C REG# Justified

Date Installed Unknown **Date Removed** Unknown Warranty No : TBV

Type TTSR

Company

Order Date

: Unknown : CAVU Aerospace

For Customer S.O. No.

: Apr-17-2019

: 040683

F.O.B. : Account No. [20993]

CAVU Aerospace Attn: Dee Caradonna 2000 Airport Road Stuttgart, AR 72160

Tel.: 480-227-4762

Cust P.O. : 00009470 :016392-000 Our Ref : 039960 Desc : Airo ... par ary Your Ref : 00009470 S/N : 090, 200 63F48

Rec. Date : 04/23/2019 MFG: **Due Date**

: 05/15/2019 Qty:1 Completed P/N: 016392-000 S/N As : 090527 J063545

> Division: Departmen* Received Date: Apr-23-2019

Duc Date

: May-15-2019

Cond As: OH

TAG#

TTSO

Manual

Revision

TAG DATE

Print Date

Into Bin Loc : Shipped

:039960

: 24-32-03

: 30/APR/2019

: 3 / Apr-15-2002

: Apr-30-2019

WORK ORDFA No 039960

Reported by Customer

Please evaluate the unit per O.E.M. specs for "Overhauled" OHC 8130-3 (dual release). If there are any mandatory A.D.'s or a S.B is written against this unit please advise prior to proceeding with work.

*** Any parts designated NSN or missing a serial number, please apply a tracking number, (serial number) and reference on all work order documents, ***

Preliminary Insp.

Verified MFR P/N and S/N of Unit. Upon incoming inspection unit found to be in a generally good phy all condition with terminal cover missing. DMF 062007.

The following was noted during Preliminary Inspection:

1. Battery received measuring residual voltage. Battery failed the residual capacity check due to low voltage. A rull charge and discharge for a proper capacity check required. The battery passed separator and capacity checks.

Continued on next page...

Copyright (c) PENTAGON 2000 Software, Inc.



NFF Avionics Services, Inc.

115 Corporation Drive,

Aliquippa PA

PA 15001 USA

Tel: 724-378-9454 FAA R.S. N01R648Y

1-877-NFF-TOGO EASA.145.5059

ra

Fax: 724-378-9461

E-MAIL: info@nffavionics.com

WEBSITE: www.nffavionics.com

TEARDOWN AND DISPOSITION REPORT Page: 2 of 2

WORK ORDER No. 039960

- 2. Performance or sep cycling IAW OEM CMM specifications required.
- 3. General cleaning ar visual inspection of the Battery and Subassemblies.
- 4. Final Charging and Servicine AW OEM CMM specifications required.

Corrective Action

Verified MFR P/N and S/N of Battray. Generally cleaned and visually inspected the Battery and all Sub-Assemblies.

Battery serviced and fully charged per JEM CN M specifications. Installed Unit Cover Plate, OK for return to service in an Overhauled condition.

Hidden Damage

Inspected the Battery for hidden damage. No Flagen Tamage found.

A/D's,S/B's,E0's

This Battery meets all OEM CMM specification. ^ ___nandated requirements.

" SAFT Type p/n: 40176-7 is represented by SAFT P atery p/i 01/392-000."

Item	Part Number / Description	art Status Qty Cond	Discrepancy / Disposition
	PARTS & MATERIALS		
1	700220 Dust Cover Missing TAG #: REC-017061-2 TAG DATE: 30/OCT/2018	32 - Laned Component 1 EA NE	Disc. : Disp. : Installed in unit
The state of the s			

Authorized Signature

Copyright (c) PENTAGON 2000 Software, Inc.