1. Approving Civil Aviation 2.	ALITHORIZED BEI EVSE	EVOE	CERTIEICATE	3. Form Tracking Number:
FAA/United States	FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG	AIRWORTHINESS		110214
4. Organization Name and Address:	ICON AEROSPACE, LLC. 2617 EXECUTIVE POINT DR. MONROE, NC 28110	FAA Repair Station EASA Reference Ph: 704-821-4266	on : 681R700B : EASA.145.6295 56 Fax: 704-821-4286	5. Work Order/Contract/Invoice Numbe. W96353
6. Item 7. Description:	8. Part Number:	9. Quentity:	10. Serial Number:	11. Status/Work
1 ACTUATOR, SPEED BRAKE	R5303M1		1860129	1
12. Remarks: OVERHAULED In Acco	DVERHAULED In Accordance with CMM 27-44-02 Rev.: וו Date The above specified unit was manufactured by: WHIPPANY	Date: MAY/05/2017		
FULL DETAILS OF WORK CARRIE WORK ORDER NUMBER: W96353	FULL DETAILS OF WORK CARRIED OUT PER WORK ORDER NUMBER: W96353	COMPLIAN N/A	COMPLIANCE WITH MANDATORY AIP' ORT, 'NESS DIRECTIVES (ADS):	ESS DIRECTIVES (ADS):
		COMPLIAN N/A	COMPLIANCE WITH SE. VICE JULLE INS 'SBs/EOs): N/A	=Os):
Cerilifes to that w	Cerlifies that the work specified in blocks 11/12 was carried out in accordance with E^SA `art-14', and 's respect to that work, the component is considered ready for release to service under EASA P, 1.145, appr. ". Aumber EASA, 145.6295	accordance with EASA vice under EASA P. 1 14:	art-14 , and , respect Appr. Aumber EASA.145.6295	www.gov.yo.
139 - Certifies the items identified shove were manufactured in conformity to:	z were-manufapiured-in conformity-to:	14. 🗓 14	×	Other regulation specified in Block 12.
Approved design data and a	Approvad design data and are in a condition for safe operation.	Certifies	Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of	e work identified in Block 11 ance with Title 14, Code of
Non-approved design data specified in Block 12:		return to serviq	Federal Regulations, part 43 and in respect to that wor return to service.	in respect to that work, the items are approved for
Tour Aumorized Signature:	196 val. ulhori A.di	14b. Authoria	14b. Authorized Signature:	14c. Approval/Certificate No.: 68IR700B
13d. Name (Types or Printed):		14d. Name (J	14d. Name (Typed or Printed)	14e. Date (dd/mmm/yyyy)
		AL #X	ALEXSANDER GARCIA	20/Nov/2018
	User/Insta	User/Installer Responsibilities		
It is important to understand the title vision where the use valler performs ork is Block full is essentially that the user parties in vectors.	It is important to understand the the vistence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user—valler viforms—ork in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in the user of that it is user of a tailer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s)from the airworthiness authority of the country specified in vice.	/ constitute authority to orthiness authority diffe ots aircraft engine(s)/pro	Install the aircraft engine/propeller/article. rent than the airworthiness authority of the country specified in peller(s)/article(s)from the airworthiness authority of the country	untry specified in
Statements in B. ck 13s and 14s do not national regulation (F. the user/installer	Statements in B. ck 13a and 14a do not constitute instellation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulatio. 1-, the user/installer before the aircraft may be flown.	ft maintenance records r	must contain an installation certification issue	d in accordance with the



FAA REPAIR STATION 68IR700B EASA REFERENCE EASA.145.6295 2617 EXECUTIVE POINT DR. MONROE, NC 28110

Ph: 704-821-4266 Fax: 704-821-4286 EMail: sam@iconaerospace.com

Page 1 **WORK ORDER**

W96353

Date Rcvd: 16/Aug/2018

TEARDOWN REPORT

BURN OF AVIATION SUPPLIES, LTD. Burwood Hor Je 8 Besseme Close, Ebblake Incustri . Estate

Verwood, Doc et. ENGLAND BH31 7 12 Cust RO#: 110214

P/N: R5303M1

S/N: 1860129

Desc: ACTUATOR, SPEED BRAKE

Mfgr: WHIPPANY

Manual Loc: W-008

ATA: 27-44-02

Rev: 11

Rev Date: 05/May/2017

Tag Date: 20/Nov/2018

Contact: Gary Chapm in Contact Ph: 4412028 Contact Fax: 44120282341'

Reason Removed: UNIT NECEIVED FOR OVERHAUL AS PER O.E.M SPEC'S

FINDINGS

RECEIVING INSPECTION:

VERIFIED UNIT DATA PLATE, NO DISCREPANCI S FOUND.

PRELIMINARY INSPECTIONS:

TESTED UNIT, FAILED FUNCTIONAL TEST.

HIDDEN DAMAGE:

NONE

CONTINUED INSPECTION:

UNIT FAILED. DISASSEMBLED AND FOUND SWITCH ACTUATOR BROKEN CAUSING UNIT TO FAIL

CORRECTIVE ACTION: UNIT CONDITION OVERHALL

REPLACED PART(S) AS REQUIRED. CLEANED AND REASSEMBLEJ UNI TEST ED AS PER O.E.M. SPEC'S.

SB's, AD's, EO's and RMK's:

NONE

CERTIFICATION

Service Performed:

OVERHAULED

MODIFIED TO:

PARTS AND MATERIALS

QTY 1

PART NUMBER

5730239-1

DESCRIPTION

ACTUATOR, SWITCH

COND

NE

MAINTENANCE RELEASE

The component identified above was serviced as specified above in accordance with the current regulations of the Federal Aviation Administration and is approved for return to service. Other pertinent details of the repair at the at this

APPROVED FOR RETURN TO SERVICE BY:

ALEXSÁNDER GARCIA

DATE:

2 /1 ov/2017

FORM IAF-3116 (TDR) REV 01/10

www.ILSmart.com/Optimizer © ILS eBusiness Services, Inc.

Pr ced by ILS Optimizer