1. Approving Competent Authority 2.		3. Form Tracking Number:
CAA.UK	AUI NORISED RELEASE CERTIFICATE EASA FORM 1	W201817341
4. Organization Name and Address:	Avia Technique Ltd.	
Avia Technique	Unit 1,3,4 & 6 Fishponds Estate Fishponds Road	Invoice Jumbs
SK Acrosarety Group	Wokingham, Berkshire, United Kingdom RG41 2QJ Ph: +441189799789 Fax: -444189797851	W20, 91734
	rn: +441189789789, Fax: +441189784511	111,141
6. Item: 7. Description:	8. Part Number: 9. Quantily: 10 Serial Number:	Status I Missla
1 Evacuation Silde Assembly	100	Organia WOIN.
12. Remarks:		Overnauled
CMM: 25-66-07 Revision: 13	The wick identified in accomplished in accompl	The \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
Cylinder: P/N 61768-101, S/N 6202-5343, D		wc/k, the items are approved for return to service under ate no. IBQY183X*
Battery: P/N D19859-103, S/N 63338, DOM 03-2018, Expiry Date 04-2022. Battery: P/N D19859-103, S/N 63338, DOM 03-2018, Expiry Date 03-2023 Escape Slide: DOM 07-2007, Last Maintenance 12-2018, Next Maintenance 12-2021, Avia Technique have checked and verified that there are no pertinent AD's or SB's rel	Avia Technique have checked and verified that there are no perlinent AD's or SB's relevant.	
13a. Certifies that the items identified above were manufactured in conformit, to:	14a. X Part-145.A.50 Release to Service X	Other regulation specified in Block 12
Non-approved design data and are in a condition for safe open. Non-approved design data specified in Block 12.	Certifles that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Part-145, and in respect to that work the flems are considered ready for release to service.	work identified in Block †1 and ith Part-145, and in respect to that e.
		TO THE PART OF THE
1.30: Aurilolised Signature;	'arilly' Ate /Approval Ref No.:	14c. Certificate /Approval Ref No.:
19d Name		UK.145.00846
	136: Date (dd/mmm/yyyy): 14d. Name	14e. Date (dd/mmm/yyyy):
	Gary Jones 20/D	20/Dec/2018
	USER / INSTALLER RESPONSIBILITIES	
This c. tificate . tes n. tautomatically constitute authority to install the item(s).	authority to install the item(s).	
\	A LATE the Viser/Unstaller performs work in accordance with regulations of an Airworthiness Authority different than the Airworthiness Authority specified in block 1, it is essential that the Jerry Vision and Indian State (Indian State). Sery State (Indian State).	1, it is essential that the
tate vents in blocks 13a and 14a do not constitute installation certification of the aircraft may be flown. Johal regulations by the user/installer before the aircraft may be flown.	tate Jents in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the Lorent formula in the contains by the user/installer before the aircraft may be flown.	sued in accordance with the



Avia Technique Ltd. Unit 1,3,4 & 6 Fishponds Estate

Fishponds Road

Wokingham, Berkshire, United Kingdom **RG41 2QJ**

Ph: +441189789789, Fax: +441189794511

Tear Down/Inspection

Work Order #: W201817341

Date Printed:

24/10/2018

Page:

Burwo a Avi. tion Supplies Ltd 8 Bessemer Cl se Burwood Hy ase Verwood, Free SH31 6AZ United Kingdo A

Ship To:

Burwood Aviation Supplies Ltd 8 Bessemer Close **Burwood House** Verwood, Dorset BH31 6AZ United Kingdom

Reference:

110 141

Date Received: 19/16,701

61621-469

Part Number:

Description:

Evacuation Slide Ar embly

Serial Number: 1941A

Customer Remarks:

Overhaul

Results from inspection:

Unit requires Overhaul

Slide DOM

Slide DOM: 07-2007 Last Maintenance: 01-2016 Reservoir DOM: 04-2007 Reservoir Life Expires: 04-2022 Battery DOM: 12-2015 Battery Life Expires: 12-2020

Faults.

Shipping Container missing. Safety Pin missing
Frangible Link damaged from Slide being received deployed. Ball Guide and Reservoir Fitting require replacement due to SIL 25-181. Power Unit has Short Life.

Corrective actions:

Overhaul with reference to the correct CMM Rev

Fit replacement:

- Reservoir Fitting and Ball Guide
- Power Unit
- Shipping Container Safety Pin
- Frangible Link

Test and Certify with reference to the correct issue of the CMM.

Inspection report generated by: Ryan Handisides

Reference: SK-GF-005

Issue: Initial