Authority/Country FAA/United States	AUTHORIZED RI	RELEASE CE	CERTIFICATE	3. Form Tracking Number ARCAD1179418
	FAA Form 8130-3, AIR	FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG	OVAL TAG	77C7U179410
4. Organization Name and Address StandardAero Component Services, Inc.	ent Services. Inc.			5. Work Order/Contract/Invoice Number
11550 Mosteller Rd. StandardAero CINCINNATI, OHIO, USA 45241	A 45241 Repair Station # T3LR667N	_R667N		AD385938
5. Item 7. Description	8, Part Number	9.	10.	
NO 1 BE	A128T02C02	Quantity	S	Status/Work
	4120103602		WIN893DW	OVERH ALL TO
12. Remarks Customer: BURWOOD AVIATION SUPPLIES LTD Customer PO: 110561	АТА	72-21-09 Additional Comme	Manual Ref. GEK 105091 - (CF34-8C) Rev:47) Rev:47 01-APR-, 118
Release/Hem: 1				
Rep Number(s) / SB(s): SPM 70-48-12 Non Conformance Record(s): N/A				
Removed From ESN: GE-E194264 TSN - UNK CSN - UNK TSO - 0.0 CSO - 0	0			
			* (
RandardAero Component Services, Inc. certifies that the work specified in block 11/12 was carried out in accordance with EASA Part-145 and . *espect o that w. 2ASA, 145, 1939.	block 11/12 was carried out in accordance with F	EASA Port-145 and . respect of		'k the component is considered rendy for release to service under EASA Part-145 Approval Number:
3a. Certifies the items identified above were manufactured in conformity to		14a. X) . CFR 43:	CFR 43.9 Return to Service	X Other regulation specified in Block 12
Non-approved design data specified in Block 12.		Cert Tes that unless of 12 was accomplished work, the items are at	Cert Tes that unless otherwise specified in Block 12, the work 12 was accomplished in accordance with Title 14, Code of Fed work, the items are approved for return to security.	Cert Tes that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to sometime.
0.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1				
N/A	13c. A Why thoriz don No.	14b. Authorized Signature	The state of the same	SACS 14c. Approval/Certificate No T3LR667N
3d. Name (Typed or Printed) N/A	1 (c. Ds. 122_mmm/yyyy) N/A	14d. Name (Typed or Printed)	ud) JOSEPH BRADY	14c. Date (dd/mmm/yyyy) 01-Mar-2019
	User/inst	User/Installer Responsibilities		
is important to understand that the existence of , 's doc, 'vent alone does not automatically constitute authority to install the aircraft engine/propeller/article,	ees not automatically constitute authority to i	nstall the afreraft engine/prope	ller/article,	
There the user/installer perform ""rk in "cordane, with a national regulations of an airworthiness anthority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her inworthiness authority access an airworthiness authority of the country specified in Block 1.	ith tendional regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block t.	lifferent than the airworthiness try specified in Block 1.	s authority of the country specified in Block (,	it is essential that the user/installer ensures that his/he
intements in Blocks 13a and F. P. act co. vitute installation certifica	lion. In all cases, aircraft maintenance recor	ds must contain an installation	certification issued in accordance with the nati	vifute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft



STANDARDAERO COMPONENT SERVICES, INC. 11550 MOSTELLER ROAD CINCINNATI, OH 45241 USA PH: (513) 618-9588

Work Order: AD385938

Custome (

BURAVI BURWOOD AVIATION SUPPLIES LTD

Customer PO Rei / Item:

110561 1

Customer WQ:

Findings Report

Er o 'stome

03-Nov-2018

End Cust PO: Engine Model:

Attention:

DAVE DAUGHTERS

Pate Re 'u. OLM THE

4126T03G02

ATA / Chapter: 72-21-09

CF34-8C5B1

Qty Received: 1 Qty Repair:

Modify to 'N: N/A Descrip on:

J.1 BEARING HOUSING

Engine S/N:

GE-E194264

Qty Reject:

Repairs

Serial Number WIN893DW

Rep Qty Repair

SPM 70-48-12

Repair Reason

SHOULDER PIN BENT - REPLACE

Reject Material (Matrial) 'ot Repaired)

N/A

ej Qty Reject Description

N/A

Reject Reason

N/A

A vove inf mation may not represent all defects / rejection descriptions

Additional Notes

N/A

Authorized Representative:

Date: 28-Jan-2019

ALEXANDER OLVEDA

These findings are as received. During the repair process and subsequent inspections, there may be causes to require addition. I repair locast is Content is confidential and proprietary to StandardAero. Information shall not be reproduced or disclosed to third parties without the written consent of standardAero.

Date Printed: January 28 2019 15:09:47

Page 1 of 1

(SPO) DVR