Block 1,it is essential that the user/installer ensures that his/her airworthiness authority accepts aircreft engine(s)/propeller(s)/article(s)from the airworthiness authority of the country It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. 13a. Certifies the items identified above were ma. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in 12. Remarks: REPAIRED In Accordance with CMM 34-12-19 Rev.: 6 Date: AUG/15/2004 ISIG - Namir (1990) Q. Te 6, item Organization Name and Address: 1. Approving Civil Aviation Sb. Authorized Signature FAA/United States Authority/Country Non-approved design data - diet, n-Bloc - Y-Approved design data and are in a sndittle WORK ORDER NUMBER: W118554 FULL DETAILS OF WORK CARRIED OUT PER The above specified unit was manufactured by: GOODRICH SENSOR, ANGLE OF ATTACK Description: to that work, the component is consid. 'ed . 'dy for re..' 's to service under EASA Part 145 Approval Number EASA.145.6295 Certifies that the work specified in bl. . 11/12 ws. "arr ad out in accordance with EASA Part-145, and in respect 2617 EXECUTIVE POINT DR ICON AEROSPACE, LLC. MONROE, NC 28110 **AUTHORIZED RELEASE CERTIFICATE** 861CAS3 dagtured in a m' willy. dor sale operation Part Number: FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG User/installer Responsipilities 9. Quantity: **EASA Reference** Ph: 704-821-4266 Fax: 704-821-428/ FAA Repair Station : 68IR700B C. MPLIANCE WITH SERVICE BULLETINS (SBs/EOS): COL PLIAN 'E V'TH MANDATORY AIRWORTHINESS DIRECTIVES (ADS): 14d. Wame (Typed or Printed) 14b. Authorized Signature: 14a. X 14 CFR 43.9 Return to Service ALEXBANDER GARCIA and described in Block 12 was accomplished in accordance with Title 14, Code of Certifies that unless otherwise specified in Block 12, the work identified in Block 11 return to service. Federal Regulations, part 43 and in respect to that work, the items are approved for ö, : EASA.145.6295 02127 Serial (umber: 区 Other regulation specified in Block 12. 11. Status/Work: REPAIRED 5. Wo. Irder/Contract/Invoice Number: 3. Form Tracking Number: W118554 14e. Date (dd/mmm/yyyy) 11602 14c. Approval/Certificate No.: 03/Sep/2019 68IR700B

specified in Block 1.

national regulations by the user/installer before the aircraft may be flown.

Statements in Block 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the



FAA REPAIR STATION 68IR700B EASA REFERENCE EASA.145.6295 2617 EXECUTIVE POINT DR. MONROE, NC 28110

Ph: 704-821-4266 Fax: 704-821-4286

EMail: sam@iconaerospace.com

WORK ORDER W118554

Date Rovd: 03/Jul/2019

TEARDOWN REPORT

BURWOOD AVIATION COPP LIES, LTD.

Burwood House 8 Bessemer Close,

Ebblake Industrial Estate

Verwood, Dorset. ENGLAND BH31 6AZ Cust RO#: 111602

P/N: 861CAS3

S/N: 02127

Desc: SENSOR, ANGLE OF ATTACK

Mfgr: GOODRICH

Manual Loc: GA-039

ATA: 34-12-19

Rev: 6

Rev Date: 15/Aug/2004

Tag Date: 03/Sep/2019

Contact: DARON GOLDING Contact Ph: 44-1202-825434 Contact Fax: 44-1202-823416

Reason Removed: UNIT RECEIVED FC & BENC & CHECK AS PER O.E.M. SPEC'S.

FINDINGS RECEIVING INSPECTION: VERIFIED UNIT DATA PLATE, NO DISCREPANCIES FOUND. PRELIMINARY INSPECTIONS: TESTED UNIT. FAILED FUNCTIONAL TEST HIDDEN DAMAGE: NONE CONTINUED INSPECTION: TESTED, FOUND UNIT CONTAMINATED, UNIT HAS A BAD VANE, DISASSEMBLY & RECY. LED. CORRECTIVE ACTION: UNIT CONDITION REPAIRED REPLACED PART(S) AS REQUIRED. CLEANED AND REASSEMBLED UNIT. TESTED AS 7 LR O.E.M SPEC'S. SB's, AD's, EO's and RMK's: NONE CERTIFICATION Service Performed: X REPAIRED MODIFIED TO: PARTS AND MATERIALS QTY **PART NUMBER** DESCRIPTION COND

MAINTENANCE RELEASE

The component identified above was serviced as specified above in accordance with the current regulation and is approved for return to service. Other pertinent details of the repair are on file at this repair station.

APPROVED FOR RETURN TO SERVICE BY:

00861-1054-0001

ALEXSANDER GARCIA

VANE

DATE:

03/Sep/2019

FORM IAF-3116 (TDR) REV 01/10

www.ILSmarl.com/Optimizer © ILS eBusiness Services, Inc.

Printed by ILS Optimizer