

1. Approving Competent Authority/Country

2.

CAA / United Kingdom

AUTHORISED RELEASE CERTIFICATE EASA FORM 1

3. Form Tracking Number

ARC41524

4. Organisation Name and Address



Oakerhurst Aircraft Services Ltd
Chrysdens Lane
Ropleigh, Essex
SS0 7JF
United Kingdom
Tel: +44 (0)1206741022
Fax:
Email: sales@oakerhurst.com
Web: www.oakerhurst.com

5. Work Order / Invoice Ref/Invoice

W2417/3 / 105925

6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No.	11. Status/Work
1	A.C Generator	976J490-2	1	PP15409	Overhauled

12. Remarks

The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the bar code is approved for return to service under certificate no. OSK1452V.
Work as stated in box 11 has been carried out in accordance with manufacturers manual No. 24-20-77, Rev 36, 1502117, 88 976J490-24-2 Embodiment, (Ceramic Bearings), TSO-04HRS CSO-0.

TSN: NIK, TSO: NIL, CSN: NIK, CSO: NIL

13a. Certifies that the items identified above were manufactured in conformity with:

- Approved design data and are in condition for safe operation
- Non-approved design data specified in block 12

14a. Part-145, A.50 Release to Service

Other regulation specified in block 12

Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.

13b. Authorised Signature	13c. Certificate/Approval Number	14b. Authorised Signature	14c. Certificate/Approval Ref. No.
			UK.145.00524
13d. Name	13e. Date (dd mmm yyyy)	14d. Name	14e. Date (dd mmm yyyy)
		Mr Billy Lander	28 Jun 2018

USER/INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute an authority to install the item(s). Where the user/installer performs the work, in accordance with regulations of an airworthiness authority specified in block 1, it is essential that the user/installer ensures that higher airworthiness authority accepts items from the work as authorised by the certificate issued in block 1. Statements in blocks 11 and 14a. constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



Oakenhurst Aircraft Services Ltd
 Claydons Lane
 Rayleigh, Essex
 SS6 7UP
 United Kingdom
 Tel: +44 (0)1268741622

EASA Part 145 UK.145.00524

FAR 145: O5KY452Y

Workshop Report

No: IR41621

Issue: 01

Date: 13-Jun-18

Burwood Aviation Supplies Limited Burwood House Bessener Close Weymouth Dorset BH31 6AZ United Kingdom Attn: Mr Daron Golding Tel: +441202825434 Fax: +441202823416 E-Mail: sales@burwood.aero			
Your Ref: 109925	Our Ref No: WP41763	Test Required: N/A	
Part No: 976J458-2	Description: A.C Generator	TSN: N/K	CSN: N/K
Serial No: PP15409	Workscope: FP&E-M Overhaul	TSO: N/K	CSO: N/K
DoM:	Overhauled:	Inspected:	
Removed From:	Serial No:	Reg No:	Position:

Inspection Findings:

Unit received for overhaul without any reported defects. Initial inspection and testing carried out. Generator passed testing however unit required to be disassembled for further test and inspection to be carried out. Bearings and bearing shield found to be worn. Bearings found to be PMA part. Unit requires overhaul, replacement parts, re-assembly, final test and inspection to be carried out. Please note that SB 24-3 will be embodied prior approval. New Ceramic bearings will be fitted as per SB 24-3. Unit received with no hours. Quote is for standard overhaul only.

Unit has been cleaned, replacement of parts, reassembled and final test.

Signed:  Name: B. LANDER Date: 28/06/18

For and on the behalf of Oakenhurst Aircraft Services Ltd

Registered address:- Claydons Lane, Rayleigh, Essex, SS6 7UP