

1. Approving Competent Authority / Country

2.

61507198



3. Form Tracking Number

20014685 00000001

**AUTHORISED RELEASE CERTIFICATE
EASA FORM 1**

4. Organisation Name and Address:



Lufthansa Technik

Lufthansa Technik AG
Weg Belm 193
22335 Hamburg
Germany

5. Work Order/Contract/Invoice

61507198

6. Item

7. Description

8. Part No.

01 OFFWING RAMP/SLIDE RH

4A3931-10

9. Qty.

10. Serial No.

1

AT0096

11. Status / Work

OVERHAULED

Burwood Aviation Supplies Ltd. 110207

ATA 2562

TP O

MK-No. 10

Pack Code 00

Res. Workshop 33533112

Workshop Station FRA031

See referred CMM for next recommended maintenance:
Slide DOM: 09.2006

TT UNKNOWN UNKNOWN UNKNOWN
TSO 0 0 0
TSC 0 0 0
TSF 0 0 0

TASK PERFORMED IN ACCORDANCE WITH CMM 25-62-24
REV. 4 / CMDS 25-62-24 ISSUE 020

Return to Service in Accordance with 14 CFR part 43
The work identified in block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work the items are approved for return to service under
FAA Certificate No. DLA7225D

13a. Certifies that the items identified above were manufactured in conformity with:
 approved design data and are in a condition for safe operation
 non-approved design data specified in block 12

14a. Part-145, A.50 Release to Service
Further details of work performed are attached either in a Workshop Report (reference number, see blocks 3 and 5) or in other applicable documents.
 Other Regulation specified in block 12
Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part- 145 and in respect to that work the items are considered ready for release to service.

13b. Authorised Signature

14b. Authorised Signature

031342

Guido Lehnert

14c. Certificate / Approval Ref. Number

DE:145.0001

13d. Name

13e. Date (dd mmm yyyy)

14d. Name

14e. Date (dd mmm yyyy)

EASA FORM 1 - Issue 2
USER/INSTALLER RESPONSIBILITIES

Note: (this certificate does not automatically constitute authority to install the item(s).
1. The user/installer performs work in accordance with regulations of an airworthiness authority different from the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her work is authorised by the airworthiness authority specified in block 1.
2. The user/installer must ensure that the aircraft is in a condition for safe flight before the aircraft may be flown.

Workshop Report



Lufthansa Technik

Lufthansa Technik AG
 Weg beim Jäger 193
 22335 Hamburg
 Germany

61507198

Certificate Ref. No.

2C 114686 000 0001

Work Order/C Intract/Invoice

61507198



Part. No. as received
 4A3931-10

Serial No. as received

AT0096

Part No. as dispatched
 4A3931-10

Serial No. as dispatched

AT10096

Reason for removal
 Overhaul

Findings

Slide has to be overhauled.
 Zea hole plug missing.
 Enclosure has to be repainted (customer request)

Modification Status according to Mod-Label
 See Unit Mod-Label if equipped

Action
 Slide Overhauled.
 Zea Hole Plugs changed.
 Enclosure repainted.

The work specified above has been performed subject to Lufthansa Technik's Standard conditions for Technical Services which, if not superseded by a later agreement or not yet agreed upon before, are acknowledged by the customer with acceptance of the part(s) hereunder.

Name

31342, Guido Leinert

Date (dd mm yy)

04 Sep 2018