



61510245

1. Approving Competent Authority / Country
LBA / Germany

2. Form Tracking Number
24901 00000001

**AUTHORISED RELEASE CERTIFICATE
EASA FORM 1**



Lufthansa Technik

4. Organisation Name and Address:
Lufthansa Technik AG
Wendheim, Lager 193
22333 Hamburg
Germany

5. Work Order/Contract/Invoice
61510245

6. Item
01 EMERGENCY EVACUATIONSLIDE FWD

7. Description
EMERGENCY EVACUATIONSLIDE FWD

8. Part No.
104003-2

9. Qty. 10. Serial No.
1

11. Status / Work
OVERHAULED

12. Remarks
Burwood Aviation Supplies Ltd. 110235
ATA 2565 TPO MK-No. 10 Pack Code 00 Resp. Workshop 33533111 Workshop Station FRA031

SBC 104003-25A403, Rev. 00 performed
SBC 25A436, Rev. 01 performed
See referred CMM for next recommended maintenance.
Slide DOM: 02.2009 S/N: FH1879
Cylinder Assy Charged P/N: 4A4089-7 S/N: 12.2008
Cylinder Body P/N: 630124-14 DC: 12.2008
Cylinder last HST: 09.2018 next HST: 12.2023
Valve Assy P/N: 4A4047-7 S/N: N: 147
Battery P/N: 780134-3 EXP: 04.2021
Part is in compliance with I.A.W. FAA A 171.3-2b.1
Subassembly earliest expiry date see below.
Expiry Date Sep. 2023

Return to Service in Accordance with 14 CFR part 43
The work identified in block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work the items are approved for return to service under
FAA Certificate No. DLAY225D

13a. Certifies that the items identified above were manufactured in conformity with approved design data and are in a condition for safe operation
 approved design data and are in a condition for safe operation
 Part-145.A.50 Release to Service
Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.

Further details of work performed are attached either in a Workshop Report (reference number: see blocks 3 and 5) or in other applicable documents.


13b. Authorised Signature
13c. Approval / Authorisation Number
13d. Name
13e. Date (dd mmm yyyy)

14a. Authorised Signature
14b. Name
14c. Certificate / Approval Ref. Number
14d. Date (dd mmm yyyy)

EASA FORM 1
USER/INSTALLER RESPONSIBILITIES

Note: This certificate does not automatically constitute authority to install the item(s).
Where the user/installer performs work in accordance with regulations of an airworthiness authority different from the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.
Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

Workshop Report

Customer Order No. 110235	 Lufthansa Technik Lufthansa Technik AG Weg beim Jäger 193 22335 Hamburg Germany	Certificate Ref. No. 61510245
Part. No. as received 104003-2	Serial No. as received EF0926	Work Order/Contract/Invoice 61510245
Part. No. as dispatched 104003-2	Serial No. as dispatched EF0926	Description EMERGENCY EVACUATIONSLIDE FWD
Reason for removal For overhaul.		
Findings Cylinder assy charged, time expired. Battery damaged. Washer Isolator damaged. SBC 104003-25A403 Rev. 00 must be performed. SBC 25A436 Rev.01 must be performed.		
Action SBC 104003-25A403, Rev. 00 performed SBC 25A436, Rev. 01 performed Overhauled cylinder assy charged, installed. Battery replaced. Washer Isolator replaced. Subassembly earliest expiry date see below. Expiry Date Sep. 2023		
Modification Status according to Mod-Label SB 25-394 SB:25A403 SB:25A436		
Responsible Workshop 33533111		
Name 31342, Guido Leinert		
Date (dd mmm yyyy) 17 Sep 2018		

The work specified above has been performed subject to Lufthansa Technik's Standard conditions for Technical Services which, if not superseded by another agreement or not yet agreed upon before, are acknowledged by the customer with acceptance of the part(s) hereunder.

Workshop Report



Lufthansa Technik

Lufthansa Technik AG
Weg beim Jäger 193
22335 Hamburg
Germany

Customer Order No. 110235	69115665 Certificate Ref. No.
Part No. as received 4A4089-7	Work Order/Contract No. 003875 00000001 //A
Part No. as dispatched 4A4089-7	Description CYLINDER ASSY, CHARGED
Reason for removal For overhaul.	Responsible Workshop 33533240
Findings Time expired, received deployed Reservoir internal and external visual examined without findings. Fusible Plug damaged	Modification Status according to Mod-Label See Unit Mod-Label if equipped
Action Fusible Plug replaced Overhauled. Hydrostatic-Test performed: 06.09.2018 Reservoir Body P/N: 630124-14 DOM: 01.12.2008 NEXT HST: 09-2023 Valve Assy P/N: 4A4047-7, S/N: N-1947 See referred CMM for next recommended maintenance	Name 42264, Karlheinz Metternich
	Date (dd mmm yyyy) 12 Sep 2018

The work specified above has been performed subject to Lufthansa Technik's Standard conditions for Technical Services which, if not superseded by another agreement or not yet agreed upon before, are acknowledged by the customer with acceptance of the part(s) hereunder.