

Inflite MRO Services Ltd North Hangar Aviation Way Southend-on-Sea Essex SS2 6UN United Kingdom

WAS (COMPONENT. 6) LTD: F \SA Part 145: UK.145.00579:

Tel: +44(0)1702 348601 WAS (COMPONENTS) LTD: FAA Repair Station: EGWY725K:

Workshop Reprirt

No: IR61118

issue: 01

Date:

05-Jun-18

**AERS Limited** Hangar A1 London Southend Arr ort Essex **SS2 6UN** United Kingdom

Attn: Henry Hyde

Tel: 01702 533988

Fax:

E-Mail:

Your Ref: A00383

Our Ref No: WP60569

Required: N/A

Part No: 746A0000-06

Description: PRV

Serial No: 0746A00L1001954

Workscope: Repair Dept: Pressurisation Works Release Type: Dual

Removed From:

Serial No:

Rer No:

Position:

Workscope Overview:

UNIT SUPPLIED FOR INSPECT &TEST

## Inspection Findings:

UNIT FAILED TEST FOUND FILTER BLOCKED, INGRESS OF DIRT, ATO PRESSURE REGULATOR, MAIN DIAPHRAGM HOLED.

REQUIRES NEW FILTER, DIAPHRAGM AND ORING REQUIRE REPLACEMENT

REPAIRED AND TESTED I.A.W LIEBHERR 21-62-11 REV 6 SEP 1/14.

Signed:

Name: A. W. CARTER

Date:

0 \$ NOV L018

For and on the behalf of Inflite MRO Services Ltd

Registered address:- Inflite House, Stansted Airport, Stansted, Essex, CM24 1RY