

1. Approving Competent Authority/Country
CAA / United Kingdom

2. **AUTHORISED RELEASE CERTIFICATE**
EASA FORM 1

3. Form Tracking Number
ARC50435

4. Organisation Name and Address



Oakenhurst Aircraft Services Ltd
Claydon's Lane
Rayleigh, Essex
SS6 7UP
United Kingdom
Tel: +44 (0)1268741622
Fax:
Email: sales@oakenhurst.com
Web: www.oakenhurst.com

5. Work Order/Contract/Invoice

WP50922 / 111107 - ITE 12

6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No.	11. Status/Work
1	Ballast Unit	3250-80	1	18857	Repaired

12. Remarks

The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under certificate no. OSKY452Y.
Work as stated in box 11 has been carried out in accordance with manufacturers manual No. ATA 33-24-16 Revision 3 Dated 25 JUL 2000

13a. Certifies that the items identified above were manufactured in conformity to:

- Approved design data and are in condition for safe operation
- Non-approved design data specified in block 12

14a. Part-145, A.50 Release to Service

Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.

Other regulation specified in block 12

13b. Authorised Signature

13c. Approval/Authorisation Number

14b. Authorised Signature

14c. Certificate/Approval Ref. No.
UK.145.00524

13d. Name

13e. Date (dd mmm yy)

14d. Name
Mr Robbie Bates

14e. Date (dd mmm yyyy)
21 Mar 2019

USER/INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authorisation to install the work specified in block 11. It is essential that the user/installer ensures that his/her airworthiness authority accepts Where the user/installer performs work in accordance with the regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute national certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



Oakenhurst Aircraft Services Ltd
 Claydons Lane
 Rayleigh, Essex
 SS6 7UP
 United Kingdom
 Tel: +44 (0)1268741622

EASA Part 145: UK.145.00524

FAR 145: O5KY452Y

Workshop Report

No: IR50711


Issue: 01

Date: 14-Mar-19

Burwood Aviation Supplies Limited Burwood House 8 Messener Close Verwood Dorset BH31 3AZ United Kingdom			
Attn: - Tel: 0044 (0) 1202 815434 Fax: 0044 (0) 1202 823416 E-Mail: repairs@burwood.com			
Your Ref: 111107 - ITEM 2	Our Ref No: WP50922	Test Required: N/A	
Part No: 3250-80	Description: Ballast Unit	TSN: N/A	CSN: N/A
Serial No: 18857	Workscope:	TSO: N/A	CSO: N/A
DoM:	Overhauled:	Inspected:	
Removed From:	Serial No:	Reg No:	Position:

Inspection Findings:

Received in poor condition for repair. Inspected and found to have dirt and dust contamination, dirty and tarnished loose lampholder contacts. Internal inspection found dry joints on pcb which require reflow for continued reliability. Initially tested and operated normally.
 Work required: Dry joints reflowed, cleaning, lampholder contacts to be cleaned, burnished and re-tensioned and full function testing in accordance with CMM.
 Inspected and electrically checked. Repaired. Full function tested in accordance with CMM.

Signed: [Signature]  Name: MR R BATES Date: 21/MAR/2019
 For and on the behalf of Oakenhurst Aircraft Services Ltd

Registered address:- Claydons Lane, Rayleigh, Essex, SS6 7UP