13b. Authorized Signature	 3 &	13a. Cantias di	Details of this work order out in accordance with I Number EASA 145.4680	12. Remarks:	-	6. Item:		4. Organizatio	FAA/I	, A
I Signature:	Approved design data and are in a condition for ask Non-approved design data appended in a rek (3)	13s. Centres the terms identified above were manufactured in conformity to	is work order are on dance with EASA Pa 3A 145.4680.	Unit REPAIRED IAW CMM A09-1147-038 R	BEZEL CONTROLLER	7. Description:	To the second se	4. Organization Name and Address:	Approving Civil Aviation Authority/Country: FAA/United States	ST OF STATE
	e ih e sondilon for vedilgel in a tek 13	manufactured in o	file at this faci t 145 and in r	AW CMM A09- ESS DIRECTIV	LER L		TEL: 816-52	Millenniu 1825 SW I Lee's Sum	<b>&gt;</b>	•
13c. Approval/Authorization No.:	O Service Control of the Control of	oriformity (b)	Details of this work order are on file at this facility under the order referenced to block 3 of this form. Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the considered ready for release to service under EASA Part-145 Approval Number EASA 145,4680.	Unit REPAIRED IAW CMM A09-1147-038 Rev 5 dated 08/25/2016 NO AIRWORTHINESS DIRECTIVES APPLY	7014332-931	8. Part Number:	TEL: 816-524-7777 FAX: 816-554-0042	Millennium International 1825 SW Market Street Lee's Summit, MO 64082	AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG	AND THE RESERVE OF THE PROPERTY OF THE PROPERT
14b. Authorized Signature:	Certifies that unless otherwise in Block 12 was accomplished and in respect to that work, the	14a. 🛭 14 CFR 43.9 Return	block 3 of this this considered			9. Quantity:			LEASE O	
inature:		to Service	form. Certifies that the wo		99012390	1. Seriel Jumber:	FAA REPAIR STATION N. TXP. 367N		DERTIFICATE PPROVAL TAG	The state of the s
14c. A	2, the work identifi Title 14, Code of F for return to servi	Other Regulation	rk specified in e under EASA				2967N	S. Nu	ω	
14c. Approval/Certificate No.:	specified in Block 12, the work identified in Block 11 and described in accordance with Title 14, Code of Federal Regulations, part 43 items are approved for return to service.	☑ Other Regulation Specified in Block 12	tifies that the work specified in block 11/12 was carried release to service under EASA Part-145 Approval		REPAIRED	11. Status/Work:	111341	5. W. 'k Order/Contract/Invoice Number:	3. Form Tracking Number: 1 11-49685	

It is imponent to understand that the existence of this Document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

User/Installer Responsibilities

13d Name (Typed or Printed)

13e, Dafe (dd/minin/yyyy);

14d. Name (Typed or Printed):

14e. Date (dd/mmm/yyyy):

M7XR967N

20/MAY/2019

Wade E. Drake

When the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the alworthiness authority of the country specified in block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



A NEW ERA IN SUPPORT

1825-2 SW N - 1 Street, Lees Summit, MO 64082

Ph: 816-5" -7777 ax: 816-554-0042

FAA 5' #: \ '7XF 67N Web: www.ar onics411.com WORK ORDER: MI-49685



START: 05/16/2019 09:49:49

: 44-1276-855977

: HONEYWELL

FINISH: 05/20/2019

PART#: 7014332-931

MODEL: BL871

SERIAL: 99012390

FAX

MFG

М	: I I	nn	~:			14#	100
141	111	CII	111	um	-	VV.	ľU

CUST COL =

CBURAVI1

PHONE

: 4 -- 76-855966

NAME

BURWOOD AVIATION SUPPLIES LTD

**ADDRESS** 

BURY OOD HOUSE

8 B' SCT. ER CLOSE, EBBLAKE INDUSTRIAL ESTATE

**VERWC JD, DORSET BH316AZ** 

ENGL A

**CUST PO# INVOICE#** 

email inv:gr y@wwood.aero : 111341

CUSTOMER INSTRUCTIONS / COM' ÆNTS: **EVAL/REPAIR** 

TASK:1 PRELIMINARY INSPECTION:

**DISCR ACTION:** 

Functional test found rotary switch interm. "and one lamp is INOP. Unit requires disassembly, cleaning, replacement of defective components, reassembly, and final testing in accordance with OEM specifications.

TASK:2 HIDDEN DAMAGE INSPECTION:

**DISCR ACTION:** 

n/a

TASK:3 IN PROCESS INSPECTION:

**DISCR ACTION:** 

TASK:4 WORK ACCOMPLISHED:

DISCR ACTION:

Disassembled unit, replaced defective components, cleaned/inspirete, reas simbled, and final tested in accordance with manufacturers specifications, Found unit airworthy.

Technician: TASK:5 PARTS USED:

PART NUMBER

DESCRIPTION

1800-4271

ROTARY SWITCH

7001168-15

LAMP

QTY

1

**TASK:6 FINAL INSPECTION:** 

DISCR ACTION:

REPAIRED

					CRS # M7XR967N			

regulations of the EAA and is appliance identified was repaired and inspected in accordance wit		
regulations of the FAA and is approved for return to service.	I CU	rrer
and is approved for return to service.		

Signed:

Name: Wade E. Drake

Date: 5-20-