

1. Approving Competent Authority / Country  
**CAA, UK**

2. **AUTHORISED RELEASE CERTIFICATE**  
**EASA FORM 1**

3. Form Tracking Number:  
**W201908773**

4. Organization Name and Address:  
**Avia Technique Ltd.**  
 Unit 1,3,4 & 6 Fishponds Estate  
 Fishponds Road  
 Wokingham, Berkshire, United Kingdom RG41 2QU  
 Ph: +441189789789, Fax: +441189794511

5. Work Order / Contract / Invoice Number:  
**201908773**  
**11134**

6. Item	7. Description	8. Part Number	9. Quantity	10. Serial Number	11. Status / Work
1	Evacuation Slide	62293-109	1.00	C 403	Overhauled

12. Remarks:  
 CMM: 25-66-11 Revision: 14



Escape Slide: DOM 12/1998 Last Maintenance 06/2019, Next Maintenance 06/2020.  
 Avia Technique have checked and verified that there are no pertinent AD's or SB's relevant.

"The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR Part 43 and in respect of the work, the items are approved for return to service under certificate no. 18QY183X"

13a. Certifies that the items identified above were manufactured in conformance with the applicable regulation.  
 Approved design data and are in accordance for installation.  
 Non-approved design data specified in Block 12


14a.  Part-145, A.50 Release to Service  
 Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Part-145, and in respect to that work the items are considered ready for release to service.

13b. Authorised Signature:	13c. Certificate /Approval Ref No.:	14b. Authorised Signature:	14c. Certificate /Approval Ref No.:
			<b>UK. 145.00846</b>
13d. Name	13e. Date (dd/mm/yyyy):	14d. Name	14e. Date (dd/mm/yyyy):
		<b>Ryan Handisides</b>	<b>04/Jun/2019</b>

**USER / INSTALLER RESPONSIBILITIES**

The certificate holder is not automatically constitute authority to install the item(s).  
 Where the user/installer performs work in accordance with regulations of an Airworthiness Authority different than the Airworthiness Authority specified in block 1, it is essential that the user/installer ensures that his/her Airworthiness Authority accepts items from the Airworthiness Authority specified in block 1.  
 Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

 <p><b>Avia Technique Ltd.</b>  Unit 1,3,4 &amp; 6 Fishponds Estate  Fishponds Road  Wokingham, Berkshire, United Kingdom  RG41 2QJ  Ph: +441189789789, Fax: +441189794511</p>	<p><b>Tear Down/Inspection</b></p> <p>Work Order #: W201908773  Date Printed: 24/05/2019  Page: 1</p>
<p><b>To:</b>  Burwood Aviation Supplies Ltd  8 Bessemer Close  Burwood House  Verwood, Dorset BH31 6AZ  United Kingdom</p>	<p><b>Ship To:</b>  Burwood Aviation Supplies Ltd  8 Bessemer Close  Burwood House  Verwood, Dorset BH31 6AZ  United Kingdom</p>
<p>Reference: 111340  Date Received: 16/05/2019  Part Number: 62293-09  Description: Evacuation Slide  Serial Number: C0303</p>	
<p><b>Customer Remarks:</b>  Overhaul</p> <p><b>Results from inspection:</b>  Unit requires Overhaul  DOM: 12-1998 - Annual Overhaul Required</p> <p><b>Faults</b>  Incorrect glues were found to be used by previous repair station on slide  Maintenance Card is full</p> <p><b>Corrective actions:</b>  Overhaul with reference to the correct CMM Rev  Fit new maintenance card  Test and Certify with reference to the correct issue of the CMM.</p>	
<p>Inspection report generated by: Andrew Prosser</p>	