

1. Approving Competent Authority/Country  
CAA / United Kingdom

2. **AUTHORISED RELEASE CERTIFICATE**  
**EASA FORM 1**

3. Form Tracking Number  
ARCI 1329

4. Organisation Name and Address

**DAKENHURST**  
AIRCRAFT SERVICES LTD  
Oakenhurst Aircraft Services Ltd  
Claydons Lane  
Rayleigh, Essex  
SS6 7UP  
United Kingdom  
Tel: +44 (0)1286741622  
Fax:  
Email: sales@oakenhurst.com  
Web: www.oakenhurst.com

5. Work Order, Order No, Invoice  
10074340 / 111576

6. Item	7. Description	8. Part No.	9. Qty	10. Serial No.	11. Status/Work
1	Lavatory Water Heater	8921082G5	1	SN 08961	Repaired

12. Remarks  
The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work the items are approved for return to service under certificate no. O5KY452Y.  
Work as stated in box 11 has been carried out in accordance with manufacturers manual No. 38-10-01 Revision 4, 15th Jan 1970.

13a. Certifies that the items identified above were manufactured in conformity to:  
 Approved design data and are in condition for safe operation  
 Non-approved design data specified in block 12

14a.  Part 25.A.50 Release to Service  Other regulation specified in block 12  
 Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.

13b. Authorised Signature  
13c. Approval/Authorisation Number  
14b. Authorised Signature  
14c. Certificate/Approval Ref. No.

13d. Name  
14d. Name  
15 Jul 2019

13e. Date (dd mmm yyyy)

14e. Date (dd mmm yyyy)



Oakenhurst Aircraft Services Ltd  
Claydons Lane  
Rayleigh, Essex  
SS6 7UP  
United Kingdom  
Tel: +44 (0)1268741622

EASA Part 145: UK.145.00524

FAR 145: O5KY452Y

### Workshop Report

No: **IR54107**

Issue: **03**

Date: **24-Jun-19**

Burwood Aviation Supplies Limited Burwood House 8 Bessemer Close Verwood Dorset BH31 6AZ United Kingdom			
Attn: - Tel: 0044 (0) 1202 825434 Fax: 0044 (0) 1202 823416 E-Mail: repairs@burwood.aero			
Your Ref: 111576	Our Ref No: WP54340	Test Required: N/A	
Part No: 8921082G5	Description: Lavatory Water Heater	TSN: N/A	CSN: N/A
Serial No: UEW 06961	Workscope:	TSO: N/A	CSO: N/A
DoM:	Overhauled:	Inspected:	
Removed From:	Serial No:	Reg No:	Position:

#### Inspection Findings:

Unit received for repair. On initial inspection the unit is in average condition. On further inspection the protective sleeve around the power cable is worn and requires replacing. During initial testing the pressure relief valve was found to be inop. The unit requires replacement parts with attaching parts, cleaning and final testing I.A.W.

Defective parts replaced. Unit descaled and tested IAW CMM. Unit functions correctly.

Signed: *L. Cronk* Name: **L. CRONK** Date: 15/ JUL /2019  
For and on the behalf of Oakenhurst Aircraft Services Ltd

Registered address:- Claydons Lane, Rayleigh, Essex, SS6 7UP