

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: G176297	
4. Organization Name and Address: Soundair Repair Group, LLC #S2DR551J 1826 BICKFORD AVENUE SNOHOMISH, WA 98290		5. Item: 7. Description: 1 Coffees Maker		8. Part Number: HF-A2000-10	
9. Quantity: 1		10. Serial Number: 0214		11. Status/Work: Repaired	
12. Remarks: The work order listed above describes the actual work performed. Soundair Repair Group, LLC certifies that the work specified in block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work the component is considered ready for release to service under EASA Part-145 approval Number EASA-145-4863 For complete list of replaced parts that identifies OEM/PMA see attached list. All work was performed in accordance with documentation listed below: MANUAL SPECS CMM NO: 25-34-77 Revision Date: 4/19/2016 13a. Certifies the items identified above were manufactured in conformity to: <input type="checkbox"/> Approved design data and are in a condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 12 13b. Authorized Signature: 13c. Approval Authorization No: 13d. Name (Typed or Printed): 13e. Date (dd/mm/yyyy): 14a. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input type="checkbox"/> Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service. 14b. Authorized Signature: 14c. Approval/Certificate No: S2DR551J 14d. Name (Typed or Printed): Duane A. Hutchins 14e. Date (dd/mm/yyyy): 01-Jul-2024					
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where an installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1. It is essential that the user/installer ensures that their airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Blocks 13a to 14e do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations of the country of the user/installer before the aircraft may be flown.					

SOUNDAIR AVIATION SERVICES
 1826 Bickford Ave, Snohomish, WA 98290
 FAA Repair Station #: S2DR551J
 ph: (360) 453-2300 ~ fx: (360) 453-2301

Tear Down/Inspection

Work Order #: G176997

Date Printed: 7/1/2024

Time: 6:08:24 AM

Page: 1

To:
 BURWOOD AVIATION SUPPLIES LTD
 BURWOOD HOUSE
 8 BESSEMER CLOSE
 VERWOOD, DORSET BH316AZ
 UNITED KINGDOM

Ship To:
 Burwood Aviation Supplies Ltd
 Burwood House
 Unit 8 Bessemer Close
 Verwood, Dorset BH31 6AZ
 UNITED KINGDOM

PC: 115631

PN: HFA2000-10

Descr: Coffee Maker

Qty: 1

Dept: coffee

Mfg: Iacobucci

TSN: Unknown

TSO: Unknown

TSR: Unknown

Customer Instructions: Repair/Overhaul per manufacturer's specs. See customer RO for detailed instructions.

Reason for Approval:

None Noted

Findings:

Coffee FAULTS/FINDING/ACTION

RFR FINDINGS: None Noted.

ADDITIONAL FINDINGS: Brew drawer is damaged. Weak brew due to worn brew pumps. Debris clogging heat exchanger. Water plug leaking.

PREVENTATIVE MAINTENANCE: None

CUSTOMER DAMAGE: None

CORRECTIVE ACTION: Unit was inspected and inspected. Defective parts and findings found during inspection were repaired or replaced. Unit was tested per applicable data.

WARRANTY: No

Outgoing Condition:	Repaired		
Mechanic Signature:	<i>Tracy West</i>	Date:	7/1/2024
Inspector Signature:	<i>James A. [Signature]</i>	Date:	7/1/2024
Final Insp:		Unit meets manufacturers specification for return to service. Reviewed and confirmed compliance with applicable AD's.	
Part Number:	HFA2000-10	TSN:	Unknown
Serial Number:	02153	TSR:	0
Manual Specs:	CMM NO: 25-34-77	Rev No:5	Revision Date:4/19/2016

Form #: RG0045

Soundair Repair Group, LLC

COPY

SOUND AIR AVIATION SERVICES
 1826 Bickford Ave, Snohomish, WA 98290
 FAA Repair Station #: S2DR551J
 ph: (360) 453-2300 ~ fx: (360) 453-2301

Replaced Parts Detail

WO#: G176997

Date Printed: 7/1/2024
 Time: 6:08:12 AM
 Page: 1 of 1

PN: HFA2000-10 Description: Coffee Maker Serial Number: 02153
 Customer: BURWOOD AVIATION SUPPLIES LTD Cust Code: BAS4 Department:

Manual(s) Information: **Notes:**
 CMM NO: 25-34-77 Coffee Maker Repair/Overhaul per manufacturer's specs. See customer RO for detailed instructions.

PN	Description	Qty Replaced	Serial No	Part Type
HFA01-1127-02A	RELIEF VALVE	1	NA	OEM PMA
HFA01-2AM	DRAWER ASSEMBLY	1	NA	OEM PMA
HFA07-38	T ADAPTER	2	NA	OEM PMA
HFE07-04	O-RING	6	NA	OEM PMA
HFE07-09	WATER CONNECTOR	1	NA	OEM PMA
HFE07-104	ELBOW ADAPTER	2	NA	OEM PMA
HFE07-112	PUMP	2	NA	OEM PMA
HFE07-233	Pump Support	3	NA	OEM PMA
HFE07-234	Cabinet Pump Support	1	NA	OEM PMA
MB0000220	SEAL	2	NA	OEM PMA
MB0000230	DRAWER SEAL	1	NA	OEM PMA

BURWOOD AVIATION COPY