



***	Security of the security of th	13e. Date (dd/mmm/yyyy): 21 NOV 2016		13d. Same Lyped or Printed): MICHAEL STANLEY	
	Andeld de Albert	13c. Approval/Authorization No.: HMIR-11785	13c	13b. Awhoriz, (Sighan) x	
		ibek 12.	Non-appro ed desig. data specified in Black 12,	Non-appro 2d desig	
		actured conformity to:	above we ma. fac	13a. Certifies the items identified above we ema. XX Approved design data and are race.	
and/or was produced under licensing NM(A321-111).	 This PMA part is not a critical component and/or was produced under licensing agreement from the holder of TC/STC #A28NM(A321-111). 	0)	g I	 Remarks: Airworthiness Approval - Export 	7
NEW	8 (/A	H3207-9	OK LATCH	1 LATCH ASSY-HOOK DOUBLE TOGGLE	·
11. Status/Work:	9. Quantity: 10. °1 Num ser:	8. Part Number:		6. Item: 7. Description:	T_T
Numbe. 92594*000	92870 (PQ1147NM)	ization Name and Address: Hartwell Corporation, 900 S. RICHFIELD ROAD, PLACENTIA, CA 92870 (PQ1147NM)	900 S. RICHFIE	4. Organization Name and Address: Hartwell Corporation, 9	
9?594*0004*1	AUTHORIZED RELEASE CERTIFICATE FAA form 8130-3, AIRWORTHINESS APPROVAL TAG	HORIZED RELEASE CERTIFI FAA form 8130-3, AIRWORTHINESS APPROVAL TAG	AUT	Aviation Authority/Country: FAA/UNITED STATES	
3. Form Tracking Number:			2	Approving Civil	

FAA form 8130-3 (02-14)

specified in Block 1.

(Export)

Statements in Block 13a and 14a do not constitute installation certification. In all cases aircrast maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircrast may be flown.

Where the user/installer work in accordance with the national regulations of an Airworthiness Authority different than the Airworthiness Authority of the country specified in Blocl 1, it is essential that the user/installer ensures that his/her Airworthiness Authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

User/Installer Responsibilities

21 NOV 2016

NSN:0052-00-012-9005