

AUTHORISED RELEASE CERTIFICATE

EASA FORM 1

1. Approving Competent Authority/Country
CAA / United Kingdom

4. Organisation Name and Address
DAKENHURST
AIRCRAFT SERVICES LTD

Oakenhurst Aircraft Services Ltd
Claydons Lane
Rayleigh, Essex
SS6 7UP
United Kingdom

5. Version Order Contract/Invoice
wP50248 / 111023

3. Form Tracking Number
AR 49880

6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No.	11. Status/Work
1	Aircraft Position Light	31-9289-1	1	4172	Overhauled

12. Remarks
The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work the item are approved for return to service under certificate no. OSK7452Y.
Work as stated in box 11 has been carried out in accordance with manufacturers manual No. 33-43-21, Rev 9, 12/12/14.

13a. Certifies that the items identified above were manufactured in conformity to:

Approved design data and are in condition for safe operation

Non-approved design data specified in block 1

13b. Authorised Signature _____ 13c. Approval/Authorisation Number _____

13d. Name _____ 13e. Date (dd mmm yyyy) _____


14a. Part-145, A.50 Release to Service Other regulation specified in block 12

Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.

14b. Authorised Signature _____ 14c. Certificate/Approval Ref. No. _____

14d. Name Mr Billy Lander 14e. Date (dd mmm yyyy) 01 Mar 2019

USER/INSTALLER RESPONSIBILITIES
This certificate does not automatically constitute authority to install the item(s).
When the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items of work which are not authorised by the authority specified in block 1.
Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



Oakenhurst Aircraft Services Ltd
Claydons Lane
Rayleigh, Essex
SS6 7UP
United Kingdom
Tel: +44 (0)1268741622

EASA Part 145: UK 145.00724

FAR 145: 05KY452Y

Workshop Report

No: **IR50038**

Issue: **01**


Date: **22-Feb-19**

Burwood Aircraft Supplies Limited Burwood House 8 Bessemer Close Verwood Dorset BH31 6AZ United Kingdom			
Attn: - Tel: 0044 (0) 1202 825434 Fax: 004 (0) 120 825416 E-Mail: repairs@burwood.aero			
Your Ref: 111023	Our Ref No: WP50248	Test Required: N/A	
Part No: 31-9289-1	Description: Aircraft Position Light	TSN: N/A	CSN: N/A
Serial No: 4172	Workscope: .	TSO: N/A	CSO: N/A
DoM:	Overhauled:	Inspected:	
Removed From:	Serial No:	Reg No:	Position:

Inspection Findings:

Aircraft Position Light received for overhaul. Not defects found during inspection and test. Unit requires overhaul components and functional tests iaw CMM.

Overhauled and tested IAW CMM.

Signed:  Name: **B.LANDER** Date: **04 MAR 2019**
For and on the behalf of Oakenhurst Aircraft Services Ltd

Registered address:- Claydons Lane, Rayleigh, Essex, SS6 7UP

COPY