

1. Approving Competent Authority / Country

2.

LBA / Germany

**AUTHORISED RELEASE CERTIFICATE
EASA FORM 1**

61606590

3. Form Tracking Number

20379975 00000001

4. Organisation Name and Address:



Lufthansa Technik

Lufthansa Technik AG
Weg beim Jäger 193
22335 Hamburg
Germany

5. Work Order/Contract/Invoice

61606590

6. Item

8. Part No.

9. Qty.

10. Serial No.

11. Status / Work

01 MODULE AV-IND LT DIMMING M469

69-55179-63

1

D01248

INSPECTED / TESTED

12. Remarks

Burwood Aviation Supplies Ltd. 111322

ATA 3316

TP F

MK-No. 10

Part Code 00

Resp. Workshop 33423023

Workshop Station HAM305

Opr. Hours Cycle Opr. Day
TT UNKNOWN UNKNOWN
TSO UNKNOWN UNKNOWN
TSC UNKNOWN UNKNOWN
TSF 0 0
TASK PERFORMED IN ACCORDANCE WITH CMM 33-1-1-32
REV. 25 / CMLS 33-1-1-32 ISSUE 013

FAA Certificate No. DLAY225D

13a. Certifies that the Items identified above were manufactured in conformity to:

approved design data and are in a condition for safe operation

non-approved design data specified in block 12

Further details of work performed are attached either in a Workshop Report (reference numbers: see blocks 3 and 5) or in other applicable documents.
 Part-145 A.50 Release to Service
 Other Regulation specified in block 12
Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part- 145 and in respect to that work the Items are considered ready for release to service.

13b. Authorised Signature

13c. Approval / Authorisation Number

14b. Authorised Signature

442715

M. Radloff

14c. Certificate / Approval Ref. Number

DE.145.0001

13d. Name

13e. Date (dd mm yyyy)

14d. Name

Matthias Radloff

14e. Date (dd mm yyyy)

17 May 2019

FOR THE USER / INSTALLER RESPONSIBILITIES

The certificate does not automatically constitute authority to install the Item(s).

The user/installer performs work in accordance with regulations of an airworthiness authority different from the airworthiness authority specified in block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

Workshop Report

61606590



Certificate Ref. No.

20379075 00000001



Lufthansa Technik

Lufthansa Technik AG
Weg beim Jäger 193
22335 Hamburg
Germany

Work Order/Contract Invoice

61606590

Description

MODULE AY-IND LT DIMMING M469

Serial No. as received

D01248

Part No. as received

69-55179-63

Serial No. as dispatched

D01248

Part No. as dispatched

69-55179-63

Responsible Workshop

33423023

Reason for removal

Repair Purchase Order 111322.
Test and recertify.

Modification Status according to Mod-Label

Findings

No findings during testing.
Relatively to the age, unit has normal wear and tear.
form, fit or function are not affected.
No abnormal wear and tear detected.

See Unit Mod-Label if equipped

Action

Incoming test performed.
Unit opened and visually inspected,
printed circuits boards and internal wire connections checked.
Unit cleaned.
Acceptance test passed.

Name

442715, Mattias Radloff

Date (dd mmn yyyy)

17 May 2019

The work specified above has been performed subject to Lufthansa Technik's Standard conditions for Technical Services which, if not superseded by an other agreement, are acknowledged by the customer with acceptance of the part(s) hereunder.

LH Form 10992 G-15 (HAM WG/Q)