

1. Approving Competent Authority/Country

2.

CAAIK

### AUTHORISED RELEASE CERTIFICATE EASA FORM 1

3. Form Tracking Number

RC49 194

4. Organisation Name and Address



WAS (COMPONENTS) LTD  
North Hangar  
Aviation Way  
Southend-on-Sea  
Essex  
SS2 8UN  
United Kingdom

Tel: +44(0)1702 348801  
Fax: +44(0)1702 541534  
Email:  
Web:

5. UK OR OR/Con. Ref/Invoice

111189


6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No.	11. Status/Work
1	OVER PRESS PROTECTOR	L95F100-803	1	14448	REPAIRED

12. Remarks

- WP66291 -  
REPAIRED & TESTED IAW INTERTECHNIQUES MAN. REF. 28-12-45, REV. 4 DATED FEB 2011  
- TCQA No. : 816-46 -

Return to Service in accordance with FAR 43.9. Certificate No: EGNW725K

Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Title 14, Code of Federal Aviation Regulations, part 43 and in respect to that work, the items are approved for return to service. Pertinent details of the repair are on file at this repair station under order.

No: 111189  
Sign:  Date: MAY 02 2019

13a. Certifies that the items identified above were manufactured in conformity with:

- Approved design data and are in condition for safe operation
- Non-approved design data specified in block 12

14a.  Part-145, A.50 Release to Service

Other regulation specified in block 12

13b. Authorised Signature

14b. Authorised Signature

WAS 42

14c. Certificate/Approval Ref. No.

UK.145.00579

13d. Name

14d. Name

S. Finch

14e. Date (dd mmm yyyy)

02 May 2019

#### USER/INSTALLER RESPONSIBILITIES

This certificate does not constitute authority to install the item(s).  
The user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1. It is essential that the user/installer ensures that his/her airworthiness authority accepts items in the work. The user/installer must ensure that the work is performed in accordance with the national regulations by the user/installer before the aircraft is returned to service.  
Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft is returned to service.



Inflite MRO Services Ltd  
 North Hangar  
 Aviation Way  
 Southend-on-Sea  
 Essex  
 SS2 6UN  
 United Kingdom  
 Tel: +44(0)1702 348601

WAS (COMPONENTS) LTD: EASA Part 145: UK.145.00579:

WAS (COMPONENTS) LTD: FAA Repair Station: EGWY725K:

**Workshop Report**

No: **IR66900**

Issue: **01**

Date: **05-Apr-19**

Burwood Aviation Supplies Limited Burwood House 8 Lessemer Close Ebblake In Estate VERWOOD Dorset BH31 6AZ United Kingdom  Attn: Daron Golding Tel: 08444 151707 Fax: 08444 150717 E-Mail: daron.golding@burwoodaviation.co.uk			
Your Ref: 111189	Our Ref No: WP66291	Test Required: N/A	
Part No: L95F100-603	Description: OVEP PRESSURE PROTECTOR		
Serial No: A74448	Workscope: Repair		
Dept: Power Plant Worksho Release Type: Dual			
Removed From:	Serial No:	Reg No:	Position:

**Workscope Overview:**

UNIT SUPPLIED FOR TEST

**Inspection Findings:**

Unit supplied for inspect and test.

Unit found to have a leaking seal, cracked burst disc which burst below test pressure.  
 Unit to be stripped, cleaned and inspected.  
 Rebuild unit replacing seal, and burst disc, carry out testing.

Unit to be released: (subject final test).

Repair/ test IAW Intertechniques 28-12-45.  
 Rev #4 Dated Feb 2011.

Dual release.....

Signed:

Name: S. Finch



Date: 02/MAY/2019

For and on the behalf of Inflite MRO Services Ltd

Registered address:- Inflite House, Stansted Airport, Stansted, Essex, CM24 1RY