ccordance with the	Statements in Block 13a and 14a do not constitute installation certification, in all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installar before the aircraft may be flown.	mainlenance records mu	tute installation certification, in all cases,aircraft e the aircraft may be flown.	Statements in Block 13a and 14a do not constitute installation certification national regulations by the user/installer before the aircraft may be flown.	Stater
specified in of the country	It is important to une viste the stence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installe, verforr is work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential than the viser/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s)/from the airworthiness authority of the country specified in Block 1.	constitute authority to ins rthiness authority differe is aircraft engine(s)/prope	It is important to une viste the stence of this document alone does not automatically constitute authority to install the aircraft where the user/installe, verforr is work in accordance with the national regulations of an airworthiness authority different than the airwish block 1, it is essential than the viser/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) specified in Block 1.	It is important to untarties the stence where the user/installer verforr s work in acc Block 1, it is essential that 's user/installer er specified in Block 1.	Where Black specie
		User/Installer Responsibilities	User/Instal		
14. Date (dd/mmm/yyyy) 14/Nov/2018	n "Gus" Garcia	Agustin			
68IR700B		14d Name (Typhology Prince)	136 - Date (1994) manufactural	13d. Name (Types or Printed).	ाउव.
ork identified in Block 11 with Title 14, Code of items are approved for	Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service. Authorized Signabre:	146.	ed in Block 12. A36, Ypr. Tr Affordsallon Nove	Approved design data and are in a condition for safe operation Non-approved design data specified in Block 12. 13b. Authorized Signature: 13b. Authorized Signature:	495-
Other regulation specified in Block 12.	X 14 CFR 43.9 Return to Service X Other regul	14a. X 14 CF	III AIN THE THE TOTAL STATE OF THE OF	O. Allundulog ui bsiniosiminiii sism sykrab reminiam kiirin kii	
	ASA . 145 Ap., oval Number EASA, 145,6295		Certifies that the work specified in blocks 11/12 was carried out in accordance. The EASA to the component is considered ready for release to service under ASA. The 145 Approval Number EAS	Certifies that the co	
OVERLOADED PPTC	RANTY ACT BEING GRANTED DUE TO OVERLOADED PPTC	RMKS: WAPRANTY AC			
÷	COMPLIANCE WITH S'_, VICE L'ULLETINS (SBs/EOs): N/A	COMPLIANC N/A			
DIRECTIVES (ADS):	COMPLIANCE WITH MANL ATOF / AIRV OR VINESS DIRECTIVES (ADS):	COMPLIANC N/A	ARRIED OUT PER 99194	FULL DETAILS OF WORK CARRIED OUT PER WORK ORDER NUMBER: W99194	
	5	Date: JUN/22/2015	CMM 25-20-35 Rev.: 11 ufactured by: ADAMS FITE	Remar	12.
			AR4714-11	1 STRIKE, ELECTRICALLY OPERATED	
Status/W. vk:	10. Serial Number:	9. Quantity:	8. Part Number:	Item 7. Description:	
5. Work Order/Contract/In Joice 'umbe. W9915.	: 68IR700B : EASA.145.6295 Fax: 704-821-4286	FAA Repair Station EASA Reference Ph: 704-821-4266	ICON AEROSPACE, LLC. 2617 EXECUTIVE POINT DR. MONROE, NC 28110	Organization Name and Address:	4.
201622	APPROVAL TAG	FAA Form 8130-3, AIRWORTHINESS APPROVAL	FAA Form 8130-3,	FAA/United States	Ī
3. Form Tracking Number:	CERTIFICATE 3.1		AUTHORIZED RELEASE	Authority/Country	;



FAA REPAIR STATION 68IR700B EASA REFERENCE EASA.145.6295 2617 EXECUTIVE POINT DR.

MONROE, NC 28110

Ph: 704-821-4266 Fax: 704-821-4286

EMail: sam@iconaerospace.com

Page 1 **WORK ORDER**

W99194

Rev Date: 22/Jun/2015

Date Rcvd: 24/Sep/2018

TEARDOWN REPORT

AERO-ZONE DIS 'RIBU" UN EUROPE

9, Earhart Avenue Shannon Free Zone County Clare, Ireland

V14 P638

Contact: JEFF DODGE Contact Ph: 353 61 704800

Contact Fax: 353 61 704808

Reason Removed: UNIT RECEIVED FOR OV FRHAUL AS PER O.E.M SPEC'S

Cust RO#: 201622 Manual Loc: AR-004

P/N: AR4714-11 ATA: 25-20-35 S/N: 1050098

Rev: 11 Desc: STRIKE, ELECTRICALLY OPERATED

Mfgr: ADAMS RITE Tag Date: 14/Nov/2018

FINDINGS

RECEIVING INSPECTION:

VERIFIED UNIT DATA PLATE, NO DISCREPANCIES FOUND.

PRELIMINARY INSPECTIONS:

TESTED UNIT. FAILED FUNCTIONAL TEST.

HIDDEN DAMAGE:

NONE

CONTINUED INSPECTION:

TESTED, UNIT IS INOP, FOUND BAD PPTC ASSY. THIS IS A PROTECTOR FOR L EVA ED TEMPERATURE CAUSED BY HI CURRENT.

CORRECTIVE ACTION: UNIT CONDITION REPAIRED

REPLACED PPTC ASSY AND TESTED UNIT. TESTED AS PER O.E.M SPEC'S

SB's, AD's, EO's and RMK's:

WARRANTY NOT BEING GRANTED DUE TO OVERLOADED PPTC

CERTIFICATION

Service Performed:

X REPAIRED

MODIFIED TO:

PARTS AND MATERIAL

QTY

PART NUMBER

73584-1

DESCRIPTION

PPTC ASSY

COND

NE

MAINTENANCE RELEASE

The component identified above was serviced as spedified above in accordance with the current regulations of the Fer eral Aviation Administration and is approved for return to service. Other pertinent details of the repair are on file at this repair station.

APPROVED FOR RETURN TO SERVICE BY:

Agustin "Gus" Garcia

DATE:

14/Nov/20

FORM IAF-3116 (TDR) REV 01/10

www.lLSmart.com/Optimizer © ILS eBusiness Services, Inc.

Printed by ILS Optimizer