Country	AUTHORISED RELEASE CERTIFICATE	3. Form Tracking Number:
CAA.UK	EASA FORM 1	4001211C10A
4. Organization Name and Address:	Avia Technique Ltd.	E Wash Order / Contract /
Avia Technicula	Unit 1,3,4 & 6 Fishponds Estate	Invoice Number:
SK Assosafety Group	Wokingham, Berkshire, United Kingdom RG41 2QJ	W201917864
		112027
6. Item: 7. Description:	8. Part Number: 9. Quantity: 10. Serial Number:	11 Status /V
1 Oxygen Cylinder Assembly	1 00	i i Gaids / Jih,
12. Remarks:		vernaule
CMM: 35-23-07 Revision: 1		ntified in Blo < 11 and descrit. Arein has been in accordant with 14 CFC Part 43 and in respect he items are at, "oved for elurn to service under
Next Overhaul / Hydrostatic Test Due; 10/2022 Cylinder Life Expiry Data: 02/2037	CEMITICATE NO.	
Avia Technique Ltd have checked and verifie	Avia Technique Ltd have checked and verified that there are no pertinent AD's or SB's relevant.	
Approved design data and are in a condition for safe operation.	4a. 7 P. t-14F A.50 Release to Service X	Other regulation specified in Block 12
n data specified in		vilh Part-145, and in respect to that 18.
13d Name	leate Appr ATRs. Vo.: 14b Authorised Signature: AVIA 43	14c. Certificate /Approval Ref No.: UK.145.00846
• 1	Non-Date do/mmm, yyy). 14d. Name	14e. Date (dd/mmm/yyyy):
		18/Oct/2019
	USER / INSTALLER RESPONSIBILITIES	
This certificate does not automatic 'v con litute.	and to install the item(s).	
where the user/installer الله من الله الله الله الله الله الله الله الل	where the user/installer party as wirk in the ordance with regulations of an Airworthiness Authority different than the Airworthiness Authority specified in block 1, it is essential that the user/installer ensures that his/he. Air orthiness Authority accepts items from the Airworthiness Authority specified in block 1.	(1, it is essential that the
Statements in blo. 's 13t, and 14a do not constitut national reculations by the ser/installer before the	Statements in blo. 's 13 and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national reculations. Ye the 'ser/installer before the aircraft may be flown.	ssued in accordance with the



Avia Technique Ltd.

Unit 1,3,4 & 6 Fishponds Estate

Fishponds Road

Wokingham, Berkshire, United Kingdom

RG41 2QJ

Ph: +441189789789, Fax: +441189794511

Tear Down/Inspection

Work Order #: W201917864

Date Printed: 11/10/2019

Page:

burwood \(\) viation Supplies Ltd

8 Besser er Close

Burwe A To se

Verwood, Forset BH31 6AZ

United K

Ship To:

Burwood Aviation Supplies Ltd

8 Bessemer Close **Burwood House**

Verwood, Dorset BH31 6AZ

United Kingdom

Reference:

1202

Date Received: 10/10/27

Part Number: Description:

80130 -06 Oxygen Ovic er Assembly

Serial Number: C13050687

Customer Remarks:

Overhaul

Results from inspection:

Unit requires Overhaul

Regulator received with missing Serial Number.

Corrective actions:

Overhaul with ref to the correct CMM

New Serial Number to be given.

Refill with Aviation/Breathing Oxygen compliant with MIL-PRF-272.0 Spr

Inspection report generated by: William Cornwell

Reference: SK-GF-005

Issue: Initial