

Global Air Services LLC 14075 SW 143 CT

Unit#4 MIAMI, FL 33186

Ph: 786-539-1538, Fax: 786-362-7177

info@globalairserv.com

Tear Down/Inspection

Work Order #: 19593

Date Printed: 8/5/2019

Time: 3:21:49 PM

Page: 1

To: ATTN:

ALARIS AEROSPACY, SYSTEMS LLC 1721 Blount Road, S

POMPANO BEACH, FL ,3060

Ship To:

ALARIS AEROSPACE SYSTEMS LLC

1721 Blount Road, Suite 1 POMPANO BEACH, FL 33069

USA

Ref #: RC4055

Phr .a #: 954-596-8736

Fax #: 954-596-8737

Email: jeremie@alarisaero.com

Code: ALARIS

F.e:

PN: VFT300B00

Descr: SKIN AIR VALVE

Qty: 1

Sta ion:

Make:

Model:

Mfg: SAFRAN

TSN: 0

TSO: 0

₹: 0

CSN: 0

CSO: 0

CSR: 0

Cond: OVERHAULED

Mechanic: J PA SCUAL

Inspector: R FUENTES

Engine Number:

Manual: 21-26-62

Rev: 7

Rev Date: 11/30/2018

Tail Number:

Serial Numbers: 2141

Symptoms:

RELIABILTY

REASON FOR REMOVAL: OVERHAUL

REMOVAL DATE: UNK

CUSTOMER RO DATE: 11JUL2019

A/C REG: UNK POS: UNK TIME: UNK CYCLE: UNK

PRIMARY FAILURE: UNIT PRETESTED IAW CMM 21-26-62 RL J/30/2018. UNIT PASSED PRETEST. CUSOTMER REQUIRES OVERHAUL

REASON FOR REMOVAL CONFIRMED: YES, UNIT FOR OVERHAU.
PART NUMBER ON DATAPLATE MATCHES CUSTOMER RO: YES
SERIAL NUMBER ON DATAPLATE MATCHES CUSTOMER RO: YES

IDENTIFICATION

AS PER OEM CMM UNIT IS IDENTIFIED CORRECTLY

AD'S FOUND

NO FAA OR EASA AIRWORTHINESS DIRECTIVES FOUND ON 05AUG2019. REPLACEMENT PARTS

UNIT IS QUOTED FOR: OVERHAUL

REPLACEMENT PARTS REQUIRED:

1 VFT300-GASKIT 100% EXPENDABLES KIT (MANDATORY)

Corrective Actions:

RECEIVING INSPECTION

UNIT PN AND SN VERIFIED WITH CUSTOMER RO AND UNIT ID PLATE. NO PHYSICAL DAMAGE IN SHIT YING NO TED TO UNIT ON ARRIVAL

RECV: M SOLARES INSP: R FUENTES DATE: 07/18/2019

PRELIMINARY INSPECTION

RODOLFO FUENTES

Form created with Quantum Control(tm) technology. Product Licensed to: Global Air Services LLC



Global Air Services LLC 14075 SW 143 CT

Unit#4 MIAMI, FL 33186

Ph: 786-539-1538, Fax: 786-362-7177

info@globalairserv.com

Tear Down/Inspection

Work Order #: 19593

Date Printed: 8/5/2019

Time: 3:21:50 PM

Page: 2

UNIT PN AND SN VERIFIED WITH CUSTOMER RO AND UNIT ID PLATE. UNIT PN VERIFIED WITH OEM CMM 21-26-62 1. CH: J PASCUAL INSP: R FUENTES DATE: 07/25/2019

FUNCT, NAL T ST

IT PRETESTED IAW CMM 21-26-62 REV 7 DATED 10/30/2018. UNIT PASSED PRETEST. CUSOTMER REQUIRES **OVERHAUL**

TF A: J PASCUAL INSP: R FUENTES DATE: 07/23/2019

DISASSEM"_ED

UNIT "SASSEMBLED, CLEANED AND INSPECTED IAW CMM 21-26-62 REV 7 DATED 10/30/2018. FOUND GASKET SEAL DENE" AND VARIOUS HARDWARE ITEMS CORRODED. NO ADDITIONAL MAJOR ABNORMALITIES NOTED TO UNIT. 1 SQUIRES LISTED ITEMS AND 100% EXPENDABLES KIT FOR OVERHAUL TEC". J PASCI'AL INSP: R FUENTES DATE: 07/25/2019

ASSEMBLY

UNIT ASSF /BI F AND PAINTED IAW CMM 21-26-62 REV 7 DATED 10/30/2018. REPLACED 100% EXPENDABLES KIT AND ALL AUT ED SPARES FOR OVERHAUL. TECH: J PASC AL INCO: R FUENTES DATE: 08/02/2019

TEST

UNIT TESTED IAW (MM 2) 26-62 REV 7 DATED 10/30/2018 PASSING TEST WITH SATISFACTORY RESULTS. UNIT TO OVERHAULED CO (DITION, SAFETY WIRED AND READY TO RETURN TO SERVICE. TECH: J PASCUAL (NSP: F FUENTES DATE: 08/02/2019

RODOLFO FUENT .S