

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES

2. **AUTHORIZED RELEASE CERTIFICATE**  
FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number: 17169

4. Organization Name and Address: **1ST CHOICE AEROSPACE**  
3361 Enterprise Way, Miramar, FL 33025, Fax: 954/430-6601, 954/430-6600

Repair Station# 90AR940B

5. Work Order/Contract/Invoice Number: 17169 / 110010

6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
001	HOT AIR TRIM VALVE	600700-00-501	1	146	OVERHAULED

12. Remarks: This item was Overhauled I/A/W Manual # CMM 21-43-02, Revision # 10 Revision Date 16/Jan/2017  
NO APPLICABLE AD'S AND NO SB'S INSTALLED.

Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the product/article is considered ready for release to service under EASA Part 145 Approval No. EASA.145.6610


13a. Certifies the items identified above were manufactured in conformity with:  
 Approved design data and are in condition for safe operation.  
 Non-approved design data specified in Block 12.

13b. Authorized Signature:

13c. Approval/Authorization No.:

13d. Name (Typed or Printed):

13e. Date (dd/mm/yyyy):

14a. Authorized Signature: 

14b. Name: (Typed or Printed) RAUL A DALEY

14c. Approval/Certificate No.: 90AR940B

14d. Date (dd/mm/yyyy): 15/Aug/2018

**User/Installer Responsibilities**

It is reported to the user/installer that the existence of this Document alone does not automatically constitute authority to install the aircraft/engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an Airworthiness Authority different than the Airworthiness Authority of the country specified in block 1, it is essential that the user/installer ensures that his/her Airworthiness Authority accepts aircraft engine(s)/propeller(s)/article(s) from the Airworthiness Authority of the country specified in block 1. Statements of block 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with national regulations by the user/installer before the aircraft may be flown.

# WORK ORDER FORM 100

Page No. 1

## 1ST CHOICE AEROSPACE

3361 Waterpocket Way  
Miramar, FL 33025  
Fax: 954/430-6600  
954/430-6600



FAA CRS No: 9QAR940B  
WORK ORDER: 17169-18

Customer: BURWOOD AVIATION SUPPLIES

Dept#:PNE

Location:FNL

Cust RO#: 110010

Step:CLOSED

Warranty Code: 00 / 0

Mfg: NORD NORD-MICR

\*\*\* NO PMA PARTS \*\*\*

Goodthru AD#:

Outgoing 600700-00-501 HOT AIR TRIM

S/N: 146

Incoming P/N: 600700-00-501	Incoming S/N: 146	Incoming Work Req.: R	Outgoing Work Req: OH
Manual#: 0337	RevDate: 16/Jan/2017	Rev#: 10	ATA: 21-43-02
Tools: A0600, A0712, A0717, A0856, A0867, A0924, A0923, A0047, A0002, A0033, A1560, A1574, A4193			
Reason/Rm: REPAIR QUOTE REQUIRED			
Date Recvd: 05/Jul/2018	Date Recrd: 29/Jul/2018	Date Estmtd:	
PRELIMINARY INSPECTION: DATE: 07/Jul/2018 INSPECTOR: PJG UNIT'S P/N AND S/N VERIFIED PER R/O AND I.D. PLATE.			
PRE TEST (Yes/No): Y DATE: 13/Jul/2018 INSPECTOR: PJG UNIT FAILS PRE TEST. (DAMAGE SWITCHES)			
HIDDEN DAMAGE: NONE NOTED			
TEARDOWN FINDINGS: UNIT DISASSEMBLED, CLEANED AND INSPECTED. UNIT HAS WORN O-RING, DEFECTIVE MICROSWITCHES, CORRODED BEARINGS. DUE TO THE EXTENT OF REPAIR, AN OVERHAUL IS REQUIRED.  OVERHAUL QUOTE			
TECHNICIAN:FLE DATE: 16/Jul/2018 INSPECTOR: PJG			
FINAL INSPECTION BEFORE ASSEMBLY: DATE: 13/Aug/2018 INSPECTOR: PJG			
CORRECTIVE ACTION: THIS UNIT WAS DISASSEMBLED, CLEANED, INSPECTED, REPAIRED AS NECESSARY, REASSEMBLED, FUNCTIONALLY TESTED, AND OVERHAULED IN ACCORDANCE WITH MANUFACTURER'S SPECIFICATIONS.			
TECHNICIAN:JRF DATE: 15/Aug/2018 INSPECTOR: RAD			
MODIFICATION/SERVICE BULLETINS: *NO APPLICABLE AD'S AND NO SB'S INSTALLED.			



# WORK ORDER FORM 100

## 1ST CHOICE AEROSPACE

3361 Enterprise Way  
Miramar, FL 33023  
Fax: 954/430-6601  
954/430-6600



FAA CRS No: 9QAR940B  
WORK ORDER: 17169-18

Customer: BUR001 / BURWOOD AVIATION SUPPLIES

Dept#:PNE

Location:FNL

Cust RO#: 110010

Step:CLOSED

Warranty Code: 00 / 0

Mfg: NORD NORD-MICK

\*\*\* NO PMA PARTS \*\*\*

Goodthru AD#:

Outgoing 600700-00-501 / HO AIR TRIM

S/N: 146

Test Data Used: ATA:21-43-0 REV#10 16JAN2017	
Test Technician: JRF	DATE: 15/Aug/2018
Final Inspection:RAD	DATE: 15/Aug/2018

ADDITIONAL COMMENTS:  
N/A

### MAINTENANCE RELEASE RECORD

THE COMPONENT IDENTIFIED ABOVE WAS OVERHAULED IN ACCORDANCE WITH THE CURRENT REGULATIONS OF THE FEDERAL AVIATION ADMINISTRATION, AND IS APPROVED FOR RETURN TO SERVICE. OTHER PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION.

Approved For Return to Service by RAUL A DALEY

*[Signature]*  
Date: 15/Aug/2018

