

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES

2. AUTHORIZED RELEASE CERTIFICATE

FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number: 16431

4. Organization Name and Address:

IST CHOICE AEROSPACE
3361 Enterprise Way, Miramar, FL, 33025, Fax: 954/430-6601, 954/430-6600

Repair Station# 9QAR940B

5. Work Order/Contract/Invoice Number:

16431/1118


| 6. Item: | 7. Description: | 8. Part Number: | 9. Quantity: | 10. Serial Number: | 11. Status/Work: |
|----------|------------------|-----------------|--------------|--------------------|------------------|
| 001 | REAR POS WING LT | 72303219-2 | 1 | 2907 | REPAIRED |

12. Remarks: This item was Repaired I/A/W Manual # CMM D201209000008 ATA 33-43-85, Revision # 4 Release Date 14/Feb/2018
NO APPLICABLE ADS AND NO SB'S INSTALLED.

Certifies that the work specified in block 11/12 was carried out in accordance with the EASA Part 145 and in respect to that work the product/article is considered ready for release to service under EASA Part 145 Approval no. EASA.145.6610

13a. Certifies the items identified above were manufactured in conformity to:
 Approved design data and are in condition for safe operation.
 Non-approved design data specified in Block 12.

14. 14 CFR 43.9 Return to Service Other regulation specified in Block 12
Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

| | | | |
|-------------------------------|----------------------------------|---|--|
| 13b. Authorized Signature: | 13c. Approval Authorization No.: | 14b. Authorized Signature: | 14c. Approval/Certificate No.: |
| | |  | 9QAR940B |
| 13d. Name (Typed or Printed): | 13e. Title (dd/mm/yyyy): | 14d. Name: (Typed or Printed): RAULA DALEY | 14e. Date (dd/mm/yyyy): 24/Jul/2018 |

User/Installer Responsibilities

It is important to note, and that the existence of this Document alone does not automatically constitute authority to install the aircraft/engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an Airworthiness Authority different than the Airworthiness Authority of the country specified in block 1, it is essential that the user/installer ensures that his/her Airworthiness Authority accepts aircraft engine(s)/propeller(s)/article(s) from the Airworthiness Authority of the country specified in block 1. The items in block 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with applicable regulations by the user/installer before the aircraft may be flown.

WORK ORDER FORM 100

1ST CHOICE AEROSPACE

3361 Enterprise Way
Miramar, FL 33025
Fax: 954-30-6601
954-30-6601



FAA CRS No: 9QAK940B
WORK ORDER: 16431-18

Customer: BUR001 / BURWOOD AVIATION SUPPLIES

Dept#: ACC Location: FNL
Warranty Code: 01 / 0
Goodthru AD#:

Customer CO#: 101180

Step: CLOSED

Mfg: HONEY HONEYWELL

*** NO PMA PARTS ***

Outgoing: 72303219-2 / REAR POS WIN

S/N: 2907

| | |
|--|------------------------------|
| Incoming P/N: 72303219-2 | Outgoing Work Req: RE |
| Incoming S/N: 2907 | |
| Incoming Work P/N: BC | |
| Manual#: 0989 | RevDate: 14/Feb/2018 Rev#: 4 |
| | ATA: 33-43-85 |
| Tools: A0449, A0057, A2467, A0092, A0200, A2687, A1173, A0112, A3807 | |
| Reason/Rm: UNIT FAILED IN SERVICE BEING RD FOR WARRANTY EVALUATOR | |
| Date Recvd: 06/Jun/2018 | Date Reqr'd: 23/Jun/2018 |
| Date Estmtd: | |
| PRELIMINARY INSPECTION: DATE: 19/Jun/2018 | INSPECTOR: RBO |
| VERIFIED P/N AND S/N WITH P.O. | |
| UNIT RECEIVED IN POOR CONDITION. UNIT CAME IN FOR WARRANTY CONSIDERATION. | |
| PRE TEST (Yes/No): Y | DATE: 19/Jun/2018 |
| INSPECTOR: RBO | |
| UNIT FAILED FUNCTIONAL TEST. | |
| HIDDEN DAMAGE: NONE NOTED | |
| TEARDOWN FINDINGS: UNIT WAS INSPECTED. FOUND LOOSE AND SCREW AND REQUIRES REWORK. DURING TROUBLE SHOOTING. FOUND BURNED POWER SUPPLY ASSY 72325217-3 AND REQUIRES REPLACEMENT. PART WAS NOT REPLACED LAST VISIT. WARRANTY WILL BE DENIED. UNIT REQUIRES CLEANING, INSPECTION, REPAIR AND TESTING. | |
| REPAIR QUOTE | |
| TECHNICIAN: ESC | DATE: 19/Jun/2018 |
| INSPECTOR: RBO | |
| FINAL INSPECTION BEFORE ASSEMBLY: | DATE: 24/Jul/2018 |
| INSPECTOR: R D | |
| CORRECTIVE ACTION: THIS UNIT WAS DISASSEMBLED, CLEANED, INSPECTED, REPAIRED AS NECESSARY, REASSEMBLED, AND FUNCTIONALLY TESTED IN ACCORDANCE WITH MANUFACTURER'S SPECIFICATIONS. | |
| TECHNICIAN: ESC | DATE: 24/Jul/2018 |
| INSPECTOR: RAL | |
| MODIFICATION/SERVICE BULLETINS: *NO APPLICABLE AD'S AND NO SB'S INSTALLED. | |



WORK ORDER FORM 100

1ST CHOICE AEROSPACE

3361 Enterprise Way
Miramar, FL 33025
Fax: 954/430-6601
954/430-6601



FAA CRS No: 9QAR940B
WORK ORDER: 16431-18

Customer: BU 2001 / BURWOOD AVIATION SUPPLIES

Dept#:ACC

Location:FNL

Cust PO#: 01180

Step:CLOSED

Warranty Code: 01 / 0

Mfg: HONEY HONEYWELL

*** NO PMA PARTS ***

Goodthru AD#:

Outgoing 7230219-2 / REAR POS WIN

S/N: 2907

| | | | |
|-------------------|--------------|-------|-------------|
| Test Date Used | ATA:33-43-85 | REV#4 | 14FEB2018 |
| Test Technician: | FSC | DATE: | 24/Jul/2018 |
| Final Inspection: | RAD | DATE: | 24/Jul/2018 |

ADDITIONAL COMMENTS:
N/A

MAINTENANCE RELEASE RECORD

THE COMPONENT IDENTIFIED ABOVE WAS REPAIRED IN ACCORDANCE WITH THE CURRENT REGULATIONS OF THE FEDERAL AVIATION ADMINISTRATION, AND IS APPROVED FOR RETURN TO SERVICE. OTHER PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION.

Approved For Return to Service by RAUL A DALEY

Raul A Daley
16
Date 24 Jul 2018

