

1. Approving Competent Authority / Country: **CAA, UK**

2. **AUTHORISED RELEASE CERTIFICATE**  
EASA FORM 1

3. Form Tracking Number: **W201811000**

4. Organization Name and Address: **Avia Technique Ltd.**  
Unit 1,3,4 & 6 Fishponds Estate  
Fishponds Road  
Wokingham, Berkshire, United Kingdom RG41 2DJ  
Ph: +441189760780, Fax: +441189794511

5. Work Order / Contract / Invoice Number: **W201811000**  
**110026**

6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Qty. Issued / V. No. Overhauled
1	Escape Slide	82265-107	1.00	C1925	

12. Remarks:  
 CANM: 25-06-11 Revision: 13  
 P: P-12303 Revision: G  
 Escape Slide: DOM 02-2013, Last Maintenance 08-2018, Next Maintenance 08-2021.  
 Avia Technique have checked and verified that there are no pertinent AD's or SIs relevant.

\*The work identified in Block 11 are described herein has been accomplished in accordance with the applicable CFR Part 43 and in respect to that work the items are approved for return to service under certificate no. 1925/110026

13a. Certifies that the items identified above were manufactured in conformity to:

Approved design data and are in a condition for safe operation.  
 Non-approved design data specified in Block 12.

14a.  Part-145, A.50 Release to Service  Other regulation specified in Block 12.

14b. Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Part 145, and in respect to that work the items are considered ready for release to service.

13b. Authorised Signature: \_\_\_\_\_

13c. Certificate Approval Ref No.: \_\_\_\_\_

13d. Name: \_\_\_\_\_

13e. Title (dd/mm/yyyy): \_\_\_\_\_

14b. Authorised Signature: \_\_\_\_\_

14c. Certificate Approval Ref No.: **UK.145.00846**

14d. Name: **Ryan Handley**

14e. Date (dd/mm/yyyy): **22/Aug/2018**

**USER / INSTALLER RESPONSIBILITIES**

This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulations of an Airworthiness Authority different from the Airworthiness Authority specified in block 1, it is essential that the user/installer ensures that his/her Airworthiness Authority accepts items from the Airworthiness Authority specified in Block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



Avia Technique Ltd.  
Unit 1,3,4 & 6 Fishponds Estate  
Fishponds Road  
Wokingham, Berkshire, United Kingdom  
RG41 2QJ  
Ph: +441189789789, Fax: +441189794511

### Tear Down/Inspection

Work Order #: W201811000  
Date Printed: 09/07/2018  
Page: 1

**To:**  
Burwood Aviation Supplies Ltd  
8 Bessemer Close  
Burwood House  
Verwood, Dorset BH31 6AZ  
United Kingdom

**Ship To:**  
Burwood Aviation Supplies Ltd  
8 Bessemer Close  
Burwood House  
Verwood, Dorset BH31 6AZ  
United Kingdom

Reference: 110026  
Date Received: 05/07/2018  
Part Number: 62293-07  
Description: Escape Slide  
Serial Number: C1925

#### Customer Remarks:

Overhaul

#### Results from inspection:

##### Slide DOM

- Slide DOM: 02/2013
- Last Maintenance: 09/2015

Unit requires Overhaul

##### Faults

- Missing Parts;
  - Countersunk Washer
  - Stud Fastener
  - Retaining Washer
  - Flat Washer
- Stopnut Nut Worn, Replacement Required

#### Corrective actions:

- Overhaul with reference to the correct CMM Rev
- Fit Missing Parts;
  - Countersunk Washer
  - Stud Fastener
  - Retaining Washer
  - Flat Washer
- Fit Replacement Stopnut Nut
- Test and Certify with reference to the correct issue of the CMM.

Inspection report generated by: Gary Jones