



Continental Aircraft Support, Inc.
 13960 NW 60th Ave.
 Miami Lakes, FL 33014 USA
 Tel. (305) 883-6100
 Fax (305) 817-9323
 Email: info@ContinentalAircraft.com
 www.ContinentalAircraft.com

ISO 9001:2008 Registered
 FAA CRS# Z196R883Y
 EASA 145.56 / 6

Teardown Report No.: 96619

Part No.: 0856AE16	S/N Received: 154260	Date: 9/13/2018
Desc.: PITOT STATIC TUBE	Mfr.: ROSEMOUNT	R/O: 051118
Publication: 34-10-66	Rev.: 9, 6/9/2014	Manual No.: E60b

Work Requested: BENCH TEST

Trouble Reported / Special Instructions: NO TROUBLE REPORTED ; EXPEDITE

Receiving Inspection:	WORK SCOPE
P/N AND S/N VERIFIED TO REPAIR ORDER. NO SHIPPING DAMAGE NOTED.	
Shop Findings: UNIT PASSED MANUFACTURER'S FUNCTIONAL TEST. NO TROUBLE FOUND. TESTING AND INSPECTION DEEMS UNIT READY FOR RETURN TO SERVICE. REQUIRES MINOR SURFACE CLEANING.	
<p>Tech Pub Checked: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A Initial Test: <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail <input type="checkbox"/> N/A</p> <p>P/N & S/N Checked: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A Disassembled: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A</p> <p>Malfunction Verified: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A Hidden Damage Insp. Req'd: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</p>	
Corrective Action: UNIT WAS INSPECTED AND TESTED IN ACCORDANCE WITH MANUFACTURER'S SPECIFICATIONS.	
<p>Cleaned / Painted: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A Final Tested: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A Service Perfm'd.: INSPECTED / TESTED</p> <p>Reworked: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A NDT: <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A Completion P/N: 0856AE16</p> <p>Returned Assembled: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A Release Insp.: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A Completion S/N: 154260</p>	
List of Airworthiness Directives, Modifications, or Service Bulletins Accomplished: NONE	
Maintenance Release	
The aircraft component identified above was serviced and inspected in accordance with current Federal Aviation Regulations and Manufacturers Maintenance Manual and was found to be airworthy for return to service. Pertinent details of the work performed is on file at our facility under the work order number stated above.	

Authorized Signature: _____

Name: ARMANDO ALFONSO

Date: 17/Sep/2018