

1. Approving Civil Aviation Authority/ Country:
FAA/United States

3. Form Tracking Number:
14242

Authorized Release Certificate

FAA Form 8130-3, Airworthiness Approval Tag

4. Organization Name and Address:
Global Air Technologies Services, LLC.
7275 NW 68th Street Unit I Miami, FL 33166 USA G1BR449Y
Phone: 786-703-9106 Fax: 786-703-9109

5. Work Order / Contract / Invoice Number:
R11195

6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	HYDRAULIC PUMP	57186-10	1ea.	K1142	OVERHAULED

GAT 3 INSP

12. Remarks:

OVERHAULED in accordance with CMM 29-20-15 Revision 41.

See Teardown/Inspection Form

Full details of work carried out per work order no. 14242

ORIGINAL


Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the HYDRAULIC PUMP MOTOR is considered ready for release to service under EASA Part 145 approval no. EASA 145.5990.

13a. Certifies the items identified above were manufactured in conformity with the applicable design data and are in a condition for safe operation.
 Approved design data and are in a condition for safe operation.
 Non-approved design data specified in Block 12

14a. 14 CFR 43.9 Return to Service Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature: Not Applicable
 13c. Approval/Authorization No.: Not Applicable
 13d. Name (Typed or Printed): Not Applicable
 13e. Date (dd/mm/yyyy): Not Applicable

14b. Authorized Signature: 
 14c. Approval/Certificate No.: G1BR449Y
 14d. Name (Typed or Printed): EDUARD RODRIGUEZ
 14e. Date (dd/mm/yyyy): 05/Mar/2018

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Block 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

TearDown/Inspection Form

Global Air Technologies Services, LLC.

7275 NW 68th Street Unit 1
Miami, FL 33166
USA

Phone: 786-703-9106 Fax: 786-703-9109

C.R.S. No.: GIBR4 9Y

Work Order: 14242

Sold To:
Scorpion Aero Solutions
6993 N.W. 82ND AVE UNIT#24 MIAMI, FL 33166

Ship To:
Scorpion Aero Solutions
6993 N.W. 82ND AVE UNIT#24 MIAMI, FL 33166

Part Number: 57186-10 Serial: K1842 Manufacturer: Parker Hannifin Corp
Description: HYDRAULIC PUMP MOTOR Model: 57186-10
Purchase Order: R11195 Service Performed: OVERHAULED
Data used Manual Number: 29-20-15 Revision: 41 Date: 3/28/2017



TearDown/Inspection Data

1.- Reason for Removal:
Unknown

Inst.: EVALUATE FOR OVERHAUL I.A.W. MFR. SPEC!

2. Initial Inspection Findings:

Preliminary Inspection: NORMAL

Hidden Damage: N/R.

3. Teardown Findings: DISASSEMBLED CLEANED INSPECTED. FOUND WORN 100% KIT REQUIRED REPLACEMENT. MAIN STATOR, HOUSING ASSY, REQUIRED SURFACE TREATMENT IAW OEM SPECS BEFORE RETURN TO SERVICE IN AN OVERHAUL CONDITION.

4. Additional Information:

Was Complaint Verified: N/A

Modifications: NONE PERFORMED

5. Final

Warranty Accepted: N/A

Final Test and Inspection: NORMAL

A.D. S.B. NO AD. / S.B. REQUIRED


6. Work Performed: UNIT HAS BEEN DISASSEMBLED, CLEANED, INSPECTED, REPAIRED AS NECESSARY, REPLACED PARTS, REASSEMBLED AND FUNCTIONALLY TESTED. OVERHAULED I.A.W. PARKER HANNIFIN, ATA # 29-20-15, REV. 41, DATED: MARCH 28, 2017. UNIT PASSED ALL REQUIRED INSPECTIONS AND TESTS. UNIT IS OK TO RETURN TO SERVICE. NO AD. OR S/B. REQUESTED OR PERFORMED UNDER THIS WORK ORDER

Maintenance Release

This certifies the item identified above was serviced in accordance with current F.A.A. airworthiness regulations and in respect to the work performed is approved to return to service. Pertinent details of the work performed are on file at this Agency under Work Order No.: 14242

Inspector's Name: EDUARD RODRIGUEZ

Technician: Eduardo Camarena

Signature: 



Date: March/05/2018

Form CRS3
Rev 3/2/06

Inspector