



1. Approving Competent Authority / Country CAA, UK		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. Form Tracking Number: W201815357	
4. Organization Name and Address:  Avia Technique SK Aerospace Safety Group Avia Technique Ltd. Unit 1, 3, 4 & 6 Fishponds Estate Fishponds Road Wokingham, Berkshire, United Kingdom RG41 2QJ Ph: +441189789789, Fax: +441189794511		5. Work Order / Contract / Invoice Number: W201815357 111 387		11. Serial Number: C4289 Quantity: 1.00 Overhauled	
6. Item: 7. Description: 1 Reservoir And Valve Assembly		8. Part Number: 61639-203		9. Quantity: 1.00 10. Serial Number: C4289	
12. Remarks: CMM: 25-65-21 Revision: 13 Next Overhaul Due: 10-2021 Cylinder Life Expires: 01-2029 Avia Technique have checked and verified that there are no pertinent AD's or SB's relevant. "The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR Part 43 and in respect of that work, the items are approved for return to service under certificate no. IBQY183X"					
13a. Certifies that the items identified above were manufactured in conformity to: <input type="checkbox"/> Approved design data and are in a condition of service. <input type="checkbox"/> Non-approved design data specified in block 12.		14a. <input checked="" type="checkbox"/> Part-145.A.50 Release to Service <input checked="" type="checkbox"/> Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Part-145, and in respect to that work the items are considered ready for release to service.		14c. Certificate /Approval Ref No.: UK.145.00846	
13b. Authorised Signature:				14d. Name Ryan Handisides	
13c. Certificate /Approval Ref No.:		13d. Date (dd/mm/yyyy):		14e. Date (dd/mm/yyyy): 01/Oct/2018	
USER / INSTALLER RESPONSIBILITIES					
This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an Airworthiness Authority different than the Airworthiness Authority specified in block 1, it is essential that the user/installer ensures that his/her Airworthiness Authority accepts items from the Airworthiness Authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					



Avia Technique Ltd.
Unit 1,3,4 & 6 Fishponds Estate
Fishponds Road
Wokingham, Berkshire, United Kingdom
RG41 2QJ
Ph: +441189789789, Fax: +441189794511

Tear Down/Inspection

Work Order #: W201815357
Date Printed: 28/09/2018
Page: 1

To:
Burwood Aviation Supplies Ltd
8 Bessemer Close
Burwood House
Verwood, Dorset BH31 6AZ
United Kingdom

Ship To:
Burwood Aviation Supplies Ltd
8 Bessemer Close
Burwood House
Verwood, Dorset BH31 6AZ
United Kingdom

Reference: 110387
Date Received: 18/09/2018
Part Number: 61639-203
Description: Reservoir And Valve Assembly
Serial Number: C4289

Customer Remarks:

Overhaul

Results from inspection:

Unit requires Overhaul
Cylinder DOM: 01-2014
Cylinder Life Expiry: 01-2029

No Faults found

Corrective actions:

Overhaul with reference to the correct CMM Rev
Test and Certify with reference to the correct issue of the CMM.

Inspection report generated by: Ryan Handisides