



61527761

3. Form Tracking Number

1. Approving Competent Authority / Country
LBA / Germany

2. **AUTHORISED RELEASE CERTIFICATE
 EASA FORM 1**

3. Form Tracking Number
 001 4433 00000001

4. Organisation Name and Address:
Lufthansa Technik
 Lufthansa Technik AG
 Vög beim Jäger 1
 20365 Hamburg
 Germany

5. Work Order/Contract/Invoice
 61527761

6. Item 01
 7. Description VALVE-OVERPRESSURE
 8. Part No. 6740E010000
 9. Qty. 10
 10. Serial No. 02145
 11. Status / Work OVERHAULED

12. Remarks
 Burwood Aviation Supplies Ltd. 110500
 ATA 3611 TPO MK-No. 10 Pack Code 00 Rep. Workshop 33335015 Workshop Station HAM063

Return to Service in Accordance with 14 CFR part 43
 The work identified in block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work the items are approved for return to service under
 FAA Certificate No. DLAY225D

13a. Certifies that the items identified above were manufactured in conformity to:
 approved design data and are in a condition for safe operation
 Part-145, A.50 Release to Service
 Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.

Further details of work performed are attached either in a Workshop Report (reference number: see blocks 3 and 5) or in other applicable documents.

13b. Authorised Signature
 13c. Approval / Authorisation Number
 014998

13d. Name
 13e. Date (dd mm yyyy)
 16 Oct 2018


14c. Certificate / Approval Ref. Number
DE.145.0001

14d. Name
 Dirk Müller

Not applicable to items which are not automatically constitute authority to install the item(s)
 Where the user/installer performs work in accordance with regulations of an airworthiness authority different from the airworthiness authority specified in block 1, it is essential that the user/installer ensures that the airworthiness authority accepts items from the airworthiness authority specified in block 1.
 Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



Workshop Report

Customer Order No. 110500	 Lufthansa Technik Lufthansa Technik AG Weg beim Jäger 193 22335 Hamburg Germany	Certificate Ref. No. 21084430000001
Part. No. as received 6740E010000	Serial No. as received 02145	Work Order, Contract/Invo. 61527761
Part No. as dispatched 6740E010000	Serial No. as dispatched 02145	Description VALVE-OVERPRESSURE
Reason for removal Note: OVERHAUL QUOTE REQUIRED		Responsible Workshop 33335015
Findings SEAL LEAKAGE, UNION AND CAP WORN. FAIL FUNCTION.FOR OVERHAUL		
Action ALL WEAR PARTS REPLACED. VALVE OVERHAULED.		
Modification Status according to Mod-Label See Unit Mod-Label if equipped		
Name 14998, Dirk Müller		Date (dd mm yy) 16 Oct 2018