



| | | | | | |
|---|--|---|--|--|--|
| 1. Approving Competent Authority / Country CAA.UK | | 2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1 | | 3. Form Tracking Number: W201814131 | |
| 4. Organization Name and Address:  Avia Technique <small>UK Aerospace Safety Group</small> Avia Technique Ltd. Unit 1,3,4 & 6 Fishponds Estate Fishponds Road Wokingham, Berkshire, United Kingdom RG41 2QJ Ph: +441189789789, Fax: +441189794511 | | 5. Work Order / Contract / Invoice Number: W201814131 110299 | | 6. Item: 7. Description: 8. Part Number: 9. Quantity: 10. Serial Number: 11. Status / WC Code: 12. Remarks: | |
| 1 Evacuation Slide System | | D31517-717 1.00 A15971 | | C Overhauled | |
| <p>12. Remarks: CMM: 25-60-56 Revision: 23 Cylinder: P/N D18309-201, S/N 750-23687, DOM 11-2017, Hydrostatically Tested 11-2017, Cylinder: Next Hydrostatic Test Due: 11-2022, Cylinder Expiry Date 11-2032. Escape Slide: DOM 03-2006, Last Maintenance 10-2018, Next Maintenance 10-2021. Avia Technique have checked and verified that there are no pertinent AD's or SB's relevant.</p> <p>The work identified in Block 11 and described herein has been accomplished in accordance with the requirements of Part 43 and in respect to that work, the items are approved for return to service under certificate number 1183X.</p> | | | | | |
| <p>13a. Certifies that the items identified above were manufactured in accordance with:</p> <p><input type="checkbox"/> Approved design data and are in a condition for safe operation</p> <p><input type="checkbox"/> Non-approved design data specified in previous block</p> <p><input checked="" type="checkbox"/> Part-145.A.50 Release to Service <input checked="" type="checkbox"/> Other regulation specified in Block 12</p> <p>14a. Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Part-145, and in respect to that work the items are considered ready for release to service.</p> | | | | | |
| 13b. Authorised Signature:  | | 13c. Certificate /Approval Ref No.: UK.145.00846 | | 14c. Certificate /Approval Ref No.: UK.145.00846 | |
| 13d. Name: Gary Jones | | 14d. Name: Gary Jones | | 14e. Date (dd/mmm/yyyy): 02/Oct/2018 | |
| USER / INSTALLER RESPONSIBILITIES | | | | | |
| <p>This certificate does not automatically constitute authority to install the item(s).</p> <p>Where the user/installer performs work in accordance with regulations of an Airworthiness Authority different than the Airworthiness Authority specified in block 1, it is essential that the user/installer ensures that his/her Airworthiness Authority accepts items from the Airworthiness Authority specified in block 1.</p> <p>Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.</p> | | | | | |

COPY

Aviation

EASA FORM 1



Avia Technique Ltd.
Unit 1,3,4 & 6 Fishponds Estate
Fishponds Road
Wokingham, Berkshire, United Kingdom
RG41 2QJ
Ph: +441189789789, Fax: +441189794511

Tear Down/Inspection

Work Order #: W201814131
Date Printed: 04/09/2018
Page: 1

To:

Burwood Aviation Supplies Ltd
8 Bessemer Close
Burwood House
Verwood, Dorset BH31 6AZ
United Kingdom

Ship To:

Burwood Aviation Supplies Ltd
8 Bessemer Close
Burwood House
Verwood, Dorset BH31 6AZ
United Kingdom

Reference: 110299
Date Received: 30/08/2018
Part Number: D31517-717
Description: Evacuation Slide System
Serial Number: A15971

Customer Remarks:

Overhaul

Results from inspection:

Unit requires Overhaul

Slide DOM

Slide DOM: 03-2006

Last Maintenance: 04-2018

Reservoir DOM: 11-2017

Reservoir Life Expires: 11-2032

No Faults found

Corrective actions:

Overhaul with reference to the correct CMM Rev

Test and Certify with reference to the correct issue of the CMM.

Inspection report generated by: Ryan Handisides