

1. Approving Civil Aviation Authority/Country:

FAA/UNITED STATES

2.

### AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number:

24645

4. Organization Name and Address:

Air Accessories & Avionics, Inc.  
8328 N.W. 30 Terrace  
Doral, FL 33122 USA  
Ph: 305-513-9418, Fax: 305-513-4496

5. Work Order/Contract/Invoice Number:

WO102714  
0774

FAA Cert #: IXSR602L

6. Item Description:

1 VACUUM GENERATOR ASSY

8. Part Number: 14330-350

9. Quantity: 1

10. Serial Number: 98101020

11. Status/Work Order Number: OVERHAULED

12. Remarks:

Overhauled in accordance with repair manual(s) listed below

Manual ID: 38-34-17, Revision #: 2, Revision Date: 7/18/2012

Certifies that the work specified in Block 11/12 was carried out in accordance with EASA Part 14 and in respect to that work the VACUUM GENERATOR ASSY is considered ready for release to service under FAA Part 14 approval number: EASA.145.4071.

See Teardown/Inspection form full details of work carried out under work order no. WO102714

13a. Certifies the items identified above were manufactured in conformity to:

Approved design data and are in a condition for safe operation

Non-approved design data specified in Block 12

14a.  14 CFR 43.9 Return to Service

Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:

13c. Approval No.:

14b. Authorized Signature:

14c. Approval/Certificate No.:

13d. Name (Typed or Printed):

13e. Date (dd/mm/yyyy):

14d. Name (Typed or Printed):

14e. Date (dd/mm/yyyy):

Thomas Dulude

08/Aug/2019

#### User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

When the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

# Teardown/Inspection Form

**Air Accessories & Avionics, Inc.**

8328 Northwest 10th Terrace

Doral, Florida

33122 (KSR602L)

Phone: (305) 513-9418 Fax: (305) 513-4496

C.R.S. No.: KSR602L

**WORK ORDER#: WO102714**

Date Open: 8/6/2019

**Bill To: ITS-INFINITY TRADING SOLUTIONS**  
450 E. ELLIOT ROAD

**ShipTo: ITS-INFINITY TRADING SOLUTIONS**  
UNIT 288, BLOCK G  
BLANCHARDSTOWN CORPORATE PARK 2  
BALLYCOOLIN  
DUBLIN 15

CHANDLER, AZ 85225

**Part Number: 14330-350**

**Serial: 98101020**

**Mfg: ZODIAC**

**Description: VACUUM GENERATOR ASSY**

**Model:**

**Purchase Order: 057745**

**Service Performed: OVERHAUL**

**Data used: Manual Number: 38-34-17**

**Revision: 2**

**Date: 7/26/2012**

## REMOVAL

**INSTRUCTIONS:** OVERHAUL IAW MFG SPECS

## INITIAL INSPECTION FINDINGS

**APPEARANCE:** VISUAL INSPECTION NORMAL  
**CORROSION:** NO CORROSION NOTED  
**LOOSE OR MISSING PARTS:** NO LOOSE OR MISSING PARTS  
**PHYSICAL DAMAGE:** CRACKED MOUNTING BRACKET ON MAIN STATOR

## TEARDOWN

**DISASSEMBLY:** AS REQUIRED BY MANUAL  
**CLEANING:** AS REQUIRED  
**PAINTING:** PAINTING AS REQUIRED  
**ASSEMBLY:** AS REQUIRED FOR OVERHAUL

## TEST

**OPERATION:** TESTED IAW MANUFACTURER'S SPECIFICATIONS  
**WAS COMPLAINT VERIFIED:** N/A  
**MODIFICATIONS:** NONE

## FINAL

**WARRANTY ACCEPTED:** N/A  
**FINAL TEST & INSPECTION:** FINAL INSPECTION NORMAL

**A.T.A.: 38-34-17**

**A.D./S.B.: N/A**

**Work Done:** REPLACED HOUSING ASSEMBLY MOTOR. UNIT WAS DISASSEMBLED, CLEANED, DECONTAMINATED, TESTED, AND INSPECTED. OVERHAULED IN ACCORDANCE WITH MANUFACTURER'S SPECIFICATIONS.


## Maintenance Release

This certifies the item identified above was serviced in accordance with current F.A.A. airworthiness regulation and in respect to the work performed is approved to return to service. Pertinent details of the work performed are on file at this Agency under Work Order No.: WO102714

**Inspector's Name:** Thomas Dulude

**Technician:** Marlon Bustos

**Signature:**



**Date:** 8/8/2019 1:04:02 PM