

1. Approving Competent Authority
/ Country
CAA.UK

AUTHORISED RELEASE CERTIFICATE
EASA FORM 1

2.
3. Form Tracking Number:
W201816939

4. Organization Name and Address:
Avia Technique Ltd.
Unit 1,3,4 & 6 Fishponds Estate
Fishponds Road
Wokingham, Berkshire, United Kingdom RG41 2QJ
Ph: +441189789789, Fax: +441189794511

5. Work Order / Contract / Invoice Number:
W201816939
1 J523


6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status / Work Order No.:
1	Oxygen Cylinder Assembly	176574-77	1.00	1178-30883	Overhaul

12. Remarks:
CMM: 35-10-76 Revision: 3
Next Overhaul / Hydrostatic Test: 11-2023
Cylinder Life Expiry Date: 03-2029
Avia Technique have checked and verified that there are no pertinent AD's or SB's relevant.

"The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR Part 43 and in respect to that work, the items are approved for return to service under certificate no. 18 Y18, UK"

13a. Certifies that the items identified above were manufactured in conformity to:
 Approved design data and are in a condition for safe operation.
 Non-approved design data specified in Block 12

Part-145, A.50 Release to Service Other regulation specified in Block 12
Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Part-145, and in respect to that work the items are considered ready for release to service.

13b. Authorised Signature:	13c. Certificate Approval No.:	14b. Authorised Signature:	14c. Certificate Approval Ref No.:
			UK.145.00846
13d. Name:	13e. Title (dd/mm/yyyy):	14d. Name:	14e. Date (dd/mm/yyyy):
		Matthew Rimmer	02/Nov/2018

This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulations of an Airworthiness Authority different than the Airworthiness Authority specified in block 1, it is essential that the user/installer ensure that the work is approved by the Airworthiness Authority specified in block 1.
Statements in blocks 1a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations of the user/installer before the aircraft may be flown.



Avia Technique Ltd.
Unit 1,3,4 & 6 Fishponds Estate
Fishponds Road
Wokingham, Berkshire, United Kingdom
RG41 2QJ
Ph: +441189789789, Fax: +441189794511

Tear Down/Inspection

Work Order #: W201816939
Date Printed: 15/10/2018
Page: 1

To:
Burwood Aviation Supplies Ltd
8 Bessemer Close
Burwood House
Verwood, Dorset BH31 6AZ
United Kingdom

Ship To:
Burwood Aviation Supplies Ltd
8 Bessemer Close
Burwood House
Verwood, Dorset BH31 6AZ
United Kingdom

Reference: 110523
Date Received: 12/10 2018
Part Number: 17657-77
Description: Oxygen Cylinder Assembly
Serial Number: 1178-30883

Customer Remarks:

Overhaul

Results from inspection:

Unit requires Overhaul
DOM: 03-2014

Corrective actions:

Overhaul with ref to the correct CMM
Refill with Aviation/Breathing Oxygen compliant with MIL-PRF-4710 Specification

Inspection report generated by: Bartosz Pachulski