

1. Approving Civil Aviation Authority/Country:
FAA/UNITED STATES

2. **AUTHORIZED RELEASE CERTIFICATE**
 FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number:
 161304

4. Organization: **Linco Airpark, Inc.**
 Name and Address: **5304 South Lawton Ave.
 FAA/EASA Repair Station: C22R760K
 Tulsa, OK 74107
 UNITED STATES**

FAA Certificate #: **C22R760K**

5. Work Order/Contract/Invoice Number:
TR100132

6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	OZONE CONVERTER A319/320/321 ENGELHARD	20499004	1 EA	914	OVERHAULED

12. Remarks: In accordance with manual No. APS 92-04-061 Revision: U Revision Date: MAY 05 2016 and Manual No. 21-11-04 Revision: JN Revision Date: JUL 22 2010
 CLEAN, OVERHAUL, TEST, DETAIL, AND INSPECT.
 UNIT RECEIVED WITH 1 PLUG(S), BEING RETURNED WITH 1 PLUG(S) INSTALLED.

Certifies that the work specified in Block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work the component is considered ready for release to service under EASA Part-145 Approval Number: "EASA 145-4153".

13a. Certifies the items identified above were manufactured in conformity to:
 Approved design data and are in a condition for safe operation.
 Non-approved design data specified in Block 12.
 14a. 14 CFR 43.9 Return to Service Other regulation specified in Block 12
 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:	13c. Approval/Authorization No.:	14b. Authorized Signature:	14c. Approval/Certificate No.:
13d. Name (Typed or Printed):	13e. Date (dd/mm/yyyy):	14d. Name (Typed or Printed):	14e. Date (dd/mm/yyyy):
		ZACK YANG	C22R760K 24/Jul/2019

User/Installer Responsibilities

It is important to understand the extent of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.
 Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.
 Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



Limco Airepair, Inc.

5304 South Lawton Ave. Tel: 918-445-4300
 Tulsa, OK 74107 Fax: 918-445-2210 (MKT)
 UNITED STATES Fax 918-445-3285 (PUR)
 www.limcoairepair.com 20-8562612
 FAA/EASA Repair Station: C22R760K

TEARDOWN REPORT

Page: 1 of 2

Aircraft : A319		F.O.B. :	
Weight of Part : 11	JETPOWER		
Valve S/N :	Attn: KRISTI MOORE, QUOTES		
Reason Removed :	905 LAKESIDE DR		
Work Requested :	SUITE 2		
Inspected By : LUKE WES	GURNEE, IL 60031		
Govt. Rating :	UNITED STATES		
Repair Recore : OVERHAUL	Tel. : 847 306-3472		
*****	Fax : 847 847-603-1604		
Core Serial # :			
For Customer : JETPOWER	W/O Kind : [OH] OVERHAUL		
S.O. No. : 080722	Line No. :		
Cust P.O. : IR100132	P/N : 20499004	Cert# :	
Our Ref : 080722	Desc : OZONE CONVERTER A319/320/321 ENG	Heat# :	
Your Ref : IR100132	S/N : 9164	Lot# :	
Contract :	MFG :	Manual :	APS 92-04-061
Proj/ DO# : SS TUBE	Qty : 1.0000	Cond As: OHB	Revision : U / May-05-2016
Completed P/N : 20499004	S/N As : 9164	Into Bin Loc :	
Company : 1	Division : MRO	Department : COM	
Order Date : Jun-28-2019	Received Date : Jun-28-2019	Disc Date : Jun-28-2019	Print Date : Jul-24-2019

WORK ORDER No. 161304

QC
 *****OVERHAULED*****

CLEAN, OVERHAUL, TEST, DETAIL, AND INSPECT.
 UNIT RECEIVED WITH 1 PLUG(S), BEING RETURNED WITH 1 PLUG(S) INSTALLED

PASSED EFFICIENCY TEST.

Z. VANG 7/24/2019
Preliminary Inspect

CUSTOMER REASON FOR REMOVAL: N/A

LAST SHOP VISIT: N/A

EVALUATION:
 -RECEIVED WITH 1 LARGE PLUG SAFETY WIRED AND NO SMALL PLUG

Continued on next page.



Limco Airepair, Inc.

5304 South Lawton Ave. Tel: 918-445-4300
 Tulsa, OK 74107 Fax: 918-445-2210 (MKT)
 UNITED STATES Fax: 918-445-3285 (PUR)
 www.limcoairepair.com 20-8562612
 FAA/EASA Repair Station: C22R760K

TEARDOWN REPORT

Page: 2 of 2

WORK ORDER No. 161304

- NO DAMAGE TO CORE OR HOUSING
- NEEDS CLEANED AND TESTED
PER APG 22-4-061
- UNIT TO BE RECERTIFIED

Can Ship 10 days after approval is received.

Evaluate Work Assgmt

EVALUATOR: JR DATE OF EVALUATION: 11/2019

EVALUATE WORK ASSIGNMENT:

- T: _____ Test, Inspect
- A: _____ Soap clean / flushing, Minor repairs such as straightening fins, minor flange repair, minor welding, test, inspect.
- B: X _____ Removal of all coatings, major repairs as required including core blockage, clean, application of coatings as required, test, inspect.
- C: _____ Complete replacement of core assembly

B.E.R.: _____ Beyond Economical Repair

R.A.I.: _____ Return As Is

Authorized Signature: _____

BROOKLYN AVIATION COPY