

1. Approving Civil Aviation Authority/Country  
 FAA/United States

# AUTHORIZED RELEASE CERTIFICATE

FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number:  
 110722

4. Organization Name and Address:  
 ICON AEROSPACE, LLC.  
 2617 EXECUTIVE POINT DR.  
 MONROE, NC 28110

FAA Repair Station : 681R700B  
 EASA Reference : EASA.145.6295  
 Ph: 704-821-4266 Fax: 704-821-4286

FAA Order Control/Invoice Number:  
**W104470**

6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	IND. FUEL QTY REPEATER	2101-01-2	1	850	OVERHAULED

12. Remarks: **OVERHAULED** In accordance with CMM 28-44-06 Rev.: 10 Date: NOV/18/2015  
 The above specified unit was manufactured by: GE  
 FULL DETAILS OF WORK CARRIED OUT PER  
 WORK ORDER NUMBER: W104470

COMPLIANCE WITH MANUFACTORY AIRWORTHINESS DIRECTIVES (ADS):  
 N/A  
 COMPLIANCE WITH SERVICE BULLETINS (SBS/EOs):  
 N/A

13a. Certifies that items identified above were manufactured in conformity with the work specified in blocks 11/12, was carried out in accordance with EASA Part-145, and in respect to that work, the component is considered ready for release to service under EASA Part 145 Approval Number EASA.145.6295

- Approved design data and aircraft consultancy, safety, variation
- Non-approved design data specified in Block 1

14a.  14 CFR 43.9 Return to Service  Other regulation specified in Block 12.  
 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:	13c. Approval/Authorization No.:	14b. Authorized Signature:	14c. Approval/Certificate No.:
			681R700B
13d. Name (Type or Print):	13e. Date (dd/mm/yyyy):	14d. Name (Typed or Printed):	14e. Date (dd/mm/yyyy):
		Agustin "Gus" Garcia	17/Jan/2019

### User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. When the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statements in Block 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



FAA REPAIR STATION 68IR700B  
 EASA REFERENCE EASA.145.6295  
 2617 EXECUTIVE POINT DR.  
 MONROE, NC 28110  
 Ph: 704-821-4266 Fax: 704-821-4286  
 EMail: sam@iconaerospace.com

Page 1  
**WORK ORDER**  
**W104470**  
 Date Rcvd : 11/Dec/2018

**TEARDOWN REPORT**

BURWOOD AVIATION SUPPLIES, LTD.  
 Burwood House  
 8 Bessemer Close,  
 Ebblake Industrial Estate  
 Verwood, Dorset.  
 ENGLAND BH31 6AZ

Cust RO#: 110746  
 P/N: 2101-01-2  
 S/N: 850  
 Desc: IND., FUEL QTY REPEATER  
 Mfgr: GE

Manual Loc: GE-014  
 ATA: 28-44-06  
 Rev: 10 Rev Date: 18/Nov/2015  
 Tag Date: 17/Jan/2019

Contact: **DARON GOLDING**  
 Contact Ph: 44-1202-825434  
 Contact Fax: 44-1202-823416

Reason Removed: UNIT RECEIVED FOR OVERHAUL AS PER O.E.M SPEC'S

**FINDINGS**

**RECEIVING INSPECTION:**

VERIFIED UNIT DATA PLATE, NO DISCREPANCIES FOUND. UNIT RECEIVED WITH CRACKED SCREEN.

**PRELIMINARY INSPECTIONS:**

TESTED UNIT. FAILED FUNCTIONAL TEST.

**HIDDEN DAMAGE:**

NONE

**CONTINUED INSPECTION:**

TESTED. UNIT HAS A BAD DISPLAY, CASE, AND LAMPS. DISASSEMBLY IS REQUIRED.

**CORRECTIVE ACTION: UNIT CONDITION OVERHAULED**

REPLACED PART(S) AS REQUIRED. CLEANED AND REASSEMBLED UNIT. TESTED AS PER O.E.M SPEC'S.

**SB's, AD's, EO's and RMK's:**

NONE

**CERTIFICATION**

Service Performed:  OVERHAULED

MODIFIED TO:

**PARTS AND MATERIALS**

QTY	PART NUMBER	DESCRIPTION	COND
1	200770-002	CASE	SV
1	71217-0003	DISPLAY	SV
2	715AS15	LAMP(S)	NE

**MAINTENANCE RELEASE**

The component identified above was serviced as specified above in accordance with the current regulations of the Federal Aviation Administration and is approved for return to service. Other pertinent details of the repair are on file at the repair station.

APPROVED FOR RETURN TO SERVICE BY:

Agustín "Gus" Garcia

DATE: 17/Jan/2019