

# AUTHORIZED RELEASE CERTIFICATE

FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

<b>1. Approving Civil Aviation Authority/Country</b> FAA/United States	<b>2.</b>	<b>3. Form Tracking Number:</b> R167129	
<b>4. Organization Name and Address:</b> ICON AEROSPACE, LLC. 2617 EXECUTIVE POINT DR. MONROE, NC 28110 PH: 704-821-4266 Fax: 704-821-4286		<b>5. Work Order/Contract/Job Number:</b> W88221	
<b>6. Item</b> 1	<b>7. Description:</b> BALLAST, FLUORESCENT LAMP	<b>8. Part Number:</b> 70-0366-11	<b>9. Quantity:</b> 1
		<b>10. Serial Number:</b> 10632	<b>11. Status/Work:</b> REPAIRED
<b>12. Remarks:</b> REPAIRED In Accordance with CMM 33-21-43 Rev.: 04 Date: FEB/01/2011 The above specified unit was manufactured by: HONEYWELL FULL DETAILS OF WORK CARRIED OUT PER WORK ORDER NUMBER: W88221 COMPLIANCE WITH MANDATORY AIRWORTHINESS DIRECTIVES (ADS): N/A COMPLIANCE WITH SERVICE BULLETINS (SBs/EOs): N/A			
<b>13a.</b> Certifies that the work specified in blocks 11/12 was carried out in accordance with EASA Part 145, and in respect to that work, the component is considered ready for release under EASA Part 145 Approval Number EASA.145.6295 Other regulation specified in Block 12.			
<b>13b.</b> <input type="checkbox"/> Approved design data and in in a condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 12.			
<b>13c.</b> Authorized Signature: _____ Date: (dd/mm/yyyy) _____			
<b>13d.</b> Name (Typed or Printed): Agustín "Gus" Garcia			
<b>13e.</b> User/Installer Responsibilities			
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where a user installs, performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.			
Statements in Block 13a and 13a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations specified by the user/installer before the aircraft may be flown.			



FAA REPAIR STATION 68IR700B  
 EASA REFERENCE EASA.145.6295  
 2617 EXECUTIVE POINT DR.  
 MONROE, NC 28110  
 Ph: 704-821-4266 Fax: 704-821-4286  
 EMail: sam@lconaerospace.com

Page 1  
 WORK ORDER  
**W88221**

Date Rcvd : 23/Apr/2018

**TEARDOWN REPORT**

UNICAL AVIATION, INC.  
 680 South Lemon Ave.  
 City of Industry, CA 91789

Cust RO#: R167129

Manual Loc: HW-300

P/N: 70-0366-11

ATA: 33-21-43

S/N: 10632

Rev: 04

Rev Date: 01/Feb/2011

Contact: REPAIRS  
 Contact Ph: 909-348-1700  
 Contact Fax:

Desc: BALLAST, FLUORESCENT LAMP

Mfrg: HONEYWELL

Tag Date: 22/May/2018

Reason Removed: UNIT RECEIVED FOR BENCH CHECK AS PER O.E.M SPEC'S

**FINDINGS**

**RECEIVING INSPECTION:**

VERIFIED UNIT DATA PLATE, NO DISCREPANCIES FOUND.

**PRELIMINARY INSPECTIONS:**

TESTED UNIT: FAILED FUNCTIONAL TEST.

**HIDDEN DAMAGE:**

NONE

**CONTINUED INSPECTION:**

DISASSEMBLED UNIT AS REQUIRED AND TESTED. FOUND UNIT CONTAMINATED.

**CORRECTIVE ACTION: UNIT CONDITION REPAIRED**

CLEANED AND REASSEMBLED UNIT. TESTED AS PER O.E.M. SPEC'S.

**SB's, AD's, EO's and RMK's:**

NONE

**CERTIFICATION**

Service Performed:  REPAIRED

MODIFIED TO:

**PARTS AND MATERIALS**

**MAINTENANCE RELEASE**

The component identified above was serviced as specified above in accordance with the current regulations of the Federal Aviation Administration and is approved for return to service. Other pertinent details of the repair are on file at this repair station.

APPROVED FOR RETURN TO SERVICE BY: Agustin "Gus" Garcia

DATE: 22/May/2018