

AUTHORISED RELEASE CERTIFICATE

EASA FORM 1

1. Approving Competent Authority / Country
CAA.UK

2. Avia Technique Ltd.

Unit 1,3,4 & 6 Fishponds Estate
 Fishponds Road
 Wokingham, Berkshire, United Kingdom RG41 2QJ
 Ph: +441189789789, Fax: +441189794811

3. Form Tracking Number:
W201816490

5. Work Order / Contract / Invoice Number:
W201816490
110183

6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status / Work
1	Pump	P99C38-805	1.00	20685	Repaired

12. Remarks:
 CMM: 28-22-19 Revision: 8

"The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR Part 43 and in respect to that work the items are approved for return to service under certificate number 118QY13X"

Avia Technique have checked and verified that there are no pertinent AD's or SB's relevant.


13a. Certifies that the items identified above were manufactured in conformity to:

Approved design data and are in a condition for safe operation.

Non-approved design data specified in Block 12

4a. Part-145 A.50 Release to Service Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Part-145, and in respect to that work the items are considered ready for release to service.

13b. Authorised Signature:	13c. Certificate / Approval Ref No.:	14b. Authorised Signature:	14c. Certificate / Approval Ref No.:
			UK.145.00846
13d. Name:	Date (dd/mm/yyyy):	14d. Name:	14e. Date (dd/mm/yyyy):
		Chris Nicholson	30/Oct/2018



USER / INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulations of an Airworthiness Authority different than the Airworthiness Authority specified in block 1, it is essential that the user/installer ensures that his/her Airworthiness Authority accepts items from the Airworthiness Authority specified in block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



Avia Technique Ltd.
 Unit 1,3,4 & 6 Fishponds Estate
 Fishponds Road
 Wokingham, Berkshire, United Kingdom
 RG41 2QJ
 Ph: +441189789789, Fax: +441189794511

Tear Down/Inspection

Work Order #: W201816490
 Date Printed: 10/16/2018
 Page: 1

To:
 Burwood Aviation Supplies Ltd
 8 Bessemer Close
 Burwood House
 Verwood, Dorset BH31 6AZ
 United Kingdom

Ship To:
 Burwood Aviation Supplies Ltd
 8 Bessemer Close
 Burwood House
 Verwood, Dorset BH31 6AZ
 United Kingdom

Reference: 117483
 Date Received: 10/5/2018
 Part Number: P9900005
 Description: Pump
 Serial Number: 20685

Customer Remarks:

Inspect/Test

Results from inspection:

Faults
 Unit requires replacement O-rings.

Date of manufacture
 NOV 1998

Corrective actions:

Repair and Test with reference to correct CMM
 Fit replacement O-rings.
 Repair, Test and Certify with reference to the correct issue CMM

Inspection report generated by: Russell Tyson