

1. Approving Competent Authority / Country

LBA / Germany

61548331

3. Form Tracking Number

20156831 00000001

**AUTHORISED RELEASE CERTIFICATE  
EASA FORM 1**



Lufthansa Technik AG  
Weg beim Jäger 193  
22335 Hamburg  
Germany

5. Work Order/Contract/Invoice

61548331

4. Organisation Name and Address:

6. Item



8. Part No.

9. Qty

10. Serial No.

11. Status / Work

7. Description

4-60000H883-00

368300021986

REPAIRED

12. Remarks

Burwood Aviation Supplies Ltd. 110722

ATA 3071

TP R

MK-No. 29

Fack Code 00

Resp. Workshop 33426015

Workshop Station HAM305

TT UNKNOWN UNKNOWN  
TSS UNKNOWN UNKNOWN  
TSF UNKNOWN UNKNOWN  
TASK PERFORMED IN ACCORDANCE WITH CMM 38-34-11  
REV. 14 / CMDS 38-34-11 ISSUE 020

**Return to Service in Accordance with 14 CFR part 43**  
The work identified in block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under  
FAA Certificate No. DLAY228D

13a. Certifies that the items identified above were mar

- approved design data and are in a condition for safe operation
- not approved design data specified in block 12

14a.  Part-145 A.50 Release to Service

Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part- 145 and in respect to that work, the items are considered ready for release to service.

Further details of work performed are attached either in a Workshop Report (reference number: see blocks 3 and 5) or in other applicable documents.

Other Regulation specified in block 12

13b. Authorised Signature

13c. Approval / Authorisation Number

14b. Authorised Signature

411978

14c. Certificate / Approval Ref. Number

DE.145.0001

13d. Name

13e. Date (dd mmm yyyy)

14d. Name

Holger Jechte

14e. Date (dd mmm yyyy)

07 Dec 2018


**EASA FORM 1 - Iss A.2  
USER INSTALLER RESPONSIBILITIES**

This certificate does not automatically constitute authority to install the item(s).  
The user/installer performs work in accordance with regulations of an airworthiness authority different from the airworthiness authority specified in block 1. It is essential that the user/installer ensures that the user/installer before the aircraft may be flown.  
Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by


# Workshop Report

61548331



Customer Order No. 110722		 <b>Lufthansa Technik</b> Lufthansa Technik AG Weg beim Jäger 193 22335 Hamburg Germany		Certificate Ref. No. 201500310000001
Part. No. as received 4-60000H883-00	Serial No. as received 368300009284	Part. No. as dispatched 4-60000H883-00	Serial No. as dispatched 368300021986	Work Order/Contract/Invoice No. 61548331
Reason for removal Unknown.	Responsible Workshop 33426015			
Findings Housing (fairing assy) cracked and corroded at tip.	Modification Status according to Mod-Label			
Action Mast assy cleaned and disassembled. Fairing assy replaced. S/N changes from 368300009284 to 368300021986 Mast assy assembled, tested and inspected.	See Unit Mod-Label if equipped			
The work specified above has been performed subject to Lufthansa Technik's Standard conditions for Technical Services which, if not stated otherwise, are agreed upon before, are acknowledged by the customer with acceptance of the part(s) hereunder.		Name 411978, Holger Jechte	Date (dd mmm yyyy) 07 Dec 2018	

LHT Form 30992 G-15 (HAM WG/C)



Smartlabel-ID: 100000003288482

61548331



Ident-Tag Barcode

# Ident-Tag



# Lufthansa Technik

Form Tracking Number | Work Order / Contract / Invoice  
20150831 00000001

Description DRAIN MAST ASSY		Part. No. 4-60000H883-00	
Eligibility	Quantity 1	Status / Work REPAIRED	Serial-/Batch No. 368300021986

Remarks  
TP R MK No. 20 Resp. Workshop 33426015 Workshop Station HAM305  
FSCM 670D3 ATA

Packaging Code: 00

<b>Installed on</b> (Information is only required in case of installation only)		
PNR NHA	SNR NHA	Position/FIN No. NHA
Station	A/C-Registration	

## Removed

PNR <sup>1</sup>	SNR <sup>1</sup>	Position/FIN No. <sup>1</sup>
Station <sup>1</sup>	A/C-Registration <sup>1</sup>	Unit Barcode No.

### Removed from NHA

 (Information is only required in case of part change on next higher assy)

PNR NHA	SNR NHA	Position/FIN No. NHA
---------	---------	----------------------

### Reason for Removal<sup>1</sup>

<input type="checkbox"/> 22 Unscheduled	Complaint No. <sup>1</sup> or WO-Reference	<input type="checkbox"/> 11 Scheduled
---	--	---------------------------------------

Failure Description<sup>1</sup> (Please write in capital letters only)

CCI-ID<sup>2</sup>

Stamp or ID Number + Signature<sup>1/2</sup>

Date<sup>1</sup>

<sup>1</sup> Mandatory entries without using CCI-Mask  
<sup>2</sup> Mandatory entries using CCI-Mask

Special Investigation Tag exists  Yes

Please send back to: (unless other return location is agreed)

LUFTHANSA TECHNIK AG  
c/o Lufthansa Technik Logistik Services GmbH  
Warenannahme / Goods Receiving  
Weg beim Jaeger 193  
22335 HAMBURG-FUHLSBÜTTEL  
Deutschland

(LTL-Information: Use this box for ZID)