

61554319



3. Form Tracking Number

20184676 00000001

AUTHORISED RELEASE CERTIFICATE
EASA FORM 1

1. Approving Competent Authority / Country
LBA / Germany

4. Organisation Name and Address:
Lufthansa Technik
Lufthansa Technik AG
Weg beim Jäger 193
22335 Hamburg
Germany

5. Work Order/Contract/Invoice
61554319

6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No.	11. Status / Work
01	TOILET ASSY	TA9125-00	1	01460577	OVERHAULED

12. Remarks
Burwood Aviation Supplies Ltd. 110768 ATA 3831 TP O MK-No. 10 P. K. Co. e 00 Resp. Workshop 33345010 Workshop Station HAM063

TT Opr. Hours Cycle Opr. Day
TSO UNKNOWN UNKNOWN 0
TSC 0 0 0
TSF 0 0 0
TASK PERFORMED IN ACCORDANCE WITH CMM 38-31-61
REV. 2 / CMLS 38-31-61 ISSUE 013

Return to Service in Accordance with 14 CFR part 43
The work identified in block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work the items are approved for return to service under
FAA Certificate No. DLA7225D

13a. Certifies that the items identified above were manufactured in conformity to: <input type="checkbox"/> approved design data and are in a condition for safe operation <input type="checkbox"/> non-approved design data specified in block 12		14a. <input checked="" type="checkbox"/> Part-145 A.50 Release to Service (reference number: see blocks 3 and 5) or in other applicable documents. <input checked="" type="checkbox"/> Other Regulation specified in block 12 Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.	
13b. Authorised Signature	13c. Approval / Authorisation Number	14b. Authorised Signature 415619	14c. Certificate / Approval Ref. Number DE.145.0001
13d. Name	13e. Date (dd mmm yyyy)	14d. Name Bernd Domrös	14e. Date (dd mmm yyyy) 14 Jan 2019

EASA FORM 1 - ISS. 1-2
USER INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).
The user/installer performs work in accordance with regulations of an airworthiness authority different from the airworthiness authority specified in block 1. It is essential that the user/installer ensures that the user/installer before the aircraft may be flown.
Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by

Workshop Report

61554319



Lufthansa Technik

Lufthansa Technik AG
Weg beim Jäger 193
22335 Hamburg
Germany

Certificate Ref. No.

2019076 0000001

Work Order/Contract/Invoice No.

61554319

Description

TOILET ASSY

Responsible Workshop

33345010

Modification Status according to Mod-Label

See Unit Mod-Label if equipped

Customer Order No.
110768

Part No. as received
TA9125-00

Serial No. as received

01460577

Part No. as dispatched
TA9125-00

Serial No. as dispatched

01460577

Reason for removal

Overhaul.

Findings

Reason for removal confirmed.
Toilet is dirty and contaminated.
Rubber parts are worn and have to be replaced.
Flush valve seals are worn and need to be replaced.
Anti-siphon valve calcified.
Bowl coating damaged/scratched.

Solenoid from water valve corroded by abnormal wear & tear.

Action

Toilet cleaned and disinfected.
All rubber parts replaced.
Flush valve overhauled and tested.
Water valve cleaned and overhauled.
Solenoid changed.
Anti-siphon valve cleaned and repaired.
Bowl recoated.
S/N components:FCM:11301171 WV:011140 A18
Toilet overhauled and tested.

The work specified above has been performed subject to Lufthansa Technik's Standard conditions for Technical Services which, if not agreed upon by the customer, are acknowledged by the customer with acceptance of the part(s).

Name

415619, Bernd Domrös

Date (dd mm yy)

14 Jan 2019

LHT 110768-00992 G-15 (HAM WG/Q)