

1. Approving Competent Authority
/ Country
CAA UK

AUTHORISED RELEASE CERTIFICATE
EASA FORM 1

3. Form Tracking Number:
W201902507

4. Organization Name and Address:
Avia Technique Ltd.
Unit 1,3,4 & 6 Fishponds Estate
Fishponds Road
Wokingham, Berkshire, United Kingdom RG41 2GJ
Ph: +441189789789, Fax: +441189794511

5. Worker Number / Certificate / Invoice Number:
W. 01902 07


6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status / Work:
1	Slide Evac System	D31865-111	1.00	A7519	Overhauled

12. Remarks:
CMM: 25-60-58 Revision: 23
Escape Slide: DOM 07/2000, Last Maintenance 02/2019, Next Maintenance 02/2020.
Avia Technique have checked and verified that there are no pertinent AD's or SB's relevant.

The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR Part 43 and in respect to that work, the items are approved for return to service under certificate no. 18QY183X"


13a. Certifies that the items identified above were manufactured in conformity to:
 Approved design data and are in a condition for safe operation.
 Non-approved design data specified in Block 12

14a. Part-145, A.50 Release to Service Other regulation specified in Block 12
Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Part-145, and in respect to that work, the items are considered ready for release to service.

13b. Authorised Signature:	13c. Certificate /Approval Ref No.:	14b. Authorised Signature:	14c. Certificate /Approval Ref No.:
			UK: 145.00846
13d. Name	13e. Date (dd/mm/yyyy):	14d. Name	14e. Date (dd/mm/yyyy):
		Ryan Handstides	22/Feb/2019

USER / INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).
Where a user/installer performs work in accordance with regulations of an Airworthiness Authority different than the Airworthiness Authority specified in block 1, it is essential that the user/installer ensures that his/her Airworthiness Authority accepts items from the Airworthiness Authority specified in block 1.
Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

 Avia Technique <small>SK Aerospace Group</small>	Avia Technique Ltd. Unit 1,3,4 & 6 Fishponds Estate Fishponds Road Wokingham, Berkshire, United Kingdom RG41 2QJ Ph: +441189789789, Fax: +441189794511	Tear Down/Inspection Work Order #: W201902507 Date Printed: 08/02/2019 Page: 1
To: Burwood Aviation Supplies Ltd 8 Bessemer Close Burwood House Verwood, Dorset BH31 6AZ United Kingdom	Ship To: Burwood Aviation Supplies Ltd 8 Bessemer Close Burwood House Verwood, Dorset BH31 6AZ United Kingdom	
Reference: 118001 Date Received: 07/02/2019 Part Number: D31861 111 Description: Slide Evac System Serial Number: A7519		
<p>Customer Remarks:</p> <p>Overhaul</p> <p>Results from inspection:</p> <p>Unit requires Overhaul</p> <p>Slide DOM Slide DOM: 07-2000 Last Maintenance: 01-2016</p> <p>Faults Hose Assembly is damaged/Worn</p> <p>Corrective actions:</p> <p>Overhaul with reference to the correct CMM Rev Fit Replacement Hose Assembly. Test and Certify with reference to the correct issue of the CMM.</p>		
Inspection report generated by: Ryan Handisides		