

1. Approving Civil Aviation Authority/Country:
FAA/United States

AUTHORIZED RELEASE CERTIFICATE

FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number:
101031

4. Organization Name and Address:
Continental Aircraft Support, Inc., 13960 N.W. 60th Ave., Miami Lakes, FL 33014 (ZN9R863X)

5. Work Order Number:
G2 788

6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Remarks:
1	LIQUID LEVEL SENSOR	14403-085	1 EA	4347	INSPECTED / TESTED

12. Remarks: In accordance with Publication No: 38-34-46 Revision: 0 Revision Date: Jun/30/2017
MFG: MONOGRAM
A/D, Mod., S/B, Accomplished: NONE

Certifies that the work specified in Block 11/12 was certified out in accordance with EASA Part 145 and in respect to that work the component is considered ready for release to service under EASA Part 145 approval no. EASA 145-5605

13a. Certifies the items identified above were manufactured in conformity with:
 Approved design data and are in a condition for safe operation.
 Non-approved design data specified in Block 11.

14a. 14 CFR 43.9 Return to Service Other regulation specified in Block 12
 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:	13c. Approval/Authorization No.:	14b. Authorized Signature:	14c. Approval/Certificate No.:
		<i>Natan Hernandez</i>	ZN9R863X
13d. Name (Typed or Printed):	13e. Date (dd/mm/yyyy):	14d. Name (Typed or Printed):	14e. Date (dd/mm/yyyy):
		NATAN HERNANDEZ	22/Mar/2019


User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where a user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Entries in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



Continental Aircraft Support, Inc.
 13960 NW 60th Ave.
 Miami Lakes, FL 33014 USA
 Tel. (305) 883-6100
 Fax (305) 817-9323
 Email: info@ContinentalAircraft.com
 www.ContinentalAircraft.com



ISO 9001:2015 Registered
 FAA CRS# ZN9R863X
 EASA 145.5605

Teardown Report No.: 101035

Part No.: 14403-085	S/N Received: 4347	Date: 3/5/2019
Desc.: LIQUID LEVEL SENSOR	Mfr.: MONOGRAM	R/O: G22788
Publication: 38-34-46	Rev.: 0, 6/30/2017	Manual No.: E8163


Work Requested: REPAIR

Trouble Reported / Special Instructions: NO TROUBLE REPORTED ; NO SPECIAL INSTRUCTIONS REPORTED

Receiving Inspection:	WORK SCOPE
P/N AND S/N VERIFIED TO REPAIR ORDER. NO SHIPPING DAMAGE NOTED.	
Shop Findings:	
PASSES MANUFACTURER'S FUNCTIONAL TEST. NO TROUBLE FOUND. TESTING AND INSPECTION DEEMS UNIT READY FOR RETURN TO SERVICE. REQUIRES MINOR SURFACE CLEANING.	
Tech Pub Checked: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A	Initial Test: <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail <input type="checkbox"/> N/A
P/N & S/N Checked: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A	Disassembled: <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
Malfunction Verified: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A	Hidden Damage Insp. Req'd.: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Corrective Action:	
INSPECTED AND TESTED IN ACCORDANCE WITH MANUFACTURER'S SPECIFICATIONS.	
Cleaned / Painted: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A	Final Tested: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
Reworked: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A	NDT: <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
Returned Assembled: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A	Release Insp.: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
Service Period: INSPECTED / TESTED	
Completion P/N: 14403-085	
Completion S/N: 4347	
List of Airworthiness Directives, Modifications, or Service Bulletins Accomplished:	
NONE	
Maintenance Release	
The aircraft component identified above was serviced and inspected in accordance with current Federal Aviation Regulations and Manufacturer's Maintenance Manual and was found to be airworthy for return to service. Pertinent details of the work performed is on file at our facility under the work order number stated above.	

Authorized Signature: Natan Hernandez Name: NATAN HERNANDEZ

Date: 22/Mar/2019



Continental Aircraft Support, Inc.
 13960 NW 60th Ave.
 Miami Lakes, FL 33014 USA
 Tel. (305) 883-6100
 Fax (305) 817-9323
 Email: info@ContinentalAircraft.com
 www.ContinentalAircraft.com



ISO 9001:2015 Registered
 FAA CRS# ZN9R863X
 EASA 145.5605

Date:

Shipping Ticket

Invoice No.: 117301

Bill To:

GLENDALE INTERNATIONAL
 Glendale International
 17 Totman Crescent
 Rayleigh, Essex, SS6 7UY
 UK
 Phone: 44-01268-741770 Fax: 44-01268-741780
 Attn: Accounts Payable

Ship To:

Glendale International
 17 Totman Crescent
 Brook Road Industrial Estate
 Rayleigh, Essex, SS6 7UY
 UK
 Phone: 44-01268-741770 Fax: 44-01268-741780
 Attn: Receiving Department

Work Order: 101035	Quantity: 1	Order No.: G22788
Shipped Via:	Air B:	Terms: NET-30

Part No.:	Description:	Manufacturer:	Serial No.:	Container:
14403-085	LIQUID LEVEL SENSOR	MONOGRAM	4347	Condition: INSPECTED /

E28601
 25 MAR 2019

Received By

Print Name: _____

Signature: _____

Date: _____