



ECE

ZODIAC AEROSPACE

RAPPORT TECHNIQUE  
SHOP FINDING REPORT

N° N1202254

Repair

Page 1 / 2

CLIENT ZODIAC AEROSPACE LTD  
Customer (COMPASS)  
DOC.CLIENT R916611  
Del.Doc.Ref.  
INSTRUCTIONS CLIENT on 1 PART/FAR145  
Customer inst.

N° DE CDE  
Customer PO/RO  
DATE DE RECEPTION 16/04/2012  
Received date

ARRIVEE Received

REFERENCE 389GC01Y03  
Received part number

REF.CLIENT  
Received customer part number

DESIGNATION BATTERY CHARGE LIMITER

FABRICANT  
Manufacturer

Quantité 1  
Quantity  
ARRIVEE Received  
N°Série 1186  
Serial number  
AMT D  
Amendment

DATES  
Livraison 01/04/1989  
Delivery  
Dépose 31/03/2012  
Removal  
TSN  
TSO  
TSR

AVION A300/310  
Aircraft Model

IMMATRICULATION : G-MONR  
Registration number

Date Service:

\*\*\* Documents maintenance / Maintenance doc ref \*\*\*  
CMM 24 32 14 REV 12 (09/10)

\*\*\* Motifs Retour / Reason for removal \*\*\*  
ON ECAM AND OHD PANEL #2 BATTERY HAS A PERMANENT GREEN FLOW BAR WHICH INTERMITTENTLY CHANGES TO AMBER WITH A MINUS FIVE TO MINUS 10 DISCHARGE INDICATED. TR 1 ALSO DROPS TO ZERO OCCASIONALLY

\*\*\* Constatations / Findings \*\*\*  
\*\*\*\* EXTERNAL APPEARANCE :  
DIRTY.

\*\*\*\* TEST IN RELATION TO CMM :  
FAULT FOUND DUE TO RELAY K400 DETERIORATED ON CB (REF:GC10537 N°1186).

\*\*\*\* DE-ASSEMBLY, INTERNAL ASPECT :  
SATISFYING.

\*\*\*\* REMOVAL REASON CONFIRMED ? :  
YES.

\*\*\* Travaux réalisés et pièces remplacées / Work performed and replaced parts \*\*\*  
CLEANING, REPLACEMENT OF DETERIORATED PART, RE-ASSEMBLY, CHECK AND COMPLETE TEST CYCLE BEFORE RESHIPMENT.

DEPART Shipped

REFERENCE DEPART Shipped part number  
389GC01Y03

REF.CLIENT Shipped customer number

IMPUTATION TECHNIQUE CLIENT Customer Liability  
YES

N°Série serial number  
1186

AMDT  
D

REMARQUES Remarks

CONTINUED TO PAGE 2



SAC023/B

B  
C  
D  
E  
F  
G  
H  
I  
J  
K  
L  
M  
N  
O  
P  
Q  
R  
S  
T  
U  
V  
W  
X  
Y  
Z

<b>RAPPORT TECHNIQUE</b> <b>SHOP FINDING REPORT</b>		N° <b>N1202254</b>
Repair		Page <b>2 / 2</b>
CLIENT Customer <b>7 DJIAC AEROSPACE LTD</b> (C8944-INS)	N° DE CDE Customer PO/RO	
DOC.CLIENT Del.Doc.Ret. <b>R9166611</b>	DATE DE RECEPTION Received date <b>16/04/2012</b>	
INSTRUCTIONS CLIENT Form1 PART/FAR145 Customer inst.		
ARRIVEE Received		
REFERENCE Received part number <b>389GC01Y03</b>	REF.CLIENT Received Customer part number	
DESIGNATION <b>BATTERY CHARGE LIMITER</b>	FABRICANT Manufacturer	
ARRIVEE Received	DATES	TSN
Quantité Quantity <b>1</b>	N°Série Serial number <b>1186</b>	AMDT Amendment <b>D</b>
Fab/RG Mfg/Ovhl	Livraison Delivery	Dépose Removal
	<b>01/04/1989</b>	<b>31/03/2012</b>
AVION: <b>A300/310</b> Aircraft Model		IMMATRICULATION: <b>G-MONR</b> Registration number
Date Service:		


**DECLARATION DE CONFORMITE**  
**STATEMENT OF CONFORMITY (NF L 00-015C)**

CLIENT DESTINATAIRE Final customer **Monarch Airlines, United Kingdom G**

VOTRE COMMANDE Your order **R9166611**

Nous déclarons que le matériel cité, réparé ou modifié, après vérifications et essais est conforme aux exigences du contrat, sauf exceptions, réserves ou dérogations énumérées dans la présente déclaration de conformité.

We hereby declare, barring exceptions, reservations, or exemptions listed in this statement of conformity, that, after completion of testing and verifications, the repaired or modified supplies listed comply with the contract requirements.



REFERENCE DEPART Shipped part number <b>389GC01Y03</b>		REF.CLIENT shipped customer part number	
IMPUTATION TECHNIQUE CLIENT Customer Liability <b>YES</b>		N°Série serial number <b>1186</b>	AMDT Amendment <b>D</b>
REMARQUES Remarks			
DATE j/m/a-d/m/y <b>25/06/2012</b>	Technicien Technician <b>E TEMPEREAU</b> P.O. Signature	Inspecteur Inspector <b>X MICHELET</b> Signature	SERVICE DE SURVEILLANCE Official Authority

Conformité et propriété

SAQ023/B



# RAPPORT TECHNIQUE

## SHOP FINDING REPORT

N° **N1202254**

Repair Page **1 / 1**

CLIENT  
Customer  
**ZODIAC AEROSPACE LTD**  
(C8944-INS)  
DOCUMENT  
Del. doc. Ref. **R9166611**  
INSTRUCTIONS CLIENT Form1 PART/FAR145  
Customer instructions

N° DE CDE  
Customer PO/RO  
DATE DE RECEPTION **16/04/2012**  
Received date

ARRIVEE Received

REFERENCE **389GC01Y03**  
Received part number

REF.CLIENT  
Received Customer part number

DESIGNATION **BATTERY CHARGE LIMITER**

FABRICANT  
Manufacturer

Quantité Quantity	ARRIVEE Received		AMDT Amendment	Fab/RG Mfg/Ovhl	DATES		TSN
	N° Série Serial number				Livraison Delivery	Dépose Removal	
	<b>1186</b>		<b>D</b>		<b>01/04/1989</b>	<b>31/03/2012</b>	<b>TSR</b>

AVION: **A300/310**  
Aircraft Model

IMMATRICULATION: **G-MONR**  
Registration number

Date Service:

\*\*\* Documents maintenance / maintenance doc ref \*\*\*  
CMM 24 32 14 REV 12 (0 /10)

\*\*\* Motifs Retour / Reason for removal \*\*\*  
ON ECAM AND OHD PANEL #2 BATTERY HAS A PERMANENT GREEN FLOW BAR WHICH INTERMITTENTLY CHANGES TO AMBER WITH A MINUS FIVE TO MINUS 10 DISCHARGE INDICATED. TR 1 ALSO DROPS TO ZERO OCCASIONALLY.

\*\*\* Constatations / Findings \*\*\*

\*\*\*\* EXTERNAL APPEARANCE :  
DIRTY.

\*\*\*\* TEST IN RELATION TO CMM :  
FAULT FOUND DUE TO RELAY K400 DETEORATED ON PCB (REF:GC10537 N°1186).

\*\*\*\* DE-ASSEMBLY, INTERNAL ASPECT :  
SATISFYING.

\*\*\*\* REMOVAL REASON CONFIRMED ? :  
YES.

\*\*\* Travaux réalisés et pièces remplacées / Work performed and replaced parts \*\*\*  
CLEANING, REMPLACEMENT OF DETERIORATED PART, RE-ASSEMBLY, CHECK AND COMPLETE TEST CYCLE BEFORE RESHIPMENT.

CONTINUED TO BE A TRUE COPY



DEPART Shipped

REFERENCE DEPART Shipped part number  
**389GC01Y03**

REF.CLIENT shipped customer part number

IMPUTATION TECHNIQUE CLIENT Customer Liability  
**YES**

N° Série Serial number  
**1186**

REMARQUES Remarks

DATE  
j/m/a-d/m/y  
**23/04/2012**

Technicien **E TEMPEREAU**  
Technician  
Signature

Continued and irregularly  
SAG023/B