





FAA REPAIR STATION 68IR700B  
 EASA REFERENCE EASA.145.6295  
 2617 EXECUTIVE POINT DR.  
 MONROE, NC 28110  
 Ph: 704-821-4266 Fax: 704-821-4286  
 Email: sam@iconaerospace.com

WORK ORDER

**W106830**

Date Rcvd : 23/Jan/2019

**TEARDOWN REPORT**

JMC GLOBAL, INC.  
 5576 S. PALMA AVE.  
 ANAHEIM, CA 92807

Cust RO#: R5404  
 P/N: MXP410-1  
 S/N: SE43250

Manual Loc: Z-007  
 ATA: 35-13-42  
 Rev: 12 Rev Date: 26/Jul/2018

Contact: REPAIRS  
 Contact Ph: 714-676-8033  
 Contact Fax: 714-676-8032

Desc: STOWAGE, FLIGHT CREW MASK  
 Mfgr: INTERTECHNIQUE

Tag Date: 21/Feb/2019

Reason Removed: UNIT RECEIVED FOR OVERHAUL AS PER O.E.M SPEC'S

**FINDINGS**

RECEIVING INSPECTION:  
 VERIFIED UNIT DATA PLATE, NO DISCREPANCIES FOUND.

PRELIMINARY INSPECTION:  
 TESTED UNIT. FAILED FUNCTIONAL TEST.

HIDDEN DAMAGE:  
 NONE

CONTINUED INSPECTION:  
 TESTED. UNIT HAS CONTAMINATION AND BROKEN HINGES, BUSHINGS AND STRAP. DISASSEMBLY IS REQUIRED.

CORRECTIVE ACTION: UNIT CONDITION OVERHAULED  
 REPLACED PART(S) AS REQUIRED. CLEANED AND REASSEMBLED UNIT. TESTED AS PER O.E.M SPEC'S.

SB's, AD's, EO's and RMK's:  
 NONE

**CERTIFICATION**

Service Performed:  OVERHAULED

MODIFIED TO:

**PARTS AND MATERIALS**

QTY	PART NUMBER	DESCRIPTION	COND
1	416438	VELCRO	NE
2	452558	BAR, HINGE	NE
1	OH KIT	OVERHAUL KIT	NE

**MAINTENANCE RELEASE**

The component identified above was serviced as specified above in accordance with the current regulations of the Federal Aviation Administration and is approved for return to service. Other pertinent details of the repair are on file at this repair station.

APPROVED FOR RETURN TO SERVICE BY: Agustin "Gus" Garcia

DATE: 21/Feb/2019