

1. Approving Civil Aviation Authority/Country:
FAA/UNITED STATES

2. **AUTHORIZED RELEASE CERTIFICATE**
 FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number:
 125746

4. Organization Name and Address:
 Pacific Aero Tech, LLC,
 23413 66th Ave. South
 Kent, WA 98032 USA

FAA Certificate #: FO4R187M

5. Work Order/Contract/Invoice Number:
 RT-28404-0301

6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Remarks/W. Ac:
1	#2 OPENABLE WINDOW ASSY, RH	141A4810-39	1 EA	09013H6575	OVERHAULED

12. Remarks: In accordance with manual No. 56-110-02 Revision: 40 Revision Date: NOV 01 2018
 OVERHAULED, TESTED AND INSPECTED IAW MFGS CMM CHAPTER 56.
 NO APPLICABLE SERVICE BULLETINS OR AIRWORTHINESS DIRECTIVES AT THIS TIME.

Certifies that the work specified in Block 11/12 was carried out in accordance with 14 CFR Part 43 and in respect to that work the component is considered ready for release to service under EASA Part-145 Approval Number: "EASA 145-5081".

13a. Certifies the items identified above were manufactured in conformity to:
 Approved design data and are in a condition for safe operation.
 Non-approved design data specified in Block 12.

14a. 14 CFR 43. Return to Service
 Other regulation specified in Block 12
 I certify that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:	13c. Approval/Authorization No.:	14b. Authorized Signature:	14c. Approval/Certificate No.:
<i>[Signature]</i>		<i>[Signature]</i>	FO4R187M
13d. Name (Typed or Printed):	13e. Date (dd/mm/yyyy):	14d. Name (Typed or Printed):	14e. Date (dd/mm/yyyy):
		Brandon Mooney	30/Apr/2019

User/Installer Responsibilities

It is important to understand that the existence of this document does not automatically constitute authority to install the aircraft engine/propeller/article.
 Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensure that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.
 Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

FAA Form 8130-3 (02-14)

NSN: 0052-00-012-9005



FAA FO4R187M
EASA 145.5081

23413 66th Ave. South
Kent WA 98032 USA
www.pacificaerotech.com
T 253.395.9535 F 253.395.9541



Work Order Disposition Report

Page: 1 of 3

Status : OVERHAULED Warranty Y/N : N Contact : Mechanic : CRT WH Code : Cust Charge : Division : Reject Doc : A/C ID # : UNK Confirmed Y/N :		F.O.B... : Account No. [ANATRADING] ANA TRADING CORP., USA Attn: REPAIR 3625 Del Amo BLVD, Suite 300 TORRANCE, CA 90503 UNITED STATES Tel. : 1 310-542-2500 Fax : 1 310-542-2501	
For Customer : ANA TRADING CORP USA S.O. No. : 070284 Line No. : 1		W/O Kind : [WS] Window Shop	
Cust P.O. : RT-28404-0301 Our Ref : Your Ref : TSN/TSO : UNK Mfg Date : 09/14 Completed P/N : 141A4810-39	P/N : 141A4810-39 Desc : #2 OPENABLE WINDOW ASSY, RH S/N : 013H675 MFG : BOEING COMMERCIAL Qty : 1 S/N As : 0J013H675	Lot/Batch# : Tag Date : 04/30/2019 Life : Manual : 56-10-02 Revision : 40 / Nov-01-2018 Into Bin Loc : RTS	Cond As: OH
Company : 1 Order Date : Mar-22-2019	Division : WIN Received Date : Jan-14-2019	Fragment : REP Due Date : Apr-26-2019	Print Date : May-02-2019

WORK ORDER NO. 125746

Reported By Customer

PLEASE OH.

Preliminary Insp.

INSPECTION OF THE UNIT FOUND VINYL CRACKING IN LOWER AFT CORNER, AFT PANEL SEAL IS MISSING, SEVERAL PARTS ARE DAMAGED/WON AND REQUIRE REPLACEMENT, FRAME IS CHAFED. DUE TO CONDITION AND AGE OF THE PANEL (DOM SEPT 2014), IT IS RECOMMENDED THE PANEL IS REPLACED.

Corrective Action

REPLACED PANEL AND ALL REQUIRED PARTS. OVERHAULED, TESTED AND INSPECTED IN ACCORDANCE WITH CMM CHAPTER 56.

Item	Part Number / Description	Part Status	Qty	Cond	Discrepancy / Disposition
PARTS & MATERIALS					
01	5-89355-88 #2 OPENABLE PANEL, RH MDL#: 727/37 Serial No. : 18059H9866	32 - Installed Component	1	EA NE	Disc. _____ Insp. : _____

Continued on next page...



FAA FO4R187M
EASA 145.5081

23413 66th Ave. South
Kent WA 98032 USA
www.pacificaerotech.com
T 253.395.9535 F 253.395.9541



Work Order Disposition Report

Page : 2 of 3

WORK ORDER No. 125746

Item #	Description	Quantity	Unit	Location	Disc.	Disp.
02	9-66525-14 SEAL, RH MDL#: 737	32 - Installed Component	1 EA	NE	Disc. _____ Disp. : _____	
03	BMS5-95B1/2 SEALANT - PS 870 B 6 OZ SEMKIT 354 MDL#: SEALANT	32 - Installed Component	1 EA	NE	Disc. _____ Disp. : _____	
04	BACB10HH04 BEARING MDL#: 737 NG	32 - Installed Component	3 EA	NE	Disc. _____ Disp. : _____	
05	BACC10HM04P WIRE CLAMP, 737 NEW GEN	32 - Installed Component	4 EA	NE	Disc. _____ Disp. : _____	
06	MB25 MOUNTING PLATE, (MB2.5), WHITE CABLE TIE	32 - Installed Component	4 EA	NE	Disc. _____ Disp. : _____	
07	BACB30NY6K2 BOLT MDL#: 737 NG	32 - Installed Component	13 EA	NE	Disc. _____ Disp. : _____	
08	BACB30NM3K19 BOLT MDL#: 737 NG	32 - Installed Component	2 EA	NE	Disc. _____ Disp. : _____	
09	BACB30NN3K2 BOLT MDL#: 737 NG	32 - Installed Component	1 EA	NE	Disc. _____ Disp. : _____	
10	NAS1149D0416J WASHER	32 - Installed Component	2 EA	NE	Disc. _____ Disp. : _____	
11	BACB30NN4K12 BOLT MDL#: 737 NG	32 - Installed Component	1 EA	NE	Disc. _____ Disp. : _____	
12	BACN11AG4 NUT, ROLLER ASSY MDL#: 737	32 - Installed Component	3 EA	NE	Disc. _____ Disp. : _____	
13	BACB30NY6K14 BOLT MDL#: 737 NG	32 - Installed Component	4 EA	NE	Disc. _____ Disp. : _____	
14	BACS40R016C018F SHIM	32 - Installed Component	1 EA	NE	Disc. _____ Disp. : _____	

Continued on next page...



FAA FO4R187M
EASA 145.5081

23413 66th Ave. South
Kent WA 98032 USA
www.pacificaerotech.com
T 253.395.9535 F 253.395.9541



Work Order Disposition Report

Page: 3 of 3

WORK ORDER No 125746

15	60-7312 GLIDE SCREW	32 - Installed Component	1 EA NE	Disc. _____ Disp. : _____
16	BACS12FA3k8 SCREW MDL#: 737	32 - Installed Component	5 EA NE	Disc. _____ Disp. : _____
17	5-89355-88 #2 OPENABLE PANEL, KIT MDL#: 727/37 Serial No. : 14269H9968	33 - Removed Component	1 EA AR	Disc. _____ Disp. : _____