

1. Approving Civil Aviation Authority/Country: 2.

FAA/UNITED STATES

AUTHORIZED RELEASE CERTIFICATE
FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number:

30721

4. Organization Name and Address: Global Air Services LLC
 14075 SW 143 CT
 Unit # 4
 MIAMI, FL 33186
 Ph: 786-539-1538, Fax: 786-362-7177

5. Work Order/Certificate/Invoice Number:

18896

FAA Approval Holder: 1GBR2988B / EASA.145.6418

6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	C.S.D.	735511A	1	B4201	OVERHAULED

12. Remarks:

Unit was Overhauled in accordance with Hamilton Sundstrand CMM 24-11-75 Rev. 28 Dated on Sep/24/2014. Full details of work carried out held on Work Order.

Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work the component is considered ready for release to service under EASA Part-145 Approval Number: EASA 145.6418.

A.D. Note: None SB: None

13a. Certifies the items identified above were manufactured in conformity to:

Approved design data and are in a condition for sale or return.

Non-approved design data specified in Block 12

14a. 14 CFR 43.9 Return to Service

Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, Part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:

13c. Approval Authorization No.:

14b. Authorized Signature:

14c. Approval/Certificate No.:

13d. Name (Typed or Printed):

13e. Date (dd/mm/yyyy):

14d. Name (Typed or Printed): LAZARO FERRER

14e. Date (dd/mm/yyyy): 13-May-2019

1GBR2988B

User/Installer Responsibilities

1. It is the responsibility of the user/installer to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

2. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is the responsibility of the user/installer to ensure that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

3. Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



Global Air Services LLC
 14075 SW 143 CT
 Unit # 4
 MIAMI, FL 33186
 Ph: 786-539-1538, Fax: 786-362-7177
 info@globalairserv.com

Tear Down/Inspection

Work Order #: 18896

Date Printed: 5/13/2019

Time: 4:32:08 PM

Page: 1

To:
 ATTN: Javier G. Galdo
 AEROSPACE SUPPORT INT'L
 7838 NW 57th Street
 DORAL, FL 33166
 USA

Ship To:
 AEROSPACE SUPPORT INT'L
 7838 NW 57th Street
 DORAL, FL 33166
 USA

Ref #: 10030518

Phone #: 786-391-1863

Fax #:

Email: javier@aerospacesupportintl.com

Code: ASI1

Site:

PN: 735511A

Descr: C.S.D.

Qty: 1

Station:

Make:

Model:

Mfg: _

TSN: 0

TSO: 0

TSR: 0

CSN: 0

CSO: 0

CSR: 0

Cond: OVERHAULED

Mechanic: J DE LOS RIOS

Inspector: L FERRER

Engine Number:

Manual: 24-11-75

Rev: 28

Rev Date: 09/24/2014

Tail Number:

Serial Numbers: B4201

Symptoms:

RELIABILITY

REASON FOR REMOVAL: OVERHAUL
 REMOVAL DATE: UNK
 CUSTOMER RO DATE: 04APR2019
 A/C REG: UNK
 POS: UNK
 TIME: UNK
 CYCLE: UNK

PRIMARY FAILURE: FUNCTIONAL TEST WAS BYPASSED. CUSTOMER REQUESTS UNIT TO BE OVERHAULED.

REASON FOR REMOVAL CONFIRMED: NO. TEST WAS BYPASSED.
 PART NUMBER ON DATAPLATE MATCHES CUSTOMER RO: YES
 SERIAL NUMBER ON DATAPLATE MATCHES CUSTOMER RO: YES

IDENTIFICATION

AS PER OEM CMM UNIT IS IDENTIFIED CORRECTLY

AD'S FOUND

NO FAA OR EASA AIRWORTHINESS DIRECTIVES FOUND ON 13MAY2019.

REPLACEMENT PARTS

UNIT IS QUOTED FOR: OVERHAUL

REPLACEMENT PARTS REQUIRED:

1 735511-GASKIT 100% EXPENDABLES KIT (MANDATORY)
 9 728638GD PISTON (WORN/DAMAGED)

REWORK PARTS

REQUIRED REWORK PARTS:

REPAIR OF QAD BRACKET BOLT HOLES IAW CMM. REPAIR # 63.

Corrective Actions:

LAZARO FERRER