

1. Approving Civil Aviation Authority/Country:
FAA / UNITED STATES

2. **AUTHORIZED RELEASE CERTIFICATE**
 FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number:
 0439366/FS

4. Organization: **ALLRIGHT CORPORATION - FAA REPAIR STATION PK3R654Y**
 Name and Address: **20014 70TH AVENUE SOUTH
 KENT, WA 98032
 USA**

FAA Certificate : PK3R654Y

5. Work Order/Certificate/Invoice Number:
 10879SR-SEA

6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	#1 WINDOW ASSY - LH (PLKINGTON)	141T4800-13	1 EA	H52	OVERHAULED

12. Remarks: In accordance with manual No. 56-11-02 Revision: 32 Revision Date: JUL 01 2018 UNIT WAS DISASSEMBLED, CLEANED, INSPECTED, OVERHAULED AND PARTS REPLACED AS NECESSARY. UNIT WAS INSPECTED, OVERHAULED AND RE-ASSEMBLED IAW CMM 56-11-02 REV 32 DATED JUL-01-2018 AD 2010-15-01 IAW SB 757-30-0019 AND SB 757-30-0020 UNIT CTR FIELD AIRCRAFT AND APPROVED TO RETURN TO SERVICE. FOR FURTHER INFO SEE WO 0439366/FS
 Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work the component is considered ready for release to service under EASA Part-145 Approval Number: 145.5287

13a. Certifies the items identified above were manufactured in conformity to:

Approved design data and are in a condition for safe operation.
 Non-approved design data specified in Block 12.

14a. 14 CFR 43.9 Return to Service Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signatures:	13. Approval/Authorization No.:	14b. Authorized Signatures:	14c. Approval/Certificate No.:
13d. Name (Typed or Printed):	13e. Date (dd/mm/yyyy):	14d. Name (Typed or Printed):	14e. Date (dd/mm/yyyy):
		PAUL MARCHUK QA INSPECTOR	PK3R654Y 17/APR/2019

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.
 The user/installer forms work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1. In this case, the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.
 State Units in blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



WWW.ALLFLIGHT.COM

TEL: (253) 437-0582

FAX: (253) 437-0586

ALLFLIGHT CORPORATION - FAA REPAIR STATION PK3R654Y

License #PK3R654Y

20014 70TH AVENUE SOUTH

KENT

WA

98032

USA

TEARDOWN REPORT

Page: 1 of 3

CUSTOMER PO : 108739SR-SEA	F.O.B. : Account No. [332V8] INFINITY AIR, INC. Attn: Mrs CORISSA GOLD, REPAIRS MANAGER 18321 VENTURA BLVD, STE 400 TARZANA, CA 91356 UNITED STATES Tel. : +1-818-881-8911 889 Fax : +1-818-881-9525
QUOTE AMOUNT :	
QUOTE DATE :	
AIRCRAFT : BOEING	
MODEL : B757/767	
CUSTOMER : INFINITY AIR	
MECHANIC : ARNOLD TAASE	
INSPECTOR : PAUL MARCHUK	
COMPLETED COND. : OVERHAULED	W/O Kind : [OH] OVERHAULED
COMPLETED DATE : 04/17/2019	
For Customer : INFINITY AIR, INC.	
S.O. No. : 096791	Line No. : 1

Cust P.O. : 108739SR-SEA	P/N : 141T4800-13	Warranty : 1 YEAR
SALESORDER : 096791	Desc : # WINDOW ASSY - LH (PILKINGTON)	Trace To : INFINITY AIR
YOUR REF : SOLD	S/N : H5269	Rev : C
WOAM : ALICIA VASQUEZ	MFG : BOEING	Tag Info : 04/19 ALLFLIGHT 8130
CSR : BROOKE	Qty : 1	Cond As: OH
Completed P/N : 141T4800-13	S/N As : H5269	Rev As: C
Company : 2	Division : 01	Department : WIN
Order Date : Apr-04-2019	Received Date : Mar-27-2019	Due Date : Apr-17-2019
		Print Date : Apr-17-2019

WORK ORDER No. 043936AFS

WORK INSTRUCTIONS

WORK ORDER INSTRUCTIONS ARE TO OVERHAUL UNIT IAW MFG SPECS
QUOTE APPROVAL REQUIRED

PRELIMINARY INSP.

1. WORK ORDER INSTRUCTIONS ARE TO OVERHAUL UNIT IAW MFG SPECS.
2. CLEANING REQUIRED FOR INSPECTION.
3. MOISTURE SEAL WORN, REQUIRES REPLACEMENT.
4. MISSING SCREWS, REQUIRE INSTALLATION.
5. WEATHER SEAL DAMAGED, REQUIRES REPAIR.
6. GLASS PANEL HAS SCRATCHES, REQUIRES POLISHING.
7. COMPLIANCE WITH AD AND SB REQUIRED.

FUNCTIONAL TEST

UNIT PASSED FUNCTIONAL TEST

POWER TERMINAL 1- J1,J5 = 9.5 OHMS

POWER TERMINAL 2- J4,J5 = 9.3 OHMS

SENSOR TERMINAL 1 -J2 = 311 OHMS

Continued on next page...



WWW.ALLFLIGHT.COM

TEL: (253) 437-0582

FAX: (253) 437-0586

ALLFLIGHT CORPORATION - FAA REPAIR STATION PK3R654Y

License #PK3R654Y

20014 70TH AVENUE SOUTH

KENT

WA

98032

USA

TEARDOWN REPORT

Page: 2 of 3

WORK ORDER No. 043936AFS

SENSOR TERMINAL 2- J3= 311 OHMS

CORRECTIVE ACTION

1. OVERHAULED UNIT IAW CMM 56-11-02 REV 32 DATED JUL-01-2018
2. CLEANED AND INSPECTED NO DEFECTS FOUND OTHER THAN NOTED
3. REMOVE AND REPLACE MOISTURE SEAL
4. INSTALLED MISSING SCREWS
5. REPAIRED DAMAGE WEATHER SEAL
6. POLISHED GLASS PANEL TO OPTICAL CLARITY
7. COMPLIED WITH AD 2010-15-01 IAW SP 757-30-0019 AND SB 757-30-0020 BY VISUAL INSPECTION
NO DEFECTS FOUND

ALL WORK PERFORMED IAW CMM 56-11-02 REV 32 DATED JUL-01-2018
AD 2010-15-01 IAW SB 757-30-0019 AND SB 757-30-0020

FINAL INSPECTION

UNIT WAS DISASSEMBLED, CLEANED, INSPECTED, OVERHAULED AND PARTS REPLACED AS NECESSARY.
UNIT WAS INSPECTED, OVERHAULED AND RE-ASSEMBLED IAW CMM 56-11-02 REV 32 DATED JUL-01-2018
AD 2010-15-01 IAW SB 757-30-0019 AND SB 757-30-0020
UNIT CERTIFIED AIRWORTHY AND APPROVED TO RETURN TO SERVICE.

MECHANICS SIGNATURE *[Signature]*

STAMP

INSPECTORS SIGNATURE *[Signature]*

STAMP

Item	Part Number / Description	Part Status	Qty	Cond	Discrepancy / Disposition
PARTS & MATERIALS					
1	141T4804-1 SEAL Warranty: FN Trace To: BOEING Tag Info: 3/19 BOEING 8130-3	32 - Installed Component	1	LA FN	Disc. _____ Disp. : _____
2	MS24693CB117 SCREW Warranty: FN Trace To: CRESCENT MFG CO. Tag Info: 4/19 WESCO COC	32 - Installed Component	3	EA FN	Disc. _____ Disp. : _____
3	PR1425B1/2	32 - Installed Component	1	EA NE	Disc. _____

Continued on next page...



WWW.ALLFLIGHT.COM

TEL: (253) 437-0582

FAX: (253) 437-0586

ALLFLIGHT CORPORATION - FAA REPAIR STATION PK3R654Y

License #PK3R654Y

20014 70TH AVENUE SOUTH

KENT

WA

98032

USA

TEARDOWN REPORT

Page: 3 of 3

WORK ORDER No. 043936AFS

SEALANT 6 OZ SEM (TUBE)

Warranty: 30 DAYS

Trace To: PRC-DESOTO

Tag Info: 1/19 PRC-DESOTO

Disp. : _____

Authorized Signature