

61603910



1. Approving Competent Authority / Country

LBA / Germany

3. Form Tracking Number

**AUTHORISED RELEASE CERTIFICATE
EASA FORM 1**

20366410 00000001

4. Organisation Name and Address:



Lufthansa Technik

Lufthansa Technik AG
Wed beim Jäger 193
22335 Hamburg
Germany

5. Work Order/Contract/Invoice

61603910

6. Item

8. Part No.

9. Qty.

10. Serial No.

11. Status / Work

01 WATER EXTRACTOR-BLEED AIR

2340406-1

1

12983

REPAIRED

12. Remarks

Burnwood Aviation Supplies Ltd. 111304

ATA 2151

TP R

MK-No. 10

Work Centre 00

Resp. Workshop 33343020

Workshop Station HAM143

Opr. Hours Cycle Opr. Day
TT UNKNOWN UNKNOWN
TSO UNKNOWN UNKNOWN
TSC UNKNOWN UNKNOWN
TSF 0 0
TASK PERFORMED IN ACCORDANCE WITH CMM 21-51-86
REV. 1 / CMDS 21-51-86 ISSUE 010

Return to Service in Accordance with 14 CFR part 43
The work identified in block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work the items are approved for return to service under
FAA Certificate No. DLAY228D

13a. Certifies that the items identified above were repaired/overhauled/overhauled to:

- approved design data and are in a condition for safe operation
- non-approved design data specified in block 12

Part-145 A.50 Release to Service
Further details of work performed are attached either in a Workshop Report (reference number; see blocks 3 and 5) or in other applicable documents.
 Other Regulation specified in block 12
Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.

13b. Authorised Signature

13c. Approval / Authorisation Number

14b. Authorised Signature

518729

14c. Certificate / Approval Ref. Number
DE:145.0001

13d. Name

13e. Date (dd mmm yyyy)

14d. Name

Michael Schmidt

14e. Date (dd mmm yyyy)
03 Jul 2019

**EASA FORM 1 - RELEASE 2
EASA FORM 1 - RELEASE 2
EASA FORM 1 - RELEASE 2**

No. of certificates does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulations of an airworthiness authority different from the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.

Statements in blocks 13a and 14e do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

Workshop Report

61603910



Lufthansa Technik

Lufthansa Technik AG
Weg beim Jäger 193
22335 Hamburg
Germany

Certificate Ref. No.

20366410 000000

Work Order/Contract/Invoice

61603910

Description

WATER EXTRACTOR-BLEED AIR

Responsible Workshop

33343020

Modification Status according to Mod-Label

| | | |
|---|-----------------------------------|----------------------------------|
| Customer Order No. 111304 | | |
| Part No. as received 2340406-1 | Serial No. as received 12983 | |
| Part No. as dispatched 2340406-1 | Serial No. as dispatched 12983 | |
| Reason for removal UNKNOWN | | |
| Findings PART CONTAMINATED. DRAIN PIPES DEFORMED. PAINT PROTECTION WORN. | | See Unit Mod-Label if equipped |
| Action PART CLEANED. DRAIN PIPES STRAIGHTENED. PRESSURE AND LEAKAGE TEST O.K. EXTRACTOR NEW VARNISHED. UNIT COMPLETED. | | |
| The work described above has been performed subject to Lufthansa Technik's Standard conditions for Technical Services which, if not superseded by any other terms, conditions or notes agreed upon before, are acknowledged by the customer with acceptance of the part(s) hereunder. | | Name 518729, Michael Schmidt |
| LHT Form 30992 3-15 (HAM WG/Q) | | Date (dd mm yyyy) 03 Jul 2019 |